Document Control Sheet

Sheet Title:	PST 2 YD
Box ID:	7141
Control Sheet ID:	0000-0000-0014-9119
Record Series Name:	WST / Petroleum Storage Tank Registrations
Record Series:	PST
Primary ID:	63297
Secondary ID:	
Doc Type:	Remediation
Security:	Public
Date:	12/30/2016 12:00AM
Title:	Incident Report
Tertiary ID	

INCIDENT REPORT

FORM INSTRUCTIONS: Use this form to report suspected/confirmed PST releases to the Texas Commission on Environmental Quality (TCEQ) within 24 hours of discovery. Forms may be e-mailed (pstrpr@tceq.state.tx.us), faxed (512/239-2216), or phoned in (512/239-2200). Call 512/239-2120 for emergencies during regular business hours, or if after hours, page 512/606-9197.

TEXAS PETROLEUM STORAGE TANK PROGRAM
INCIDENT REPORT FORM

Facility Information	Facility Name: FAST LANE #25 Address: 2248 I.H 10 & WASHINGTON City: BEAUMONT County: JEFFERSON Facility ID: 63297 Ghost tank(s)? ☐Y ☑N Pre-existing LPST ID? ☑N ☐Y: #
Responsible Party (RP) Information	Contact Person: CRAIG HILL Phone: 408 842 1414 Company: STEINHAGEN OIL Co. INc. Fax: 409 842 9574 Address: PO Box 25037 City: BEAUMONT State: TX Zip: 77730 The RP is the . . . ☐ tank owner ☐ tank operator ☐ landowner ☐ other
Release reported by (if different than RP):	Contact person: _____ Phone: _____ Company: _____ Address: _____ City: _____ State: ___ Zip: ___
Insurance Provider	Name of insurance provider: TOMIL Policy No.: _____ Date insurance provider was notified about this release: _____

RELEASE DETAILS

☐ Confirmed ☐ Suspected	☐ AST ☑ UST	Date discovered: 12.30.16	Date reported to TCEQ: 12.32.16	Tank system piping:	☑ pressurized ☐ suction/gravity ☐ unknown

Check all that apply:

Release discovery
- ☐ Routine tank closure or site assessment
- ☐ Free product or sheen
- ☐ Odors
- ☐ Automatic tank gauge
- ☐ Probe or sensor
- ☐ Inventory records
- ☐ Tank tightness test failure
- ☐ Line tightness test failure
- ☐ Groundwater monitoring well
- ☐ 1-mo. SIR failure or "inconclusive"
- ☐ 2-mo. inventory control discrepancy
- ☐ Vapor detection (auto or manual)
- ☐ Public or private water supply contaminated

Substance
- ☐ Gasoline (leaded, unleaded, unknown)
- ☐ Diesel/Fuel oil
- ☐ Waste oil
- ☐ Hydraulic/ transmission/ mineral oil
- ☐ Jet fuel/kerosene
- ☐ Petroleum of unknown type
- ☐ Hazardous subst. (describe in Comments)
- ☐ Unknown
- ☐ Other (describe in Comments)

Impacted media
- ☐ Groundwater
- ☐ Surface water
- ☐ Soil
- ☐ Air

Cause
- ☐ Spill
- ☐ Overfill
- ☐ Phys/mech damage
- ☐ Faulty installation
- ☐ Corrosion
- ☐ Other (describe in Comments)
- ☐ Unknown

Source
- ☐ Tank
- ☐ Dispenser
- ☐ Piping
- ☐ Submersible Turbine Pump (STP) Area
- ☐ Delivery Problem
- ☐ Other (describe in Comments)
- ☐ Unknown

Comments/Notes

SUPER - INVENTORY CONTROL - PROCEDURES TO
RE-EVALUATE & MODIFY.
TANK & LINE TIGHT

RECEIVED
AUG 13 2018
TCEQ
CENTRAL FILE ROOM

<<< TCEQ USE ONLY >>>   PM: complete this form when a PST release is reported to TCEQ, and provide to Admin Staff for LPST number assignment. Initial here to assign new LPST no.: _____ PM   TL/2nd Reviewer   ADMIN   fax completed form to RP & enter into appropriate databases. NEW LPST ID#: _____   Priority Code: _____   Region No.: _____   County Code: _____

TCEQ-20097 December 2007 (previous versions obsolete)