AIR CO/WM0052G/RN102296860/CO

Texas Comission on Environmental Quality Investigation Report WHITING OIL AND GAS CORPORATION CN600132757

GW OBRIEN 457 TANK BATTERY

RN102296860

Investigation # 825863		Incident # 137933				
Investigator: JESUS BENS	010	Site Classification MIN 0-15 FINS				
Conducted: 06/04/2010 0	06/04/2010	SIC Code: 1311 NAIC Code: 211112				
Program(s): AIR NEW PERMITS	SOURCE					
Investigation Type : Compli	ance Invest File Review	Location : FROM ODESSA GO 20 WEST 36 MILES TO MONAHANS TURN RIGHT ON 18 NORTH GO 8 MILES THE SITE IS LOCATED ON THE LEFT 0.25 MILE FROM ROUTE 18 NORTH				
Additional ID(s): 82977 WM0052	G					
Address: ; ,	Activity Typ	e : REGION 07 - MIDLAND UML3 - Upset Maintenance Level 3				
<u>Principal(s) :</u> Role	Name					
RESPONDENT	WHITING OIL AND	GAS CORPORATION				
<u>Contact(s) :</u>						
Role	Title	Name Phone MONTY MANSELL Work (432) 686-6516				
Regulated Entity Contact						
Regulated Entity Contact						
Regulated Entity Contact Other Staff Member(s) :						
Regulated Entity Contact Other Staff Member(s) : Role	Name					
Other Staff Member(s) :	Name ROBERT BRADSH ALICE CONE JARED BASURTO	MR JOEY NOYOLA Work (432) 943-1307				
<u>Other Staff Member(s) :</u> Role QA Reviewer Supervisor	ROBERT BRADSH ALICE CONE	MR JOEY NOYOLA Work (432) 943-1307 HAW				
<u>Other Staff Member(s) :</u> Role QA Reviewer Supervisor	ROBERT BRADSH ALICE CONE JARED BASURTO	MR JOEY NOYOLA Work (432) 943-1307 HAW				

Investigation Comments :

INTRODUCTION

Introduction: Incident #137933 has been reviewed for compliance with Title 30 Texas Administrative Code Chapter 101 (30 TAC 101), 101.201, 101.222(a) and (b). The investigator finds that this incident was reported properly per 30 TAC 101.201 in a timely manner. The investigator's review of this incident finds that the incident is not found to be excessive pursuant to 30 TAC 101.222(a) per the information provided in the final report. The cause of this incident occurred at a site not owned

	() ·	\bigcirc
2 of 2		
malfunction or t designed to ope	preakdown of equipment at the site for	tigator finds that the RE experienced no or which the incident was reported. This site is and it operated as represented in the ed to this Investigation
	· · ·	
Signed /2	<u>Environmental Investigator</u>	Date 06/04/2010
Signed	Supervisor	_ 4/ Date <u>6.7.70</u>
Attachments	: (in order of final report sub	omittal)
Enforcement	Action Request (EAR)	Maps, Plans, Sketches
Letter to Fac	ility (specify type) :	Photographs
	port	Correspondence from the facility
Investigation Re		Other (specify) :
Investigation Re		
Investigation Re		Other (specify): INCIDENT 137933 AND 12 NONTH SUMMARIS

.

.

-

Texas Commission on Environmental Quality

Emissions Ekaht Review (On or After 01/05/2006) Checklist

Unit Name : uml3

Investigation #:825863

Facility Name : GW OBRIEN 457 TANK BATTERY

County : WINKLER TCEQ Investigator : JESUS BENSOJO

Due Item Comments Answer Description Date No. 6 NO Was the emissions event(s) excessive? [101.222(a)] 7 YES Did the owner/operator comply with the requirements of TAC §101.201 (relating to Emissions Event Reporting and Recordkeeping Requirements)? [101.222(b)(1)] 8 YES Did the owner/operator prove that the unauthorized emissions were caused by a sudden, unavoidable breakdown of equipment or process, beyond the control of the owner/operator? [101.222(b)(2)] 9 YES Did the owner/operator prove that the unauthorized emissions did not stem from any activity/event that could have been foreseen and avoided/planned for, or been avoided by better operation and maintenance practices or technically feasible design consistent with good engineering practice? [101.222(b)(3)] 10 YES Did the owner/operator prove that the air pollution control equipment/processes were maintained and operated in a manner consistent with good practice for minimizing emissions and reducing the number of emissions events? [101.222(b)(4)] 11 YES Did the owner/operator prove that prompt action was taken to achieve compliance once the operator knew or should have known that applicable emission limitations were being exceeded, and any necessary repairs were made as expeditiously as practicable? [101.222(b)(5)] 12 YES Did the owner/operator prove that the amount and duration of the unauthorized emissions and any bypass of pollution control equipment were minimized and all possible steps were taken to minimize the impact of the unauthorized emissions or ambient air quality? [101.222(b)(6)] 13 YES Did the owner/operator prove that all emission monitoring systems were kept in operation if possible? [101.222(b)(7)] 14 YES Did the owner/operator prove that the owner/operator actions in response to the unauthorized emissions were documented by contemporaneous operation logs or other relevant evidence? [101.222(b)(8)] 15 YES Did the owner/operator prove that the unauthorized emissions were not part of a frequent or recurring pattern indicative of inadequate design, operation, or maintenance? [101.222(b)(9)] 16 YES Did the owner/operator prove that the percentage of a facility's total annual operating hours during which unauthorized emissions occurred were not unreasonably high? [101.222(b)(10)]

17	Did the owner/operator prove that the unauthorized emissions did not cause or contribution exceedance of the national ambient duality standards (NAAQS), prevention of significant deterioration (PSD) increments, or to a condition of air pollution? [101.222(b)(11)]	YES .	
18	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
19	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
20	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
21	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
22	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
23	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
24	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
25	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
26	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
27	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	

.

.

.

.

.

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



Attachment 1

INCIDENT 137933

WHITING OIL AND GAS CORPORATION GWO-457 BTY

> WINKLER COUNTY, TEXAS WM0052G CN600132757 RN102296860

INVESTIGATION NO. 825863 INVESTIGATOR: JESUS J. BENSOJO DATE: JUNE 04, 2010

Page 1 of 2

au

825863 Acc NUM#: _ WM@ 329

Confirm Final Report of Incident 137933 to Send to TCEQ Regulated Entity: RN102296860 Today's date is: 04/13/2010

Incident Tracking Num	137933			In	cident Status:	OPEN				
Submittal Type:		FINAL	REPORT							
Name of Owner or Ope	rator:	WHITI	NG OIL AND GA	S CORPORAT		egulated Entity umber:	RN102296860			
Physical Location:		FROM ODESSA GO 20 WEST 36 MILES TO MONAHANS TURN RIGHT ON 18 NORTH GO 8 MILES THE SITE IS LOCATED ON THE LEFT 0.25 MILE FROM ROUTE 18 NORTH								
Event/Activity Type:		EMISSIONS EVENT								
Date and Time Event D or Scheduled Activity S	04/05/2010 @ 14:00									
Event Duration:		99 hours, 0 minutes								
Process Unit or Area Co	ommon Name	s					······································			
GWO-457 Bty										
Facility Common Name				Facility Id	entification]	Number (FIN)				
GWO-457 Bty		· · · ·								
Emission Point Commo	Emission Point Common Name:					r:	<u></u>			
Flare	<u> </u>			-						
List of Air Contaminan	t Compounds									
Description	Est. Qua Opacity	ntity/	Units	Emission Limit	Units	Authorization				
Hydrogen Sulfide	1.70		POUNDS	0.01000	TONS/YR	PBR 82977				
VOCs	57.15		POUNDS	9.68000	TONS/YR		· · · · ·			
NOX	30.70	<u></u>	POUNDS	0		'No specific em this facility'	issions authorizations fo			
СО	61.30		POUNDS	0		'No specific em this facility'	issions authorizations fo			
Sulfur dioxide	160.18		POUNDS	0		'No specific em this facility'	issions authorizations fo			
Cause of Emission Ever	nt or Excess O	pacity Even	t, or Reason for S	cheduled Activ	vity:					
Targa Permian is shutting causing us, Whiting, to fl			s to their 16" gath	ering line betwe	een Monahan	s and Whiting's Wic	kett, CO2 Gas Plant			
Actions Taken, or Being	g Taken, to M	inimize Emi	ssions And/or Co	rrect the Situa	tion:					
TARGA completed their	repairs / main	tenance, cont	inued accepting o	ir gases, and wo	e stopped all	flaring.				
Basis Used to Determin	e Quantities a	nd Any Add	itional Informati	on Necessary t	o Evaluate t	he Event:				
We use gas flow rate, con	mposition of th	e gas and mo	eculer weight of	the constituents	to determine	the total emmission	ns.			
Person Making Notifica	tion: M	onty Mansel	l	Date/Tin	ne:	04/05/	2010 @ 04:42:53 PM			
Notifier Phone:	4	2-6866516								
Incident Contact: Brian Ashburn										
Contact E-mail:	bi	ian.ashburn@)whiting.com							
Contact Phone:	4	32-6866745 e	ext:							
Notification Jurisdictio		MIDLAND								

0

Affirmative Defense	The owner or operator of the regulated entity asserts this reported event or activity, as applicable, meets the applicable affirmative defense criteria. YES	
Publication Status:	VERIFIED	

I agree that data displayed in this report is the exact data or is acceptably equivalent to the data provided for the specified regulated entity, and the information is, to the best of my knowledge, true, accurate and complete. By entering my password and pressing the 'Confirm Submit' button, I agree that:

- 1. I am Monty C Mansell, the owner of the STEERS account ER019660.
- 2. I have the authority to submit this data on behalf facility located at RN102296860.
- 3. I have personally examined the foregoing and am familiar with its content and the content of any attachments, and based upon my personal knowledge and/or inquiry of any individual responsible for information contained herein, that this information is true, accurate, and complete.
- 4. I further certify that I have not violated any term in my TCEQ STEERS participation agreement and that I have no reason to believe that the confidentiality or use of my password has been compromised at any time.
- 5. I understand that use of my password constitutes an electronic signature legally equivalent to my written signature.
- 6. I also understand that the attestations of fact contained herein pertain to the implementation, oversight and enforcement of a federal environmental program and must be true and complete to the best of my knowledge.
- 7. I am aware that criminal penalties may be imposed for statements or omissions that I know or have reason to believe are untrue or misleading.
- 8. I am knowingly and intentionally submitting 1 incident record.

This document was signed by Monty C Mansell. Signature Hash: 9F1E614CB7BF768ED4D779A9590A831CF5D859B8C6A6FF5625E8DA40822C01A9

The following is additional information contained in your Copy of Record: Submission IP address: 208.180.181.230 Submission date and time: 04/13/2010 09:44:56 AM Submission STEERS Version: 5.60 Submission Confirmation Number: 72938 Submission Data Hash Code: 72669A5B3543B844863C0C8308316A76D99B87ABAC15A834AEC9901268EA29EE STEERS AEME Incident Id: 75760

(4/13/2010) WWW - UPSET07 - TCEQ Incidents for Confirmation 72938 were entered today

From: To: Date: Subject: <UPSET07@tceq.state.tx.us> <UPSET07@tceq.state.tx.us> 4/13/2010 11:40 AM TCEQ Incidents for Confirmation 72938 were entered today Page 1

* DO NOT REPLY TO THIS E-MAIL *

TCEQ Incident #137933 (AEME ID 75760), with a Discovery Date of 04/05/2010 02:00 PM, Type of EMISSIONS EVENT was entered today for Regulated Entity: RN102296860 GW OBRIEN 457 TANK BATTERY

This email is sent whenever an incident is submitted through STEERS. If this incident was submitted via STEERS using a probationary account, or if this incident was entered/modified by TCEQ staff, you will have until midnight 04/16/2010 to verify the information on the Incident(s). Otherwise, you may disregard this email.

to verify the information on the Incident(s).

You may review the information on this incident online at:

https://www6.tceq.state.tx.us/steers

WARNING:

As we either enter or correct data for your incident report form,

the database is updated immediately.

If you try to review this incident before our data entry is complete,

you may see only part of the data from your incident report---for example,

our database may show that the incident occurred but show no data on contaminants.

If this happens, please do not repudiate the information.

Instead, cancel the process and review the incident again later.

(4/13/2010) WWW - UPSET07 - STEERS Air Emissions Submitted - Incident 137933

From:<steers@tceq.state.bx.us>To:<monty.mansell@whiting.com>CC:<upset07@tceq.state.bx.us>Date:4/13/2010 9:40 AMSubject:STEERS Air Emissions Submitted - Incident 137933

This confirms the submittal of your incident information to the TCEQ. You submitted a final report for incident 137933, regulated entity RN102296860. Your submittal was received at 04/13/2010 09:44 AM.

The confirmation number for this submittal is 72938-

72669A5B3543B844863C0C8308316A76D99B87ABAC15A834AEC9901268EA29EE.

You may access the copy of record from the submit log which is available from the Home page of STEERS Internet Version 5.6.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers@tceq.state.tx.us.

(4/6/2010) WWW - UPSET07 - TCEQ Incidents for Confirmation 72779 were entered today

Page

 From:
 <UPSET07@tceq.state.bx.us>

 To:
 <UPSET07@tceq.state.bx.us>

 Date:
 4/5/2010 6:40 PM

 Subject:
 TCEQ Incidents for Confirmation 72779 were entered today

* DO NOT REPLY TO THIS E-MAIL *

TCEQ Incident #137933 (AEME ID 75590), with a Discovery Date of 04/05/2010 02:00 PM, Type of EMISSIONS EVENT was entered today for Regulated Entity: RN102296860 GW OBRIEN 457 TANK BATTERY

This email is sent whenever an incident is submitted through STEERS. If this incident was submitted via STEERS using a probationary account, or if this incident was entered/modified by TCEQ staff, you will have until midnight 04/08/2010 to verify the information on the Incident(s). Otherwise, you may disregard this email.

to verify the information on the Incident(s).

You may review the information on this incident online at:

https://www6.tceq.state.tx.us/steers

WARNING:

As we either enter or correct data for your incident report form,

the database is updated immediately.

If you try to review this incident before our data entry is complete,

you may see only part of the data from your incident report---for example,

our database may show that the incident occurred but show no data on contaminants.

If this happens, please do not repudiate the information.

Instead, cancel the process and review the incident again later.

(4/5/2010) WWW - UPSET07 - AEME Initial Notification

From:	<steers@tceq.state.tx.us></steers@tceq.state.tx.us>
To:	<upset07@tceq.state.bx.us></upset07@tceq.state.bx.us>
Date:	4/5/2010 4:40 PM
Subject:	AEME Initial Notification

The following AEME initial notification was submitted via STEERS:

Regulated Entity: RN102296860 Name of Owner/Operator: WHITING OIL AND GAS CORPORATION Incident Type: EMISSIONS EVENT Incident Status: VERIFIED Physical Location: FROM ODESSA GO 20 WEST 36 MILES TO MONAHANS TURN RIGHT ON 18 NORTH GO 8 MILES THE SITE IS LOCATED ON THE LEFT 0.25 MILE FROM ROUTE 18 NORTH Page 1

Event Start Date and time: 04/05/2010 @ 14:00 Contact Name: Brian Ashburn Contact Phone: 432 - 6866745 ext: Cause (first 50 characters): Targa Permian is shutting down for scheduled repai Confirmation Number: 72779-586BEB383FE4CED1D8DCD26CF0358F5FF23B9BBDBF56547D3D8AD4C5D4635795

This initial notification has NOT YET been entered into the official TCEQ CCEDS database. Once it has been entered, you will receive another email containing the incident tracking number.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers@tceq.state.tx.us.

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



Attachment 2

12 MONTH SUMMARY

WHITING OIL AND GAS CORPORATION GWO-457 BTY

> WINKLER COUNTY, TEXAS WM0052G CN600132757 RN102296860

Investigation No. 825863 Investigator: Jesus J. Bensojo Date: June 04, 2010

Reportable Events 12 Month Summary

Date	Region		RN#	inc	;# St	aff	Туре	EPN Name	EPN#	FIN Name	FIN #	PCN Name
04/05/2010			N 07 - RN102296860		All All		All	Ali	All	All	All	All
RN10229	6860	GW O	BRIEN 4	57 TANK	BATTER	Y	~4-					
Inc# Type)	Status	Staff	Start DT	End DT	Duration	Duration %	EPN Name	EPN #	FIN Name	FIN #	PCN Name
122507 EMIS EVEN Cause		CLOSED downstre		04/07/2009 shut down,		66 Hr 30 Mi to flare.	n. 0.75%			GWO 457	aan farananga kultur — arri	(GWO 457
128315 EMIS EVEN	SIONS	CLOSED	VMCLEAN	08/18/2009	08/28/2009	251 Hr 0 Mi	n. 2.87%	Flare		G.W.O. 457 TAN BATTERY	K	G.W.O. 457 TANK BATTERY
Cause	SO2 =	26.3 lb/d	ay	eline leak ca ed a reportal	-							
37933 EMIS EVEN	SIONS	CLOSED	JBENSOJO	04/05/2010	04/09/2010	99 Hr 0 Min	. 1.13%	Flare	n I National and the second second	GWO-457 Bty	e e e se ¹ st. uzunz neur mennen 1746	GWO-457 Bty
Cause			is shutting excess ga		heduled rep	pairs to thei	r 16" gathei	ring line betweer	n Monahans an	d Whiting's Wicke	ett, CO2 Gas F	Plant causing us,

	A Imission on Investigati IITING OIL AND G CN6001	Environn. on Report AS CORPORA	-
	GW OBRIEN 457		RY
	RN1022		4 400507
Investigation #747350			ŧ 122507
Investigator: JESUS BI	ENSOJO	<u>Site Classific</u> MIN 0-15 F	
Conducted: 05/28/2009	9 05/28/2009	SIC Code NAIC Co	e: 1311 de: 211112
Program(s): AIR N PERM	EW SOURCE IITS		
Investigation Type : Co		MILES TO MO NORTH GO 8	COM ODESSA GO 20 WEST 36 ONAHANS TURN RIGHT ON 18 MILES THE SITE IS LOCATED 0.25 MILE FROM ROUTE 18
Additional ID(s): 8297 WM0			
Address: ; ,	Activity Typ		MIDLAND Maintenance Level 3
<u>Principal(s) :</u> Role	Name		
RESPONDENT	WHITING OIL AND	GAS CORPORATIO	DN
Contact(s) :			
Role	Title	Name	Phone
Regulated Entity Contact	PRINCIPAL ENGINEER	JAGADEESAN SETHURAMAN	Work (303) 390-4986
Other Staff Member(s) :			
Role	Name		france range
QA Reviewer	ROBERT BRADSH	IAW	RECEIVED JUN 0 9 2009
Supervisor	ALICE CONE		JUN 0 9 2000
	Associated Che	ck List	
Checklist Name		<u>Unit Name</u>	CENTRAL FILE ROOM

Checklist Name Emissions Event Review (On or After 01/05/2006)

Unit Name UML3

Investigation Comments:

INTRODUCTION

÷

Introduction: Incident #122507 has been reviewed for compliance with Title 30 Texas Administrative Code Chapter 101 (30 TAC 101), 101.201, 101.222(a) and (b). The investigator finds that this incident reported properly per 30 TAC 101.201 in a timely manner. The investigator's review of this incident finds that the incident is not found to be excessive pursuant to 30 TAC 101.222(a) per the information provided in the final report. The cause of this incident occurred at a site not owned or operated by the regulated entity (RE). The investigator finds that the RE experienced no malfunction or breakdown of equipment at the site for which the incident was reported. This site is designed to

GW OBRIEN 457 TANK BATTERY - KERMIT

5/28/2009 Inv. # - 747350

Page 2 of 2

operate as it was authorized to operate and it operated as represented in the authorization during this incident.

No Violations Associated to this Investigation

/aime Signed (vironmental Investigator

05/28/09 Date

Chie 4 Signed Supervisor

Date 6/1/01

Attachments: (in order of final report submittal)

____Enforcement Action Request (EAR)

Letter to Facility (specify type) : ____

Investigation Report

<u>Sample Analysis Results</u>

___Manifests

___NOR

Texas Commission on Environment Quality

Emissions Event Review (On or After 01/05/2006) Checklist

Unit Name: UML3

Investigation #:747350

County : WINKLER TCEQ Investigator : JESUS BENSOJO

Facility Name : GW OBRIEN 457 TANK BATTERY

ltem No.	Description	Answer	Comments	Due Date
6	Was the emissions event(s) excessive? [101.222(a)]	NO		
7	Did the owner/operator comply with the requirements of TAC §101.201 (relating to Emissions Event Reporting and Recordkeeping Requirements)? [101.222(b)(1)]	YES		
8	Did the owner/operator prove that the unauthorized emissions were caused by a sudden, unavoidable breakdown of equipment or process, beyond the control of the owner/operator? [101.222(b)(2)]	YES		
9	Did the owner/operator prove that the unauthorized emissions did not stem from any activity/event that could have been foreseen and avoided/planned for, or been avoided by better operation and maintenance practices or technically feasible design consistent with good engineering practice? [101.222(b)(3)]	YES		
10	Did the owner/operator prove that the air pollution control equipment/processes were maintained and operated in a manner consistent with good practice for minimizing emissions and reducing the number of emissions events? [101.222(b)(4)]	YES		
11	Did the owner/operator prove that prompt action was taken to achieve compliance once the operator knew or should have known that applicable emission limitations were being exceeded, and any necessary repairs were made as expeditiously as practicable? [101.222(b)(5)]	YES		
12	Did the owner/operator prove that the amount and duration of the unauthorized emissions and any bypass of pollution control equipment were minimized and all possible steps were taken to minimize the impact of the unauthorized emissions on ambient air quality? [101.222(b)(6)]	YES		
13	Did the owner/operator prove that all emission monitoring systems were kept in operation if possible? [101.222(b)(7)]	YES		
14	Did the owner/operator prove that the owner/operator actions in response to the unauthorized emissions were documented by contemporaneous operation logs or other relevant evidence? [101.222(b)(8)]	YES		
15	Did the owner/operator prove that the unauthorized emissions were not part of a frequent or recurring pattern indicative of inadequate design, operation, or maintenance? [101.222(b)(9)]	YES		
16	Did the owner/operator prove that the percentage of a facility's total annual operating hours during which unauthorized emissions occurred were not unreasonably high? [101.222(b)(10)]	YES		

17	Did the owner/operator prove that the uthorized emissions did not cause or contribute h exceedance of the national ambient air quality standards (NAAQS), prevention of significant deterioration (PSD) increments, or to a condition of air pollution? [101.222(b)(11)]	YES	
18	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
19	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
20	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
21	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
22	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
23	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
24	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
25	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
26	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	
27	Other violations that relate to this unauthorized emissions event can be cited here.	COMPLIANT	

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



ATTACHMENT 1

INCIDENT 122507 & 12 MONTH SUMMARY

WHITING OIL AND GAS CORPORATION GW OBRIEN 457 TANK BATTERY WINKLER COUNTY WM0052G CN600132757 RN102296860

> Investigation Number: 747350 Investigator: JESUS BENSOJO Date: May 28, 2009

AL

· nvestly Confirm Final Report of Incident 122507 to Send to TCEQ Regulated Entity: RN102296860 Today's date is: 04/16/2009

Hon # 747350 GCC # SWM0052G

Incident Tracking Numb	122507			Incident S	tatus:	OPEN				
Submittal Type:		FINAL	REPORT					.I \		
Name of Owner or Opera	itor:	WHITT	NG OIL AND GAS	CORPORATI	ION	Regulated Number:	Entity	RN102296860		
Physical Location:	,	FROM ODESSA GO 20 WEST 36 MILES TO MONAHANS TURN RIGHT ON 18 NORTH GO 8 MILES THE SITE IS LOCATED ON THE LEFT 0.25 MILE FROM ROUTE 18 NORTH								
Event/Activity Type:		EMISSIONS EVENT								
Date and Time Event Dis or Scheduled Activity Sta		04/07/2009 @ 17:00								
Event Duration:		66 hours, 30 minutes								
Process Unit or Area Con	nmon Names									
GWO 457										
Facility Common Name				Facility Ide	ntificati	on Number	(FIN)			
GWO 457										
Emission Point Common	Name:			Emission Po	oint Nur	nber:				
flare '				flare						
List of Air Contaminant	Compounds		· · · ·	.						
Description	Est. Quant Opacity	ity/	Units	Emission Limit	Unit	S	Authorizati	on		
NOX	25.06		POUNDS	0			not included in the PBR 82977			
со	50.026		POUNDS	0			not included in the PBR 82977			
Sulfur dioxide	315.511		POUNDS	0			not included in the PBR 82977			
Hydrogen Sulfide	3.352		POUNDS	.09	TON	IS/YR	PBR 82977			
VOCs	75.89		POUNDS	9.68	TON	IS/YR	PBR 82977			
Cause of Emission Event	or Excess Opa	city Event	, or Reason for Sc	heduled Activi	ity:			·		
Targa downstream facility	shut down, rou	ting gas to t	flare.							
Actions Taken, or Being	l'aken, to Min	imize Emis	sions And/or Cor	rect the Situati	ion:					
Targa attempting to fix plan	nt and make op	erational.								
Basis Used to Determine	Quantities and	l Any Addi	tional Informatio	n Necessary to	Evaluat	te the Event				
Used the gas flow rate, the estimated for potential dura		f the gas, an	d the molecular we	ight of constitu	ients to d	letermine the	total emissi	ons. Emissions are		
Person Making Notification	on: Dani	iel Morel		Date/Time:			04/08/20	09 @ 04:47:49 PM		
Notifier Phone:	303-	3904087								
Incident Contact:	Jaga	Jagadeesan Sethuraman								
Contact E-mail:	deesan.seth	uraman@whiting.c	om							
Contact Phone:	303-	3904986 ex	t:							
Notification Jurisdictions	REG	ION 07 - N	AIDLAND							
Affirmative Defense			perator of the regularity defense crite		rts this re	eported even	t or activity,	as applicable, meets the		
Publication Status:	VER	IFIED								

I agree that data displayed in this report is the exact data or is acceptably equivalent to the data provided for the specified regulated entity.

- 1. I am Joey M Noyola.
- 2. I have protected my account/password and am in full compliance with the electronic signature agreement submitted to receive account ER017254.
- 3. I have the authority to submit this data on behalf of the facility located at RN102296860.
- 4. This action constitutes an electronic signature equivalent to my written signature.
- 5. I am knowingly and intentionally submitting 1 incident record.

This document was signed by Joey M Noyola. Signature Hash: 8CE5389A909A5E9B69A31064F1D95C6BABA0E798DC579CA63D49EF2B6CA537E2

The following is additional information contained in your Copy of Record: Submission IP address: 208.42.241.30 Submission date and time: 04/16/2009 11:38:54 AM Submission STEERS Version: 5.52 Submission Confirmation Number: 64086 Submission Data Hash Code: A6F93FC7ED48F278C457206C627BF66A06AD3D9501BA2684E89634BA791CF29E STEERS AEME Incident Id: 66264

.,

(4/16/2009) WWW - UPSET07 - TCEQ Incidents for Confirmation 64086 were entered today

Page 1

 From:
 <UPSET07@tceq.state.bx.us>

 To:
 <UPSET07@tceq.state.bx.us>

 Date:
 4/16/2009 1:39 PM

 Subject:
 TCEQ Incidents for Confirmation 64086 were entered today

* DO NOT REPLY TO THIS E-MAIL *

TCEQ Incident #122507 (AEME ID 66264), with a Discovery Date of 04/07/2009 05:00 PM, Type of EMISSIONS EVENT was entered today for Regulated Entity: RN102296860 GW OBRIEN 457 TANK BATTERY

This email is sent whenever an incident is submitted through STEERS. If this incident was submitted via STEERS using a probationary account, or if this incident was entered/modified by TCEQ staff, you will have until midnight 04/19/2009 to verify the information on the Incident(s). Otherwise, you may disregard this email.

to verify the information on the Incident(s).

You may review the information on this incident online at:

https://www6.tceq.state.tx.us/steers

WARNING:

2

As we either enter or correct data for your incident report form,

the database is updated immediately.

If you try to review this incident before our data entry is complete,

you may see only part of the data from your incident report---for example,

our database may show that the incident occurred but show no data on contaminants.

If this happens, please do not repudiate the information.

Instead, cancel the process and review the incident again later.

(4/16/2009) W.WW - UPSET07 - STEERS Air Emissions Submitted - Incident 122507

 From:
 <steers@tceq.state.bc.us>

 To:
 <joey.noyola@whiting.com>

 CC:
 <upset07@tceq.state.bc.us>

 Date:
 4/16/2009 11:39 AM

 Subject:
 STEERS Air Emissions Submitted - Incident 122507

This confirms the submittal of your incident information to the TCEQ. You submitted a final report for incident 122507, regulated entity RN102296860. Your submittal was received at 04/16/2009 11:38 AM.

The confirmation number for this submittal is 64086-

:

A6F93FC7ED48F278C457206C627BF66A06AD3D9501BA2684E89634BA791CF29E.

You may access the copy of record from the submit log which is available from the Home page of STEERS Internet Version 5.5.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers@tceq.state.tx.us.

(4/9/2009) WWW - UPSET07 - TCEQ Incidents for Confirmation 63876 were entered today

From: To: Date: Subject: <UPSET07@tceq.state.tx.us> <UPSET07@tceq.state.tx.us> 4/8/2009 6:48 PM TCEQ Incidents for Confirmation 63876 were entered today Page

* DO NOT REPLY TO THIS E-MAIL *

TCEQ Incident #122507 (AEME ID 66038), with a Discovery Date of 04/07/2009 05:00 PM, Type of EMISSIONS EVENT was entered today for Regulated Entity: RN102296860 GW OBRIEN 457 TANK BATTERY

This email is sent whenever an incident is submitted through STEERS. If this incident was submitted via STEERS using a probationary account, or if this incident was entered/modified by TCEQ staff, you will have until midnight 04/11/2009 to verify the information on the Incident(s). Otherwise, you may disregard this email.

to verify the information on the Incident(s).

You may review the information on this incident online at:

https://www6.tceq.state.bx.us/steers

WARNING:

As we either enter or correct data for your incident report form,

the database is updated immediately.

If you try to review this incident before our data entry is complete,

you may see only part of the data from your incident report---for example,

our database may show that the incident occurred but show no data on contaminants.

If this happens, please do not repudiate the information.

Instead, cancel the process and review the incident again later.

(4/9/2009) WWW - UPSET07 - AEME Initial Notification

From:	<steers@tceq.state.tx.us></steers@tceq.state.tx.us>
To:	<upset07@tceq.state.tx.us></upset07@tceq.state.tx.us>
Date:	4/8/2009 4:48 PM
Subject:	AEME Initial Notification

The following AEME initial notification was submitted via STEERS:

Regulated Entity: RN102296860 Name of Owner/Operator: WHITING OIL AND GAS CORPORATION Incident Type: EMISSIONS EVENT Physical Location: FROM ODESSA GO 20 WEST 36 MILES TO MONAHANS TURN RIGHT ON 18 NORTH GO 8 MILES THE SITE IS LOCATED ON THE LEFT 0.25 MILE FROM ROUTE 18 NORTH

Event Start Date and time: 04/07/2009 @ 17:00 Contact Name: Jagadeesan Sethuraman Contact Phone: 303 - 3904986 ext: Cause (first 50 characters): Targa downstream facility shut down, routing gas t Confirmation Number: 63876-613C78BCAAA8C3D77B207E9E05CE730AC32FD9D65A120B5E4C3483484229E6B4

This initial notification has NOT YET been entered into the official TCEQ CCEDS database. Once it has been entered, you will receive another email containing the incident tracking number.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers @ tceq.state.tx.us.

Reportable Events 12 Month Summary

Date	Date Region		RN#	ind	# St	aff Ty	ype	EPN Name	EPN #	FIN Name	FIN #	PCN Name 🔌	
04/07/2	009 REGIO MIDLA		RN1022	RN102296860 AI				All	All	All	All	Ali	
RN102296860		GW O	GW OBRIEN 457 TANK BATTERY										
Inc#	Туре	Status	Staff	Start DT	End DT	Duration	Duration %	EPN Name	EPN#	FIN Name	FIN #	PCN Name	
	EMISSIONS Event	CLOSED	ACONE	04/07/2009	04/10/2009	66 Hr 30 Min.	0.75%	flare	flare	GWO 457		GWO 457	

Cause: Targa downstream facility shut down, routing gas to flare.

()

4 . . /