Item Barcode:

00254460

Attachment #1 AIR PERMIT

FODLER LEVEL

AIR PA #:	HP0495D	035262		
File Type:	PERMITS			
Volume:	001			
Inclusive Dates:	1/1/2003 - 12	2/31/2004		
Media	a Code/ Form		☐ Microfiche	
			⊠ Roll Microfilm	

Files appearing on this roll of microfilm/ electronic image were filmed/ scanned as received and per instructions from the Texas Commission on Environmental Quality's Records Managemeent Coordinator, Kate Fitzpatrick.

Box Barcode:

Ale p	of Invact#/ h	N102570421/30	PA PAGE 1 of
06/29/2004 NSR 1	PERMITS IMS- PROJECT REG	CORD	
PROJECT#: 107682	PERMIT#: 35262	STATUS: C	DISP CODE:
RECEIVED: 12/06/2002	PROJTYPE: XOWN	RENEWAL:	ISSUED DATE:
FEE DATE: GROUP: PAR	FEE AMT: \$ 0	STDX1/SP: 0	SUP-DISP DATE: 06/30/2004
PAR1_2: STEGER, JULIE			
ADMIN REVIEW			
A - PAR RECEIVED :	12/06/2002 A - CENTRAL UPDATED :	REGISTRY 09/15/2003	CEIVE MA
ISSUED TO: CHEVRON US COMPANY NAME: CHEVR CUSTOMER REGISTRY ID PRIMARY CONTACT INF CONTACT TYPE: RESPON	ON USA INC : CN600132484 ORMATION		AUG 26 2019 CENTRACEGE ROOM
NAME: MR PETER BOTES PHONE: 432-687-7297 ext		TITLE: ENVIRONMENTAL FAX: 432-687-7660 ext	SPECIALIST
STREET: 15 SMITH ROAD		CITY/STATE,ZIP: MIDLANI	D. TX . 70905-
UNIT: SSU SATELLITE #1- SIC: 0 REGION: 2 SITE NAME: SSU SATELLI COUNTY: HOCKLEY CAPACITY: LOCATION: APPROX. 7.6 M CR. APPROX 0.1 MI	ACCOUNT: HP0495D	REG ENTITY ID: R UNITTYPE: 303 N. ON	RN102570421
PUBLIC NOTICE PUBLIC NOTICE REQUIRE	ED?: N PN1 ALT LANGU	JAGE: NO PN2 ALT LAN	IGUAGE: NO
EMISSION RATES			
TONS/YR REDUCTION	NOX CO VOC PM SO2 O	THER TOTAL	
PROJECT NOTES ADMINISTRATIVE: PREV	TOUS OWNER TEXACO E&I	P CO	
TECHNICAL ACTIVITY I	HISTORY		
PROJECT ATTRIBUTES			
PROJECT LINK			

PROJECTS/PERMITS VOIDANCE

Texas Commission on Environmental Quality Reportable Activity Report

Submittal Type

Incident #

Investigation #

FINAL

39153

Customer Name

CN#

CHEVRON USA INC

CN600132484

Name of Owner or Operator

RN/Air Acct #

Physical Location

SSU SATELLITE 1 19

RN102570421

APPROX. 7.6 MI. S. OF SUNDOWN ON RR 303

N. ON CR. APPROX 0.1 MI

Event/Activity Type

Date / Time Event Discovered or Scheduled Activity Start/End

Duration

MAINTENANCE

05/17/2004 @ 08:00 am 05/17/2004 @ 01:00PM

5 hrs. 0 min.

Process Unit or Area Common Na	me				
SSU Sat 1-19					1 2004
Facility Common Name		Facility Ider	ntification N	umber (FIN)	JIM 1 2009
production separater		PROD. SEP		ICEO	- CENTRAL FILE ROOM
Emission Point Common Name vent stack		Emission P	oint Number	(EPN)	
List of Compound Descriptive type(s) of individually Listed or Mixtures of Air Contaminant Compounds Released, including opacity	Estimated Total Quantity for Air Contaminants for Emissions / Opacity Value for Opacity	Units	Authorized Emissions Limit / Opacity Limit	Units	Authorization (rule or permit #)
Hydrogen suifide	46.000	POUNDS	0.000		35262
Non-Methane Non-Ethane Natural Gas	940.000	POUNDS	0.000		35262

Cause of Emissions Event of Excess Opacity Event, or Reason for Scheduled Activity:

maint. event - will SD and tie into Oxy line - gives us other options operationally if they go down

Oxy will be shutting their line down to make a tie in that will give us a second line to the Oxy plant. Once this tie in is complete. Oxy will be able to isolate a line and repair while continuing to deliver our gas to the plant. Less upset emissions.

Actions Taken, of Being Taken, to Minimize Emissions and/or Correct the Situation:

vent gas and make tie in

Due to the nature of CO2 it makes it difficult for us to shutin wells or pinch them back due to the pressure we will create on the wells. However, we are trying to coordinate our shut in with the Oxy tie in so that we only have to go down once. Tie ins were made and we were down for 5 hours only

This did not result in a reportable event

Basis Used to Determine Quantities and Any additional Information Necessary to Evaluate the Event:

RQ for NMNE natural gas by definition (5000#) in regs, gas analysis, excel spreadsheet, 24 hour basis

Person Making Initial Notification

Peter Botes - (432) 687-7297

Initial Notification Date/Time

05/06/2004 08:25

Method

STEERS

Person Making Final Report Peter Botes - (432) 687-7297

Final Report Date/Time 05/26/2004 07:25

Method **STEERS**

Incident Primary Contact

Peter Botes. (432) 687-7297

Jurisdiction(s) Notified

REGION 02 - LUBBOCK

Agency Comments

Assigned Staff Member: Gary Shipp

Facility Common Name

production separater

INTRODUCTION

On June 4, 2004, an Air Upset/Maintenance Level 4 investigation (UML4) was conduct for a scheduled maintenance, startup, and shutdown (SMSS) event, incident no. 39153. The investigation evaluated compliance with 30 TAC §101.211(a), 30 TAC §101.211(b), 30 TAC §101,222(a), and 30 TAC §101,222(c).

ASSESSMENT OF COMPLIANCE WITH STATE RULES

30 TAC §101.211 - Scheduled Maintenance, Startup, and Shutdown Reporting and Recordkeeping Requirements

30 TAC §101.211(a) - Notification

The initial notification for this SMSS was submitted to TCEQ Lubbock regional office on May 6, 2004 @ 07:25, via STEERS. The initial notification indicated the SMSS would begin on May 17, 2004, @ 8:00, and end on May 18, 2004 @, 8:00. The RE estimated that 222 lbs. of H2S and 4.515 lbs. of non-methane/non-ethane natural gas would be vented during the maintenance event. The SMSS was conducted so that the facility could be connected to another sales line. The additional line gives the operator another route for product in case of a pipeline failure and should reduce the likely hood of an emission event. Notice of the event was at least ten (10) day s prior to the SMSS event. All required information was contained in the notice.

30 TAC §101.211(b) - Final Record

The final SMSS record / report was received via STEERS on May 26, 2004, @ 7:25. This final report met the 14 days provision specified in the reporting requirements. The record retention requirement could not be evaluated, since this investigation only evaluated records maintained in the Lubbock Regional office..

30 TAC §101.211(c) - Final Record

For any scheduled maintenance, startup, or shutdown activity for which an initial notification was submitted under subsection (a) of this section, if the information required in subsection (b) of this section differs from the information provided under subsection (a) of this section, the owner or operator of the facility shall submit a copy of the final record to the commission office for the region in which the facility is located no later than two weeks after the end of the scheduled activity.

The final SMSS record / report was received via STEERS on May 26, 2004. @ 7:25. The final record showed that only 46 lbs. of H2S and 940 lbs. of non-methane/non-ethane natural gas was vented. In addition, the maintenance event only lasted 5 hours instead of 12 originally estimated.

30 TAC §101.222, Demonstrations

30 TAC §101.222(a) - Excessive Emission Events The executive director shall determine when emissions events are excessive.

An Emissions event is defined as any upset event or unscheduled maintenance, startup, or shutdown activity that results in unauthorized emissions from an emissions point. The final report demonstrated that the final total estimated quantity for non-methane / non-ethane natural gas did not exceed the quantity estimated in the initial notification. This SMSS was not required to be reported as a emission event, so this requirement is not applicable.

30 TAC §101.222(b) - Non-excessive events

Emissions events determined not to be excessive are subject to an affirmative defense to all claims in enforcement actions brought against these events, other than claims for administrative technical orders and action for injunctive relief.

An Emissions event is defined as any upset event or unscheduled maintenance, startup, or shutdown activity that results in unauthorized emissions from an emissions point. Since, this is a SMSS event this is not applicable.

30 TAC §101.222(c) - Scheduled maintenance, startup, or shutdown activity Emissions from a scheduled maintenance, startup, or shutdown activity are required to be included in a permit under Texas Health and Safety Code, §382.0518 or §382.0519, a standard permit under §382.05195, or a permit by rule under §382.05196

The RE submitted notification of the scheduled maintenance per 30 TAC §101.211(a), created a final record per 30 TAC §101.211(b), and submitted the final record to the TCEQ as required. The emissions could not have been prevented through planning and design and did not appear to be part of a recurring pattern indicative of inadequate design, operation, or maintenance. The facility is operated under Permit by Rule Registration No. 36262 and is permitted to vent gas. The operator indicated that shutting in well, or pinching back the wells is very difficult because to the pressure build up that would occur because of the CO2 used for oil recovery. The RE made the connection in five (5) hours instead of the twelve (12) hours estimated. The event did not cause a condition of air pollution.

CONCLUSION

The RE appeared to have complied with all rules and regulations for this SMSS, so no further action is warranted at this time.

Section Manager

6-7-04 Date 6-7-ewf

Date

WWW - UPSET02 - Web STEERS Air Emissions Submitted - Incident 39153

From: <steers@tceq.state.tx.us>
To:

Date: 5/26/2004 7:26 AM

Subject: Web STEERS Air Emissions Submitted - Incident 39153

CC: <upset02@tceq.state.tx.us>

This confirms the submittal of your incident information to the TCEQ. You submitted a final report for incident 39153, regulated entity RN102570421. Your submittal was received at 05/26/2004 07:25 AM.

The confirmation number for this submittal is 12588-7F4CA027C76CABBD084BE33B65F0B765. You may access the copy of record from the submit log which is available from the Home page of STEERS Internet Version 4.1.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers@tceq.state.tx.us.

WWW - UPSET02 - Web STEERS Air Emission Submitted - Incident 39153

From:

<steers@tceq.state.tx.us>

To:

<botespi@chevrontexaco.com>

Date:

5/6/2004 8:26 AM

Subject: Web STEERS Air Emission Submitted - Incident 39153

CC:

<up><upset02@tceq.state.tx.us>

This confirms the submittal of your incident information to the TCEQ. You submitted an initial notification for incident 39153, regulated entity RN102570421. Your submittal was received at 05/06/2004 08:25 AM.

The confirmation number for this submittal is 11799-E7374A874978E29A05E55F12974D9AD3. You may access the copy of record from the submit log which is available from the Home page of STEERS Internet Version 4.1.

If you have any questions please contact the STEERS Help Line at 512-239-6925 or by e-mail at steers@tceq.state.tx.us.

Texas @mmission on Environmenta@uality Reportable Activity Notification

Submittal Type

Incident #

Investigation #

INITIAL

39153

Customer Name

CN#

CHEVRON USA INC

CN600132484

Name of Owner or Operator

RN/Air Acct #

SSU SATELLITE 1 19

Physical Location

RN102570421

APPROX. 7.6 MI. S. OF SUNDOWN ON RR 303

N. ON CR. APPROX 0.1 MI

Event/Activity Type

Date / Time Event Discovered or Scheduled Activity Start/End Duration

MAINTENANCE

05/17/2004 @ 08:00 am 05/18/2004 @ 08:00AM

24 hrs. 0 min.

Process Unit or Area Common Name

SSU Sat 1-19

Facility Common Name

Facility Identification Number (FIN)

production separater

PROD. SEP.

Emission Point Common Name	Emission Point Number (EPN)				
vent stack	VENT				
List of Compound Descriptive type(s) of Individually Listed or Mixtures of Air Contaminant Compounds Released, Including opacity	Estimated Total Quantity for Air Contaminants for Emissions / Opacity Value for Opacity	Units	Authorized Emissions Limit / Opacity Limit	Units	Authorization (rule or permit #)
Hydrogen sulfide	222.000	POUNDS	0.000		35262
Non-Methane Non-Ethane Natural Gas	4,515.000	POUNDS	0.000		35262

Cause of Emissions Event of Excess Opacity Event, or Reason for Scheduled Activity:

maint. event - will SD and tie into Oxy line - gives us other options operationally if they go down Actions Taken, of Being Taken, to Minimize Emissions and/or Correct the Situation:

Basis Used to Determine Quantities and Any additional Information Necessary to Evaluate the Event:

gas analysis

Person Making Initial Notification

Initial Notification Date/Time

Method

Peter Botes - (432) 687-7297

05/06/2004 08:25

STEERS

Person Making Final Report

Final Report Date/Time

Method

Peter Botes - (432) 687-7297

05/06/2004 08:25

STEERS

Incident Primary Contact

Peter Botes, (432) 687-7297

Jurisdiction(s) Notified

REGION 02 - LUBBOCK

Agency Comments

Assigned Staff Member: Gary Shipp