Initial Notification Report	
Existi Sources (commenced prior to 9/17/200 CM 6 0 5 296 49) Applicable Rule: 40 CFR Part Subpart HHHHHH (MACT 6H)- National Emission Lards for Hazardous Air	
Pollutants: Paint Stripping and Miscellaneous Surface Coating Operations at Area Sources	7464
AIR/RN100586353-54644/PA	
1. Print or type the following for each plant in which paint stripping or surface coating operations are performed. (records must be maintained on site)	
Owner/Operator/Title McKenzie Equipment Co. Inc.	
Street Address	
City Houston State Texas Zip Code 77275-2329	
Plant Name McKenzie Equipment Co.	
Plant Phone Number <u>713-946-1413</u>	
Plant Contact/Title PAUL ELrod V.P. Production & Facilities	
Plant Address (If different than owner/operator's)	
Street Address 9260 BRYAnt St. OCT 182	
City Houston State Texas Zip Code 770 75 ENTRAL FILE FILE FILE FILE FILE FILE FILE FIL	MOON
Email Address: <u>Pelrod @ mckenzieair. Com</u> 2. Surface coating operation at the area source (check the appropriate by in period of the control of the contro	
Motor Vehicle and Mobile Equipment Surface Coating FOR R12 FILE ROOM	
Miscellaneous Surface Coating Number of Spray Booths: Number of Preparation Stations: Number of painters usually employed:	
Operation Description:	
Disassemble customer's equipment, estimate repairs,	
Clean and replace, Repair pants as required.	
Reassemble eaupment, test RUN, clean and paint Also touch up new eaupment and packaged skids	
The course hew emphers and pricks year stras	
Use additional pages as needed	
3. Paint Stripping Operation at the area source (check appropriate box and describe the operation):	
Chemical Mechanical Annually plan to use more than 1 ton of MeCl Have developed and am implementing a written MeCl minimization plan	
Operation Description:	
REMOVE RUST, OLD PAIN + (LOOSE), ANY SCALE BUILDUP	
Mechanically with electric wike Brushes, wike brushes,	•
Sanding pads, sand paper	
Use additional pages as needed	

Texas Commission on Environmental Quality

TCEQ Form 20454 rev 04/25/08

RECEIVED

JAN 11 2010

REGION 12

Page 1

RN 100586353

Initial Notification Report Continued Existing Sources (commenced prior to 9/17/2007)

Statement of Compliance for all area source operat	
	mane.
T. Statelification compliance for an area source operat	

The area source at the operation is not yet in compliance with each relevant requirement of the MACT 6H (initial notification must be no later than January 11, 2010 and must submit compliance certification on or before March 11, 2011)

The area source at the operation is in compliance with each relevant requirement of the MACT 6H

Certification of Compliance Status

5. Print or type the name and title of the Responsible Official for the plant:

V.P. Production & Facilities

A Responsible Official can be:

- the president, vice-president, secretary, or treasurer of the company that owns the plant;
- -the owner of the plant
- the plant manager
- a government official if the plant is owned by the Federal, State, City, or County government; or
- A ranking military officer if the plant is located on a military base.

Based on information and belief formed after reasonable inquiry, I certify the information contained in this report to be accurate, complete and true

Hul Elrol 12/28/2009
(Signature of Responsible Official) (Date)

Telephone: 1/3-948-2409 Email: pelrod@nckenzieair.com

Mail form to: **EPA Region 6** Director, Air Pesticides and Toxics 1445 Ross Avenue Suite 1200 Dallas, Texas 75202-2733

Texas Commission on Environmental Quality Air Program Support Section, MC-174 P.O. Box 13087 Austin, TX 78711-3087

Texas Commission on Environmental Quality Regional Office - http://www.tceg.state.tx.us/about/directory/ Look up the appropriate Regional Office closest to where your plant is located.



