



0000-0000-0030-9498

Document Control Sheet

Sheet Title:	AIR CP - SE
Box ID:	9210
Control Sheet ID:	0000-0000-0030-9498
Record Series Name:	OCE / Air Compliance
Record Series:	AIR CP
Primary ID:	109879056
Secondary ID:	
Doc Type:	Reports
Security:	Public
Date:	12/31/2018 12:00AM
Title:	Notification
Tertiary ID	



March 21, 2019

TCEQ Region 14 (Corpus Christi)
Attn: Ms. Kelly Ruble
NRC Bldg., Suite 1200
6300 Ocean Drive, Unit 5839
Corpus Christi, TX 78412-5839

RE: 40 CFR 60, Subpart OOOO - Annual Report
Reporting Period: 1/1/2018 through 12/31/2018
Hilcorp Energy Company
CN600125991

On behalf of Hilcorp Energy Company (Hilcorp), and in accordance with 40 CFR 60.5420, please find enclosed the corresponding report for the affected sources located in Texas within Region 14 for the referenced owner/operator. This report covers the time period of 1/1/2018 through 12/31/2018.


If you have any questions or require additional information, please do not hesitate to contact Nicholas Fitzmorris with HLP Engineering at 337-839-1075. All written correspondence should be directed to: **Hilcorp Energy Company, 1111 Travis Street, Houston, TX 77002, Attn: Brady Dodson.** Thank-you in advance for your assistance with this matter.

Sincerely,
HILCORP ENERGY COMPANY

A handwritten signature in black ink, appearing to read 'Brady Dodson', written over a white background.

Brady Dodson

Enclosures



PO BOX 61229
Houston, TX 77208-1229

1111 Travis Street
Houston, Texas 77002

Phone: 713/209-2400

hilcorp.com

40 CFR 60 - SUBPART OOOO; ANNUAL REPORT

Reporting Period: 1/1/2018 to 12/31/2018

<i>General Information</i>	
Company Name: Hilcorp Energy Company	
<i>Mailing Address</i>	
Street: P.O. Box 61229	
City: Houston	
State: Texas	Zipcode: 77208
<i>Responsible Official</i>	
Name: Matt Vicenik	Title: Environmental Manager
Email: [REDACTED]	Phone: 713-289-2951
<i>Report Preparer</i>	
Name: Nicholas Fitzmorris, P.E.	Title: Project Manager
Email: [REDACTED]	Phone: 337-839-1075
<i>Affected Facilities</i>	<i>Included in this report?</i>
Gas Wells	NO
Reciprocating Compressors	YES
Continuous Bleed Pneumatic Controllers	NO
Storage Vessels	NO

Certification

I hereby certify that, based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete.

Matt Vicenik

 Name of Responsible Official



 Signature of Responsible Official

Environmental Manager

 Title

3-26-19

 Date Signed

40 CFR 60 - SUBPART OOOO; ANNUAL REPORT
(TCEQ Region 14 - Corpus Christi)

Reporting Period: 1/1/2018 to 12/31/2018
 Company Name: Hilcorp Energy Company
 Affected Facility: Reciprocating Compressors

Reciprocating Compressor ID	Location	County	Lat/Long	Date of Last Rod Packing Replacement	Cumulative months since initial startup, since October 15, 2012 OR since last rod packing replacement (whichever is later)	Were there any deviations during this reporting period? (Y/N)	Description of Deviations
14-0365	WT Bell CDP	De Witt		1/25/2018	11	N	Not Applicable
12-0214	West Ranch Site 100	Jackson	28.8031, -96.6147	4/22/2016	32	N	Not Applicable
12-0212	West Ranch Site 400	Jackson	28.8031, -96.6147	4/28/2016	32	N	Not Applicable
12-0215	St. Charles Unit #5	Jackson	28.8031, -96.6147	3/24/2016	33	N	Not Applicable
12-0216	West Ranch Site 600	Jackson	28.8031, -96.6147	*	*	N	Not Applicable
11-0149	Provident City Min.	Lavaca	29.2811, -96.6601	4/11/2018	9	Y ¹	Rod Packing was not changed within 36 months
11-0120	Bruton	Refugio	28.3298, -97.1514	8/15/2018	5	N	Not Applicable
11-0201	Clement Heard 1	Refugio	28.3753, -97.1679	5/16/2018	7	N	Not Applicable
11-0202	Clement Heard 2	Refugio	28.3753, -97.1679	12/19/2018	0	Y ¹	Rod Packing was not changed within 36 months
11-0203	Clement Heard 3	Refugio	28.3753, -97.1679	4/12/2016	33	N	Not Applicable
11-0116	Fannie Heard #20	Refugio	28.3828, -97.1408	5/3/2018	8	N	Not Applicable
11-0117	Fannie Heard #22	Refugio	28.3828, -97.1408	1/8/2016	35	N	Not Applicable
11-0111	Fannie Heard TB4 #9 (91)	Refugio	28.3896, -97.1336	12/27/2018	0	N	Not Applicable
11-0139	Fox Hines #13	Refugio	28.3673, -97.2168	11/5/2018	2	Y ¹	Rod Packing was not changed within 36 months
11-0180	Fox Hines #14	Refugio	28.3474, -97.2169	*	*	N	Not Applicable
11-0200	H&D	Refugio	28.3471, -97.1712	10/31/2017	14	N	Not Applicable
11-0113	Lambert D #17	Refugio	28.3529, -97.1687	11/7/2018	2	Y ¹	Not Applicable
11-0118	TOC A Lease #1	Refugio	28.3575, -97.1499	12/20/2018	0	Y ¹	Rod Packing was not changed within 36 months
11-0119	TOC A Lease #1	Refugio	28.3575, -97.1499	2/25/2016	34	N	Not Applicable
11-0107	TOC C Lease #10	Refugio	28.3723, -97.1581	5/8/2018	8	Y ¹	Rod Packing was not changed within 36 months
11-0114	TOC C Lease #19	Refugio	28.3726, -97.158	9/20/2018	3	Y ¹	Rod Packing was not changed within 36 months
11-0135	WB Fox #12	Refugio	28.3393, -97.2267	2/4/2019	0	Y ¹	Rod Packing was not changed within 36 months
11-0231	Welder	Refugio	28.4916, -97.1676	8/12/2016	29	N	Not Applicable
14-0395	St. Charles CTB No. 1	Jackson	28.2071, -96.9144	7/20/2017	17	N	Not Applicable
14-0401	St. Charles No. 3	Jackson	28.2071, -96.9144	9/18/2017	15	N	Not Applicable
11-0078	West Ranch #1-400 Site Unit 1	Jackson	29.6452, -95.8281	5/12/2016	31	N	Not Applicable

* Unit was released from location.

- Hilcorp is implementing additional tracking in order to avoid similar delays in rod packing replacement in the future.