## Public Water System Sample Collection Analysis Report Public Water System ID # TX1120014

Report to: GAFFORD CHAPEL WSC PO BOX 1160 SULPHUR SPRINGS, TX 75483-1160

## Collection Date 3/24/2020

Water analyses are required by law (30 TAC §290, THSC §341.0315). I acknowledge that the sampling technician has been accompanied during sampling and that the sample has been collected from the correct location indicated on this form. Water systems are responsible for all laboratory fees. Falsification of this form or systems are responsible for all laboratory rees. Falsilication of this form of tampering with water samples is a crime punishable under state and federal law. Refusing to sample, including refusing to sign this form, will result in a monitoring and reporting violation(s), possible enforcement, and fines.

DANTEL ROMANS

WATER SYSTEM REPRESENTATIVE

CHRISTINA NIXON

SAMPLING LOCATION

SAMPLE POINT: TRT-TAP

FACILITY LOCATION: HWY 11 / CR 4724 FACILITY ID: EP002

SAMPLE LOCATION: MT ZION PLANT - STANDPIPE

FREE CHLORINE RESIDUAL: 2.49 mg/L TAP FLUSHING - START: 10:27

TOTAL CHLORINE RESIDUAL: -- mg/L END: 10:49 SAMPLE SAMPLE. ANAT.YSTS

SAMPLE PRIOR COMPLI TD TYPE PRESERVATION PERTOD TYPE TIME 2063044 10:49:30 2 - 40 ML GLASS & FIELD BL ASCORBIC ACID, HC1 PH<2, COOL 4C VOC 1Q2020 LCRA RT N

COMMENTS: LOT DHL 03/04/20 EXP 06/04/20

LAT: N 33.202777

LONG: W -95.83637

pH: 8.6

TEMPERATURE: 66