Air CP_100216720_CP_20161201_Investigation_1377152 Texas Commission on Environmental Quality Investigation Report

The TCEQ is committed to accessibility. If you need assistance in accessing this document, please contact oce@tceq.texas.gov

Customer: DCP Midstream, LP Customer Number: CN601229917

Regulated Entity Name: HUDSON BOOSTER STATION Regulated Entity Number: RN100216720

Investigation # 137	77152	Incident Nu	mbers					
Investigator: TIN	MOTHY DEWBRE	Site Classifie	cation PERMIT BY RULE CASE-BY-CASE MAJOR SOURCE					
Conducted: 12/01	/2016 12/01/2016	NAIC Code: SIC Code:						
· · · · · · · · · · · · · · · · · · ·	R OPERATING PERMITS R NEW SOURCE PERMITS							
Investigation Type:	Compliance Invest File Review	STRATFORD 6.8 MI ON RA	Location: FROM US 287 POPLAR ST & US 54 IN STRATFORD GO 13.8 MI S ON US 287 TURN E & GO 6.8 MI ON RANCH RD 1573 TURN N & GO 0.6 MI ON GRAVEL RD TO BOOSTER STATION ON L					
Additional ID(s):	SJ0021N 40749 73352 2479							
Address: ,		Local Unit: REGION	01 - AMARILLO					
, ,		Activity Type(s):	OG - Oil and Gas - AIR QUALITY Hig Level OPCCFCE - AIR OPCCFCE - OFFICE PERMIT COMPLIANCE CERTIFICATION FOR IN-HOUSE FCE	h				
<u>Principal(s):</u>								
Role	Name							
RESPONDENT	DCP MIDSTREAM	LP						
<u>Contact(s):</u>								
Role	Title	Name	Phone					
REGULATED ENTITY CONTACT	ENVIRONMENTAL SPECIALIST	MICHELLE BROWN	Cell (806) 678-7616 Work (806) 354-3613 Fax (806) 354-3697					
Other Staff Membe	er(s):							
Role	Name		RECEIVED					
QA Reviewer	EDWARD VANCE							
Supervisor	EDWARD VANCE		FEB 07 2017					
			CENTRAL FILE ROOM					

HUDSON BOOSTER STATION - STRATFORD

12/1/2016 Inv. # - 1377152

Page 2 of 4

Associated Check List

<u>Checklist Name</u> AIR ANNUAL COMPLIANCE CERTIFICATION REVIEW - OPCCFCE <u>Unit Name</u> Investigation

Investigation Comments:

INTRODUCTION

On December 1, 2016, an Office Permit Compliance Certification Full Compliance Evaluation (OPCC FCE) was conducted for DCP Midstream LP (DCP), Hudson Booster Station (Hudson). Hudson consists of two separate natural gas processing facilities located at the same site. This facility is a natural gas compression plant, located southeast of Stratford in Sherman County. The facility is located 14 miles south of Stratford on Highway 287, then 7 miles east on FM 1573, then 0.7 mile north on County Road 16. The facility is surrounded by open range and farmland. The terrain is flat. The closest receptor is a residence, located north of this plant. This facility is a major source for one or more criteria pollutants and the units at this facility are affected under Title V (Federal Operating Permit) requirements. Timothy Dewbre, TCEQ Region 1 Air Investigator, conducted this investigation.

This investigation was conducted to verify compliance with permit compliance certification, deviation reporting, and certification by responsible official requirements of 30 TAC Chapter 122, for a site with one or more issued Title V Federal Operating Permit(s). Reportable upset/maintenance records and complaints were reviewed per 30 TAC Chapter 101. Reviews were conducted using TCEQ Region 1 records. No on-site investigation or additional documentation was required to determine compliance. The last Title V investigation of this facility was an OPCC FCE, conducted on January 25, 2016, and covered the reporting period of October 1, 2014 through September 30, 2015.

Daily Narrative

DCP submitted a Site Operating Permit (SOP) application on December 3, 2001. The Site Operating Permit No. 02479 was issued to this facility on May 10, 2004. Previously, the facility had been operating under the provisions of the General Operating Permit (GOP) No. 0433 but this permit was voided on the same date. Following the modification of the NSR permit No. 73352, the company submitted a Title V permit revisions application on January 25, 2010 to incorporate the NSR permit revisions in the Federal Operating Permit. The permit was revised on June 7, 2010. The company submitted a Title V permit renewal application on January 29, 2014, which was completed on October 30, 2014.

A Certificate by Responsible Official (CRO), Permit Compliance Certification (PCC), and a semi-annual deviation report were submitted for the October 1, 2015 through March 31, 2016 period on April 28, 2016 (Attachment 1). This was within 30 days after the end of the certification period as required by 30 TAC 122.146(2). For this compliance period, there was one deviation. Adequate information was included with the deviation report for the investigator to determine the deviations appeared to be non-reportable emissions events resulting from compressor blowdowns. A detailed evaluation of non-reportable emissions events is beyond the scope of this investigation.

A CRO, PCC, and a semi-annual deviation report for the period of April 1, 2016 through September 30, 2016, were received on October 28, 2016 (Attachment 2). This was within 30 days after the end of the certification period as required by 30 TAC 122.146(2). For this compliance period, there was one deviation. Adequate information was included with the deviation report for the investigator to determine the deviations appeared to be non-reportable emissions events resulting from compressor blowdowns. A detailed evaluation of non-reportable emissions events is beyond the scope of this investigation.

After a review of the facility file, I did not find any evidence of any other deviations that the company should have reported.

Exit Interview No exit interview was conducted for this investigation.

GENERAL FACILITY AND PROCESS INFORMATION

Process Description

HUDSON BOOSTER STATION - STRATFORD

12/1/2016 Inv. # - 1377152

Page 3 of 4

Hudson Booster Station is a natural gas compression plant, located in Sherman County. Natural gas from the wells in the surrounding area flows into the booster site at approximately 2 lbs vacuum. The gas passes through an inlet scrubber where the liquid materials are separated from the gas. The gas is compressed by four (4) compressor engines to about 205 psig. The site compresses, on the average, about 15 MMSCFD. The compressed gas is routed to the discharge line and is delivered to Sherman Plant. The compressors at this facility consist of two 2,000 hp Clark (2 stroke, lean burn), one 580 hp Waukesha L7042 (4 stroke rich burn), and one 580 hp Superior 8G825 (4 stroke rich burn) engine. The last two engines were installed in 1999 and are equipped with the A/F ratio controllers. Sweet natural gas is used as the fuel for these engines. Several storage vessels are used for the storage of condensate, lube oil, anti-freeze, and solvent at this facility. A detailed process description is on file at the TCEQ Region 1 Office.

BACKGROUND

Hudson Booster Station currently has a Regulated Entity compliance history classification of High with a compliance history rating of 0.00. DCP Midstream, LP currently has a Customer compliance history classification of satisfactory with a compliance history rating of 3.01 (Attachment 3).

Agreed Orders, Court Orders, and Other Compliance Agreements No violations were issued during this investigation.

Prior Enforcement Issues See Attachment 3.

Complaints

A review of the region files indicates that there has been no air quality complaints filed against this regulated entity in the five years prior to this investigation.

ADDITIONAL INFORMATION

Conclusions and Recommendations: Hudson appears to be operating in compliance with the applicable regulations reviewed during this investigation.

Additional Issues

No additional issues are associated with this investigation.

Attachments

Attachment 1: Certification by Responsible Official, PCC, and Semi-Annual Deviation Report. Attachment 2: Certification by Responsible Official, PCC, and Semi-Annual Deviation Report. Attachment 3: Compliance History Report

No Violations Associated to this Investigation

12/1/2016 Inv. # - 1377152

Page 4 of 4

Signed Environmental Investigator

Signed Supervisor

Date 12-20-2016

Date _12-20-16

Attachments: (in order of final report submittal)

___Enforcement Action Request (EAR)

____Letter to Facility (specify type) : _____

Investigation Report

____Sample Analysis Results

<u>____Notice of Registration</u>

____Maps, Plans, Sketches

____Photographs

____Correspondence from the facility

 χ Other (specify) :

Measy Ser Attachments

TCEQ Attachment 1



Certification by Responsible Official, PCC, and Semi-Annual Deviation Report

Hudson Booster Station RN100216720

DCP Midstream LP CN601229917

November 30, 2016 Timothy Dewbre



DCP Midstream 9101 HWY 136 Borger, TX 79007

si)

April 28, 2016

Texas Commission on Environmental Quality Attn: Eddie Vance, Region 1 Air Section Manager 3918 Canyon Drive Amarillo, TX 79109-4933

Re: Title V Permit Annual Compliance Certification and Semi-Annual Deviation Report

Dear Mr. Vance:

Enclosed, please find the appropriate compliance certification and semi-annual deviation report for the following facility:

TCEQ ID No.	Facility Name	County	Title V Permit No.
SJ-0021-N	Hudson Booster	Sherman	O2479

This certification and deviation report (TCEQ Form PPC and OP-CR01, and deviation report) are being submitted pursuant to 30 TAC §122.146.

Should there be any questions regarding this submittal, please contact me at (806) 354-3651.

Sincerely, DCP Midstream, LP

Steve Kuhn Environmental Specialist

Enclosures

cc. EPA Region VI Attn: Administrator Region VI Title V Certifications 1445 Ross Avenue Suite 1200 Dallas, TX 75202





Form OP-CRO1 Certification by Responsible Official Federal Operating Permit Program

All initial permit application, revision, renewal, and reopening submittals requiring certification must be addressed using this form. Updates to site operating permit (SOP) and temporary operating permit (TOP) applications, other than public notice verification materials, must be certified prior to authorization of public notice or start of public announcement. Updates to general operating permit (GOP) applications must be certified prior to receiving an authorization to operate under a GOP.

I. IDENTIFYING INFORMATIO	<u></u>	าม ระวะว่า มาการรับการรับการทั้งการระ	
	• •••••••••••••	KO100015	
A. RN: RN100216720	B. CN: CN		C. Account No.: SJ-0021-N
D. Permit No.: O2479 F. Area Name: Hudson Booster		E. Project No.:	
G. Company Name: DCP Midstream	. I P		
II. CERTIFICATION TYPE (Plea		ppropriate box)	
A. Responsible Official:		B. 🛛 Duly Author	rized Representative:
III. SUBMITTAL, TYPE (Place an	"X" in the app	propriate box) (Only one r	response can be accepted per form)
SOP/TOP Initial Permit Applicati	on	Update to Permit App	plication
GOP Initial Permit Application		Permit Revision, Ren	newal, or Reopening
Other: Compliance Certification			
IV. CERTIFICATION OF TRUTH	Ē		
This certification does not extend to	information v	which is designated by th	he TCEQ as information for reference only.
I, <u>Ronnie Trammell</u> (Certifier Name printed or typ	ved)	, certify that I	am the <u>DAR</u> for this application (RO or DAR)
and that, based on information and b period in Section IV.A below, or on th			the statements and information dated during the time, are true, accurate, and complete:
Note: Enter EITHER a Time Period C not valid without documentation date(ute(s) for each certification	on. This section must be completed. The certification i
A. Time Period: From	to		
A. Time Period: From	e*	End Date*	
B. Specific Dates: <u>4-28-16</u>			
	e used when t		e 5* Date 6* Date 7* Date 8* 'Update to Permit Application' and there are multiple the documentation. Do not use the Time Period option
Signature: R.h. Juan			Signature Date: April 28, 2016
Title: <u>General Manager of Operat</u>	ions		

Texas Commission on Environmental Quality Federal Operating Permit Form Permit Compliance Certification - PCC (Part 1)

Perr	nit Holder Name	DCP Midstream, LP	Customer Number	CN601229917
Area	a Name	Hudson Booster	Account Number	SJ0021N
Оре	rating Permit Number	O2479	Report Submittal Date	04/28/2016
Cert	ification Period Start Date	10/01/2015	End Date	03/31/2016
1.	(Indicate response by placing	ompliance with Permit Terms and Conditions a 'x' in the appropriate column for each of the following question nose permit terms and conditions identified in the 'Summary of Devia		Response:
	minimum, but not limited to, the reporting, or testing required by t	continuous or intermittent compliance method data from monitoring, the permit and any other credible evidence or information, was the p ne terms and conditions of the permit over the Certification Period?	recordkeeping.	X Yes No
II.	Summary of Deviations			Response:
	(Indicate response by placing	a 'x' in the appropriate column for each of the following questio	ons)	
A.	Were there any deviations from a to the agency? If the answer to the agency?	any permit requirements during the Certification Period that have pre this question is `Yes`, please complete Part 2, and attach Part 2 to th	eviously been reported his page.	
1				
	and the total	ubmitted reports did not contain specific information on monitoring number of deviations experienced over the entire certification pe vide that information.	methods, frequency riod, then use form	Yes X No

/RP

Texas Commission on Environmental Quality Federal Operating Permit Deviation Report Form Form Dev Rep (Part 1)

/RP

.

Pern	nit Holder	Name		DCP Midstre	eam, LP				Cus	stomer N	lumber CN60122	9917
Area	Name			Hudson Bo	oster					ount Nu -XXXX-X		
	ort Period t Date	10/01/	2015		ort Perio Date	od ₀₃	3/31/2016 Operating Number	Permit _{O2479}			Report Submittal Date	04/28/2016
				· ·	Operat	ting Perm	it Requirement for Which	n Deviations are E	Being Report	ted		
		Number		Term and Condition No.		Pollutant	Regulatory Requirement Citation	Type of Requirement	SOP or G Index Number		Monitoring Method	Monitoring Frequency
	ID See Be			See Below		See Below	Can Dalaur	Car Dalar				
	T	· · · · · · · · · · · · · · · · · · ·	Deviatio	on Period		No.	See Below See Below Cause of		NA		See Below Corrective Action Taken to	See Below
	Incident	Sta	and the second sec	End		of Dev	Deviation				Deviation Sit	uation
_	No.	Date	Time	Date	Time							
1		10/01/2015 00:00:00 03/31/2016 00:00:00 1 See attached compressor blowdown event docut compliance with TCEQ 30 TAC 101.201 & 101.2 non-reportable, recordable upsets that occurred 2015 through March 31, 2016. [30 TAC 101.201 ENV ENV/FIN: PROC1 VENT/Engine Compressors, Five of Requirement: Record					2 101.201 & 101.211. ets that occurred from [30 TAC 101.201 & 7 ne Compressors, Polli	 These are documentation for compliance with TCEQ 30 TAC m October 1, 101.201 & 101.211. These are non-reportable, recordable upsets that occurred from October 1, 20 				
				Total D	eviations		Is there a Part 2 Miscellaneous supporting this deviation?	Monitoring/Credible	Evidence form	Y4	es X No	

Texas Commission on Environmental Quality Federal Operating Permit Form Permit Compliance Certification - PCC (Part 2)

/RP

Permit Holder	Name	DCP Midstream, LP	Custome	r Number	CN601229917	
Area Name	<u> </u>	Hudson Booster	Account	Number	SJ0021N	
Operating Per	mit Number	O2479	Report S	ubmittal Date	04/28/2016	
Certification P	eriod Start Date	10/01/2015	End Date		03/31/2016	
		Identification of Deviation Reports Submitted During (Note: All reports must be certified to truth, accuracy, and comple)	
Report Date	(Name	Report Description of unit, Name of Rule, Dríver for report, etc)		Report Submitted To		Report Previously Certified?
04/28/2016	See attached compress These are non-reportat No: 1)	sor blowdown event documentation for compliance with TCEQ 30 TAC 101.2 ole, recordable upsets that occurred from October 1, 2015 through March 31.	01 & 101.211. 2016. (Event	TCEQ Region 1		Yes X No

Process An EPN: RN1002167	Process Blowdown Vent (V-1)	Hudson Bo	oster SJ-0021-N	-		de Midstre	D am			Month: October - March Year; 2015-2016	
Compressor	Blowdown Events - Documentation for Compliance with	TCEQ 30 TAC 10	01.201 & 101.	211 , 30 TA	C §106.352 Table 8 an	d 30 TAC §106.	359 (c) (2)	(E)		Lat: 36.1492 Long: -101.9012	
Event Date	TCEQ Facility ID No.	Vent Start (15:00)	Vent End (15:20)		<u>Vent Type</u> Startup/Shutdown Maintenance Upset	No. of Blowdowns per Event	Total Pounds VOC Vented	Total Pounds H2S Vented	Cause for Release	Corrective Actions to Minimize Emissions	Operator Initials
10/13/15	ENG-2 Clark	15:00	15:01	1	Upset	1	80.1	0.07	Suction pressure too high as a result of 3rd party power failure	Power Restored	zc
11/17/15	ENG-2 Clark	14:00	14:01	1	Upset	1	80.1	0.07	Suction pressure too high as a result of 3rd party power failure	Power Restored	zc
2/8/16	ENG-2 Clark	8:00	8:01	1	Upset	1	80.1	0.07	3rd Party Power Failure	Power Restored	zc
2/23/16	ENG-2 Clark	3:30	3:31	1	Upset	1	80.1	0.07	3rd Party Power Failure	Power Restored	zc
								0.07		Power Restored	ZC
					·····						
			<u> </u>			· · · ·					
	-		l		ļ						
		·	<u> </u>					i			+
				L							
											+
											+
	Part - Patrice						-		· · · · · · · · · · · · · · · · · · ·		
		-							· · · · · · · · · · · · · · · · · · ·		+
	······										
						<u> </u>					
		_								-	
											1
											-
	······································										+
									· · · · · · · · · · · · · · · · · · ·		+
					·						
											+
											+
_											





Certification by Responsible Official, PCC, and Semi-Annual Deviation Report

Hudson Booster Station RN100216720

DCP Midstream LP CN601229917

November 30, 2016 Timothy Dewbre





DCP Midstream 9101 HWY 136 Borger, TX 79007

October 27, 2016

Texas Commission on Environmental Quality Attn: Eddie Vance, Region 1 Air Section Manager 3918 Canyon Drive Amarillo, TX 79109-4933

Re: Title V Permit Annual Compliance Certification and Semi-Annual Deviation Report

Dear Mr. Vance:

Enclosed, please find the appropriate compliance certification and semi-annual deviation report for the following facility:

TCEQ ID No.	Facility Name	County	Title V Permit No.
SJ-0021-N	Hudson Booster	Sherman	O2479

This certification and deviation report (TCEQ Form PPC and OP-CR01, and deviation report) are being submitted pursuant to 30 TAC §122.146.

Should there be any questions regarding this submittal, please contact me at (806) 354-3651.

Sincerely, DCP Midstream, LP

Steve Kuhn Environmental Specialist

Enclosures

cc. EPA Region VI Attn: Administrator Region VI Title V Certifications 1445 Ross Avenue Suite 1200 Dallas, TX 75202





Form OP-CRO1 Certification by Responsible Official Federal Operating Permit Program

All initial permit application, revision, renewal, and reopening submittals requiring certification must be addressed using this form. Updates to site operating permit (SOP) and temporary operating permit (TOP) applications, other than public notice verification materials, must be certified prior to authorization of public notice or start of public announcement. Updates to general operating permit (GOP) applications must be certified prior to receiving an authorization to operate under a GOP.

I.	IDENTIFYING INFORMATIO	ON					
A.	RN: RN100216720	В.	CN:	CN60	1229917	C. Account No.: SJ-)021-N
D.	Permit No.: O2479				E. Project No.:		
F.	Area Name: Hudson Booster			_			
G.	Company Name: DCP Midstream	n, LP	•				
п.	CERTIFICATION TYPE (Plea	ase n	ark t	he appr	opriate box)		
А.	Responsible Official:				B. 🛛 Duly Authori	zed Representative:	
ш	. SUBMITTAL TYPE (Place an	"X"	in the	e appro	priate box) (Only one re	esponse can be accepted	per form)
	SOP/TOP Initial Permit Applicati	on			Update to Permit App	lication	
	GOP Initial Permit Application				Permit Revision, Rene	ewal, or Reopening	
\boxtimes	Other: Compliance Certification						
IV.	CERTIFICATION OF TRUTH	H					
Th	is certification does not extend to	info	rmati	ion whi	ch is designated by the	e TCEQ as information	for reference only.
I.	Ronnie Trammell				, certify that I a	m the DAR	for this application
/	(Certifier Name printed or typ	ped)				m the <u>DAR</u> (RO or DAR)	
	that, based on information and b tiod in Section IV.A below, or on th						
	te: Enter EITHER a Time Period (valid without documentation date(pecifi	c Date((s) for each certification	n. This section must be c	ompleted. The certification is
A. OR	Time Period: From	e*		_ to	End Date*		
Ti und	Specific Dates: <u>10-27-16</u> Date 1 Date he Time Period option may only b certified submittals; or a submittal he "Submittal Type" is 'Other.'	oe us	ed wh			Update to Permit Applic	
Sig	mature: R.D. Jum	u	<			_Signature Date:	October 27, 2016
Tit	le: <u>General Manager of Operat</u>	ions					

Texas Commission on Environmental Quality Federal Operating Permit Form Permit Compliance Certification - PCC (Part 1)

RN100216720

Permit Holder Name	DCP Midstream, LP	Customer Number	CN601229917						
Area Name	Hudson Booster	Account Number	SJ0021N						
Operating Permit Number	O2479	Report Submittal Date	10/27/2016						
Certification Period Start Date	ation Period Start Date 04/01/2016 End Date								
(Indicate response by placing a With the possible exception of the minimum, but not limited to, the c reporting, or testing required by th	Certification of Continuous Compliance with Permit Terms and Conditions (Indicate response by placing a 'x' in the appropriate column for each of the following questions) With the possible exception of those permit terms and conditions identified in the 'Summary of Deviations' found using, at a minimum, but not limited to, the continuous or intermittent compliance method data from monitoring, recordkeeping, reporting, or testing required by the permit and any other credible evidence or information, was the permit holder in continuous compliance with all the terms and conditions of the permit over the Certification Period?								
II. Summary of Deviations (Indicate response by placing a	a 'x' in the appropriate column for each of the following questions)		Response:						
	iny permit requirements during the Certification Period that have previous his question is `Yes`, please complete Part 2, and attach Part 2 to this pa								
and the total r	Important Note: If Previously submitted reports did not contain specific information on monitoring methods, frequency and the total number of deviations experienced over the entire certification period, then use form DevRep to provide that information.								
B. Were there any deviations from a submitted to the agency? If the a	Were there any deviations from any terms or conditions of the permit during the Certification Period that are currently being submitted to the agency? If the answer to this question is `Yes`, please include the relevant reports along with this page.								

/RP -

., •

Texas Commission on Environmental Quality Federal Operating Permit Deviation Report Form Form Dev Rep (Part 1)

AIR CO/ RN100216720

/RP • . ---

													_			
Perm	it Holder	Name			DCP Midstr	eam, LP						Cı	Istomer N	umber	CN60122	9917
Area	Name				Hudson Bo	ooster							count Number (-XXXX-XX) SJ00		D21N	
Repo Start	rt Period Date	04	4/01/2016	6		port Period d Date							Report S Date	Submittal	10/27/2016	
						Operatir	ng Pern	nit Requirement	for Which	Deviatio	ons are E	Being Repo	rted			
	ID	Number			Term and Condition No		ollutant			SOP or 0 Index Numb	c	Monitori Metho		Monitoring Frequency		
	D See Be						<u>-</u>									·
	DID GRP				See Below	Se	e Below	See Be			Below	NA	<u></u>	See Bel		See Below
Dev Item	m				<u></u>	No. of	Cause of Deviation								ken to Remedy or Mitigate on Situation	
No.	Incident No.															
1		Date			Date	Time		See attached comp								
J		04/01/2016 00:00:00 09/30/2016 00:00:00 1 See attached compressor blowdown event documental compliance with TCEQ 30 TAC 101.201 & 101.211. T non-reportable, recordable upsets that occurred from A through September 30, 2016. [30 TAC 101.201 & 101 EPN/FIN: PROC1 VENT/Engine Compressors, Polluta VOC/H2S, Type of Requirement: Record						. These are m April 1, 2016 101.2111.	docume 6 101.201 recordat	& 101.211.	mpliance wi These are r at occurred t	th TCEQ 30 TAC ion-reportable, from April 1, 2016				
					Total	Deviations:	1	Is there a Part 2 Mis supporting this devi	scellaneous ation?	Monitorin	g/Credible	Evidence form	T Ye	s X No		

Texas Commission on Environmental Quality Federal Operating Permit Form Permit Compliance Certification - PCC (Part 2)

AIR CO/ RN100216720

- RP/،

Permit Holder Name	DCP Midstream, LP	Customer Number	CN601229917
Area Name	Hudson Booster	Account Number	SJ0021N
Operating Permit Number	O2479	Report Submittal Date	10/27/2016
Certification Period Start Date	04/01/2016	End Date	09/30/2016

Identification of Deviation Reports Submitted During the Certification Period (Note: All reports must be certified to truth, accuracy, and completeness by the Responsible Official)						
Report Date	Report Description (Name of unit, Name of Rule, Driver for report, etc)	Report Submitted To	Report Previously Certified?			
10/27/2016	See attached compressor blowdown event documentation for compliance with TCEQ 30 TAC 101.201 & 101.211. These are non-reportable, recordable upsets that occurred from April 1, 2016 through September 30, 2016. (Event No: 1)	TCEQ Region 1	Yes X No			

Process Area Name - EPN: Process Blowdown Vent (V-1) RN100216720 Compressor Blowdown Events - Documentation for Compliance with TC		SU-VOL 1-14				dep Midstréam				Morith: April - Septamber Year: 2016 Lat: 36.1492	
Compresso	or Blowdown Events - Documentation for Compliance with TCI	EQ 30 TAC 10	1.201 & 101.	211 , 30 TA	C §106.352 Table 8 an	d 30 TAC §106.	359 (c) (2)	(E)		Long: -101.9012	-
Event Date	or Blowdown Events - Documentation for Compliance with TCI	Vent Start (15:00)	Vent End (15:20)	Duration (mins.)	Vent Type Startup/Shutdown Maintenance Upset	No. of Blowdowns per Event	Total Pounds VOC Vented	Total Pounds H2S Vented	Cause for Release	Corrective Actions to Minimize Emissions	Operator Initials
		10:00				1	80.1	0.07			
7/27/16	ENG-2 Clark	10:00	10:01	1	Upset	1	80.1	0.07	broken gas pocket	replaced gas pocket	ZC
	· · · · · · · · · · · · · · · · · · ·							<u> </u>	· · · · · · · · · · · · · · · · · · ·		+
		<u> </u>					<u> </u>				<u> </u>
		L									+
										· · · · · · · · · · · · · · · · · · ·	<u> </u>
								_			
			· · · · · ·								
											-
		<u> </u>									+
				<u> </u>							+
											+
		-					<u> </u>				+
							·		· · ·	· · ·	
	· · · · · · · · · · · · · · · · · · ·										
											+
			-							· · · · · · · · · · · · · · · · · · ·	
											+
				_							
											-
		1									
							<u> </u>				1
		<u> </u>								······································	+
		<u>+</u>		<u> </u>			<u> </u>		· · · · ·		+
\vdash	h	1									+
								· · ·			
			 								

- -

TCEQ Attachment 3

.



Compliance History Report

Hudson Booster Station RN100216720

DCP Midstream LP CN601229917

November 30, 2016 Timothy Dewbre The TCEQ is committed to accessibility. To request a more accessible version of this report, please contact the TCEQ Help Desk at (512) 239-4357.



Item 4

Item 5

Compliance History Report

Compliance History Report for CN601229917, RN100216720, Rating Year 2016 which includes Compliance History (CH) components from September 1, 2011, through August 31, 2016.

or Owner/Operat		7, DCP Midstream, LP	Classification: SATISFACT	ORY Rating	3.01
Regulated Entity	RN10021672	0, HUDSON BOOSTER	Classification: HIGH	Rating	: 0.00
Complexity Point	s: 6		Repeat Violator: NO		
CH Group:	03 - Oil and O	Gas Extraction		, , <u>, </u>	
Location:	FROM US 287 RANCH RD 15 SHERMAN CO	573 TURN N & GO 0.6 MI	STRATFORD GO 13.8 MI S ON US 28 ON GRAVEL RD TO BOOSTER STATI	37 TURN E & GO 6.3 ON ON L SHERMAN	8 MI ON I, TX,
TCEQ Region:	REGION 01 -	AMARILLO	· · · · · · · · · · · · · · · · · · ·		
AIR NEW SOURCE AIR NEW SOURCE AIR NEW SOURCE	ERMITS ACCOUNT NUM PERMITS REGISTRATIO PERMITS PERMIT 7335 PERMITS REGISTRATIO VENTORY ACCOUNT N	DN 40749 A 52 A DN 133535 A	IR OPERATING PERMITS PERMIT 2 IR NEW SOURCE PERMITS ACCOU IR NEW SOURCE PERMITS REGIST IR NEW SOURCE PERMITS AFS NU	NT NUMBER SJ002 RATION 117937	1N
Compliance Histo	ry Period: Septemb	er 01, 2011 to August 3:	1, 2016 Rating Year: 2016	Rating Date:	09/01/2016
Date Compliance	History Report Pre	pared: November 30			
			·		
Agency Decision	Requiring Complian	nce History: Enforce		<u>.</u>	
- · · · ·					
Component Perio	d Selected: Septer	mber 01, 2011 to Augus	31, 2016		
-			31, 2016 on Regarding This Compliance	e History.	
-	er to Contact for A			-	
TCEQ Staff Memb	er to Contact for A Staff Member	dditional Informatio	on Regarding This Compliance	-	
TCEQ Staff Memb	er to Contact for A	dditional Informatio	on Regarding This Compliance	-	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i	er to Contact for A Staff Member /Operator Histor n existence and/or oper	dditional Information	Phone: (512) 239-1 ar compliance period?	-	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i	er to Contact for A Staff Member /Operator Histor n existence and/or oper	dditional Information	on Regarding This Compliance Phone: (512) 239-1	000	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne	dditional Information Y: ration for the full five year ership/operator of the sit	Phone: (512) 239-1 Phone: (512) 239-1 ar compliance period? e during the compliance period?	000 YES	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne	dditional Information	Phone: (512) 239-1 Phone: (512) 239-1 ar compliance period? e during the compliance period?	000 YES	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (Components (M	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th	dditional Information Y: ration for the full five year ership/operator of the sit	Phone: (512) 239-1 Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A – J	000 YES	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (Components (M A. Final Orders, N/A	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th court judgments, a	dditional Information Y: ration for the full five yea ership/operator of the sit e Site Are Listed i	Phone: (512) 239-1 Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A – J	000 YES	
Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (Components (M A. Final Orders, 6 N/A B. Criminal conv N/A	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th court judgments, a	dditional Information Y: ration for the full five year ership/operator of the sit <u>e Site Are Listed i</u> and consent decrees	Phone: (512) 239-1 Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A – J	000 YES	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (Components (M A. Final Orders, N/A B. Criminal conv N/A C. Chronic exces N/A	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th court judgments, a ictions: sive emissions eve	dditional Information Y: ration for the full five year ership/operator of the sit <u>e Site Are Listed i</u> and consent decrees	on Regarding This Compliance Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A - J :	000 YES	
TCEQ Staff Memb Name: TCEQ S Site and Owner 1) Has the site been i 2) Has there been a (Components (M A. Final Orders, f N/A B. Criminal conv N/A C. Chronic exces N/A D. The approval Item 1 Ju	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th court judgments, a ictions: sive emissions even dates of investigat ily 30, 2012	dditional Information Y: ration for the full five yea ership/operator of the site e Site Are Listed in and consent decrees ents: ions (CCEDS Inv. Tr (1020940)	on Regarding This Compliance Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A - J :	000 YES	
 TCEQ Staff Membric Name: TCEQ Staff M	er to Contact for A Staff Member /Operator Histor n existence and/or oper known) change in owne ultimedia) for th court judgments, a ictions: sive emissions eve dates of investigat	dditional Information Y: ration for the full five yea ership/operator of the sit <u>e Site Are Listed i</u> and consent decrees ents: ions (CCEDS Inv. Tr	on Regarding This Compliance Phone: (512) 239-1 ar compliance period? e during the compliance period? n Sections A - J :	000 YES	

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

(1222338)

(1306928)

January 28, 2015

January 26, 2016

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred.

- F. Environmental audits:
- G. Type of environmental management systems (EMSs): N/A
- H. Voluntary on-site compliance assessment dates: $_{\mbox{N/A}}$
- I. Participation in a voluntary pollution reduction program: N/A
- J. Early compliance: N/A

Sites Outside of Texas:

N/A