

# Texas Commission on Environmental Quality Investigation Report

TISEO PAVING CO  
CN600426225

## TISEO PAVING CONCRETE BATCH PLANT 2 RN100786524

Investigation # 828765

Incident #

Investigator: KARA ALLEN

Site Classification

MIN 0-15 FINS

PORTABLE ACCOUNT

Conducted: 05/25/2010 -- 06/02/2010

SIC Code: 3531

NAIC Code: 327320

Program(s): AIR NEW SOURCE  
PERMITS

Investigation Type : Site Assessment

Location : NORTHSIDE OF MONTE CARLO  
(FM 1377) APPROXIMATELY 2200 FEET  
WEST OF FM 75 IN PRINCETON TEXAS

Additional ID(s) : 949655G

Address: ; ,

Activity Type : REGION 04 - DFW METROPLEX  
POSICH116 - Chapter 116 Portable Permit Site Review &  
RelocationPrincipal(s) :

Role	Name
RESPONDENT	TISEO PAVING CO

Contact(s) :

Role	Title	Name	Phone
Regulated Entity Contact	SECRETARY / TREASURER	LOUIS TISEO	Work (972) 289-0723 Fax (972) 216-5637

Other Staff Member(s) :

Role	Name
Supervisor	EJAZ BAIG
Investigator	ARIEL YEHL

**Associated Check List**Checklist NameAIR PERMIT SITE REVIEW  
AIR PERMIT SITE REVIEWUnit NameCBP Monte Carlo Project  
CBP CorinthInvestigation Comments :

LOCATION

Site#1

Monte Carlo Project

North side of Monte Carlo (Farm to Market Road (FM) 13770, approximately 2200 feet west of FM  
75 in Princeton, Collin County.

Site #2

**RECEIVED**  
JUL 19 2010  
TCEQ  
CENTRAL FILE ROOM

Southeast corner of the intersection of Dobbs and Quail Run in Corinth, Denton County.

#### INTRODUCTION

This Site Assessment Investigation was conducted by the writer, Ms. Kara Allen of the Texas Commission on Environmental Quality (TCEQ) DFW Region Office Air Section, accompanied by Mr. Ejaz Baig, P.E., and Ms. Ariel Yeh both with the TCEQ DFW Region Air Section for Tiseo Paving Company (Tiseo). The TCEQ DFW Regional Office received two portable relocation requests from Tiseo on 5/7/10. The applications concerned the relocation of a Concrete Batch Plant (CBP) to the above referenced locations. The relocations would be authorized under Air Quality Standard Permit for CBP.

#### Daily Narrative

On 5/25/10, the writer accompanied by Mr. Baig and Ms. Yeh conducted a site review of the proposed location for Site#1. It was noted that the distance from the proposed location to the nearest property line was approximately 100 feet. The distance from the location to the nearest off-property receptor (residence) was approximately 2500 feet, as represented. It appeared that the site can meet all applicable distance limits required by Air Quality Standard Permit for CBP.

On 6/2/10, the writer accompanied by Ms. Yeh conducted a site review of the proposed location for Site #2. It was noted that the distance from the proposed location to the nearest property line was approximately 100 feet. The distance from the location to the nearest off-property receptor (residence) was approximately 300 feet, as represented. It appeared that the site can meet all applicable distance limits required by Air Quality Standard Permit for CBP.

#### Exit Interview

An exit interview was not conducted since there was no contact with the regulated entity. A Customer Satisfaction Survey was not provided.

#### GENERAL FACILITY AND PROCESS INFORMATION

##### Process Description

Tiseo CBP 2 is a portable CBP. Washed raw aggregate materials are hauled to site via covered trucks. Aggregates are loaded into aggregate bins using a front-end loader. Cement and fly ash are pumped to the pigs from the delivery trucks using a closed air hose pumping system. Cement is moved via an air hose from the pig to the cement silo. Fly ash is moved from the pig to a fly ash silo via an air hose. Aggregate bins and silos feed to a discharge point. Emissions for the aggregates, cement and fly ash are handled by the central dust collection system.

#### BACKGROUND

Tiseo CBP 2 has a compliance history rating at 3.01 and a performance classification designated as Average By Default. Tiseo has a compliance history rating at 2.94 and a performance classification designated as Average.

#### Current Enforcement Actions

No violations were noted during this investigation.

#### Agreed Orders, Court Orders, and Other Compliance Agreements

None in the last five years.

#### Prior Enforcement Issues

None in the last five years

#### Complaints



No complaints are on file for the last five years.

ADDITIONAL INFORMATION:

Conclusions and Recommendations

Recommend approval as represented. An authorization letter was sent to Tiseo for Site#1 on 6/1/10 and Site#2 on 6/2/10.

Additional Issues

None noted during this investigation.

**No Violations Associated to this Investigation.**

Signed *Kam Allen*  
Environmental Investigator

Date 7/13/10

Signed *[Signature]*  
Supervisor

Date 07-14-10

**Attachments: (in order of final report submittal)**

- Enforcement Action Request (EAR)
- Letter to Facility (specify type) : \_\_\_\_\_
- Investigation Report
- Sample Analysis Results
- Manifests
- NOR

- Maps, Plans, Sketches
- Photographs
- Correspondence from the facility
- Other (specify) : \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_