

WM MR_Rio Grande_RP_20211027_Monthly Report-athatche
Texas Commission on Environmental Quality
Investigation Report

The TCEQ is committed to accessibility. If you need assistance in accessing this document, please contact oce@tceq.texas.gov

Customer: RGWM-Insp-River-North Floodway-South Levee
Customer Number: CN603837030

**Regulated Entity Name: RGWM-INSP-LOWER REACH III- ANZALDUAS
DAM- PROGRESO BRIDGE**

Regulated Entity Number: RN106122468

Investigation # 1770918

Investigator: ARACELI THATCHER

Conducted: 10/01/2021 -- 10/26/2021

Program(s): WATER RIGHTS

Investigation Type: Compliance Investigation

Incident Numbers

Site Classification CERTIFICATE OF
ADJUDICATION

No Industry Code Assigned

Location:

RN102633302,RN102861937,RN102861937,RN102740
781,RN102817822,
RN101498707,RN103189393,RN101472363,RN101471
837,RN102640141,
RN104505391,RN102627312,RN102861838,RN102789
415,RN102886280,
RN103133187,RN104349428,RN102720331

Additional ID(s):

Address: ,
, ,

Local Unit: REGION 16 - LAREDO

Activity Type(s): WMDIVER - WM Diversion Site
Investigation

Principal(s):

Role

Name

RESPONDENT
RESPONDENT

RGWM-INSP-RIVER-NORTH FLOODWAY-SOUTH LEVE
RRGWM GWM INSP LOWER REACH III ANZALDUAS DA

Contact(s):

Role

Title

Name

Phone

Other Staff Member(s):

Role

Name

QA Reviewer
QA Reviewer

ANTHONY STAMBAUGH
GEORGINA BERMEA

Associated Check List

Checklist Name

RIO GRANDE WATERMASTER INSPECTION
CHECKLIST

Unit Name

RGWM-CHK

Investigation Comments:

INVESTIGATION NUMBER CCEDS Inv #1770918

INTRODUCTION

Watermaster Specialist, Araceli Thatcher, of the Texas Commission on Environmental Quality (TCEQ), Rio Grande Watermaster Program, conducted surveillance and monitoring along the Rio Grande River and its tributaries to include several water right holders /diverters within the following reaches along the Rio Grande. These field investigations were conducted during the period of October 01 through October 26, 2021; and included water right holders /diverters within the following reaches of the Rio Grande.

Middle Rio Grande Reach's (MR) have been broken down as follows:

MR I between Amistad Dam and Del Rio International Bridge - RN106122690

MR II between Del Rio Int'l Bridge and the Eagle Pass Int'l Bridge - RN106122716

MR III between the Eagle Pass Int'l Bridge and San Antonio Crossing - RN106122724

MR IV between the San Antonio Crossing (Xing) and Laredo Int'l Bridge - RN106122732

MR V between the Laredo International Bridge and San Ygnacio - RN106122740

MR VI between the San Ygnacio to Falcon Dam - RN106122757

Middle Rio Grande Tributaries (MT) have been broken down as follows:

MT - Cienegas and San Felipe creeks - RN106122765

MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado, and Rosita creeks - RN106122807

MT - San Ambrosia, Manadas, Lake Casa Blanca, Becerro, Napalosa and Javalina creeks - RN106123060

GENERAL ENTITY AND PROCESS INFORMATION

The following entities referred to in this investigation were surveyed and/or monitored during the surveillance inspections. The standard industrial classification (SIC) codes of, 721 for crop planting, cultivating and or protecting, 1381 for oil and gas exploration activities, and or 4941 for water supply entities. A detailed description of each regulated entity with their associated water right account information can be found in the TCEQ Rio Grande Watermaster files, including specific SIC codes and associated water right information.

Water right accounts and or diverters in the following reaches include:

MR I-Amistad Dam to Del Rio Bridge,

MR II-Del Rio Bridge to Eagle Pass Bridge,

MR III-Eagle Pass Bridge to San Antonio Crossing,

MR IV-San Antonio Crossing and the Laredo Bridge,

MR V-Laredo Bridge to San Ygnacio, MR V- Laredo Bridge to San Ygnacio,

MR VI- San Ygnacio to Falcon Dam,

MT - Cienegas and San Felipe creeks,

MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado and Rosita creeks,

MT - San Ambrosia, Manadas, Becerra, Napalosa and Javalina creeks

BACKGROUND

The TCEQ Rio Grande Watermaster Program routinely conducts inspections along the Rio Grande River and or its Tributaries to ensure compliance with the applicable State and Watermaster rules and regulations related to diversion and use of State waters.

ADDITIONAL INFORMATION:

During the course of these investigations, the Watermaster Specialist performed watermaster-related activities that may have included but were not limited to the following:

462 Inspections

16 Measurements

0 On-Site Notices

3 Doppler Checks

Please refer to the attached investigation notes (Attachment A: Deputy's Daily Report) for the specific observations of these investigation sites.

No Violations Associated to this Investigation

Signed

Araceli Thatcher

Date 10/29/2021

Environmental Investigator

Signed



Date 10/29/2021

Supervisor

Attachments: (in order of final report submittal)

☐ Enforcement Action Request (EAR)

☐ Maps, Plans, Sketches

☐ Letter to Facility (specify type) : _____

☐ Photographs

☐ Investigation Report

☐ Correspondence from the facility

☐ Sample Analysis Results

☒ Other (specify) :

☐ Manifests

Attachment A

☐ Notice of Registration

**TEXAS COMMISSION ON ENVIRONMENTAL
QUALITY**



ATTACHMENT A

Regulated Entity No.	RN106122690 RN106122716 RN106122724 RN106122732 RN106122740 RN106122757	Regulated Entity	Lower Reaches I, II, III, IV, V, VI	County Name WEBB Zapata	WEBB AND ZAPATA
Investigation Date	10/01/2021 – 10/26/2021	TCEQ Investigator(s):	Araceli Thatcher		

Deputy Daily Report

10/01/21, 10/04/21, 10/05/21, 10/06/21, 10/11/21, 10/12/21, 10/13/2021, 10/14/21,
10/18/21, 10/19/21, 10/20/21, 10/21/21, 10/25/21, 10/26/21



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/01/2021	Inspections:	35
Time Start:	09:00	Measurement:	1
Time End:	16:50	Doppler:	0
Inspec Time:	6.0	On-Site Notice:	0
RN#:	106122740	Travel Time:	1.5

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:25	2743-000	Sheila Slaughter Glassord	6M4-23							✓			
09:25	2743-001	David M Slaughter Jr	6M4-23							✓			
09:45	2746-000	Sacred Heart Childrens's Home	6M5-1							✓			
09:50	2748-000	F J Richter Farms Partners	6M5-3							✓			
10:00	2751-000	Hapo Holdings LLC	Ghost							✓			
10:25	2812-000	Sherry R Lewis	5M5-7							✓			
10:50	2753-000	Angelita Hernandez	4M5-8							✓			
10:50	2753-001	Profirio Hernandez	4M5-8							✓			
11:00	2754-000	Martha Cadena	Ghost							✓			
11:15	2756-000	Philip John Mac Mahon	4M5-10							✓			
11:15	2756-001	Philip John Mac Mahon	4M5-10M							✓			
11:25	2757-000	Javier Acevedo	6M5-11							✓			
11:40	2758-000	Antonio C Lopez	3M5-12A							✓			
11:55	2759-000	Carlos T Benavides Jr	8M5-13							✓			
12:05	2759-001	Killam Development Ltd	3M Temp							✓			
12:05	2721-000	Killam Development	3M Temp							✓			
12:15	2720-001	Webb County Utilities	3M6-1							✓			
12:15	2720-001	Webb County Utilities	3M6-1A							✓			
12:15	2720-002	Webb County Utilities	6M6-1B							✓			
12:15	2720-002	Webb County Utilities	6M6-1C							✓			
12:15	2720-002	Webb County Utilities	6M6-1D							✓			
13:00	2768-000	Lasker O'Keefe Hereford	12M6-6							✓			
13:10	2769-00	Rancho Blanco LLC	12M6-7							✓			
13:10	2769-000	Rancho Blanco LLC	10M6-8							✓			
13:20	2772-001	Rancho Blanco LLC	12M6-11							✓			



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Comments: Page 2 of 2 Specialist Signature *Araceli Thatcher*



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/04/2021	Inspections:	49
Time Start:	09:15	Measurement:	0
Time End:	16:45	Doppler:	0
Inspec Time:	5.5	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.5

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:05	2779-009	Lone Star La Perla	4M7-11A							✓			
10:35	2780-000	Wichita Partnership LTD	12M7-14							✓			
10:35	2780-001	Wichita Partnership LTD	Mining							✓			
11:00	2781-001	Fernando Gurtierrez	4M7-15							✓			
11:00	2781-001	Fernando Gutierrez	Ghost							✓			
11:30	2782-000	M C Properties Partnership	6M62-2							✓			
12:45	0461-005	Siesta Shores	6M10-6B	300	210					✓	✓		
12:45	0345-001	Siesta Shores	6M10-6C							✓			
12:55	DF 75	Dan Richter	"							✓			
12:55	2426-002	Donald L Hayes	1M10-6							✓			
13:00	2430-000	Wayne Pierce	Ghost							✓			
13:05	2808-000	D G Delorme Oso Blanco	Ghost							✓			
13:10	2810-000	J A Guevara Best Western	Ghost							✓			
13:10	2809-000	D G Delorme Bass Lake Rv	Ghost							✓			
13:15	2422-003	Christine McKee	Ghost							✓			
13:20	2708-000	Joel Ruiz	Ghost							✓			
13:30	2725-001	Cyrus B Reynolds	2M9-27							✓			
13:35	2422-002	Lynn D Smith	Ghost							✓			
13:40	2426-001	L C Barker	1M9-25							✓			
13:50	2434-000	Orvalle J Flores	Ghost							✓			
13:50	2433-000	C E Deyo	Ghost							✓			
13:50	2718-000	Gerald Bader	Ghost							✓			
13:53	2806-000	Zapata Co WW	Ghost							✓			
13:55	DF 70	L W DAaker	Ghost							✓			
13:55	DF 57	R N Bledsoe	Ghost							✓			

Comments:

Page

1

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:10	2804-001	Elena Strokes	1M9-22A							✓			
14:10	2804-002	John A Nixon	1M9-22A							✓			
14:15	2804-000	Zapata Co Water Works	16M9-21C							✓			
14:15	2804-000	Zapata Co Water Works	16M9-21D							✓			
14:15	2804-000	Zapata Co Water Works	16M9-21E							✓			
14:25	DF-14	J R Terrell	-							✓			
14:25	DF-45	W I Hammond	-							✓			
14:27	2801-000	Jose Luis Garza	1M9-20							✓			
14:30	DF-61	B D Love	-							✓			
14:40	2719-000	Delozeis Family LP	Ghost							✓			
14:45	2429-001	Straud B Jacobs	Ghost							✓			
14:50	2432-001	T C Miller	Ghost							✓			
14:55	2431-001	T Weldon	Ghost							✓			
14:55	2435-009	J Reyes	Ghost							✓			
14:55	DF-58	M L Cave	Ghost							✓			
14:55	2435-010	M L Caves	Ghost							✓			
15:00	2435-007	FJ Kilian	Ghost							✓			
15:00	2435-002	Rock H Wilkinson	Ghost							✓			
15:10	DF-56	R E Lee	Ghost							✓			
15:15	2423-000	Albert J Long	Ghost							✓			
15:20	2428-000	A C Durivage	Ghost							✓			
15:25	2424-001	AF Muehsam	Ghost							✓			
15:30	2425001	Gaylen Gilbreath	Ghost							✓			
15:30	DF-20	J E Fields	Ghost							✓			

Comments:

Page

2

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date: 10/05/2021 Inspections: 17
Time Start: 09:30 Measurement: 0
Time End: 16:00 Doppler: 0
Inspec Time: 5.5 On-Site Notice: 0
RN#: 106122740 Travel Time: 2.0

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:45	2775-000	Roberto Vidaurri	4M7-1							✓			
10:45	2775-004	Gerardo Vidaurri	4M7-1B							✓			
11:40	2775-001	Edward J Herbst	8M7-3							✓			
11:40	2775-008	Rosemarie A Geary	8M7-3							✓			
11:40	2775-010	Jennifer Herbst Vergara	8M7-3							✓			
11:40	2775-011	Sandra E Parsome	8M7-3							✓			
11:40	2775-012	Mary Josephine Garcia	8M7-3							✓			
11:40	2775-0014	Alfred Herbst	8M7-3							✓			
13:25	2780-000	Wichita Partnership Ltd	12M7-14							✓			
13:25	2780-001	Wichita Partnership Ltd	Mining							✓			
14:15	2704-002	James Haynes	4M6-14							✓			
14:15	2704-002	James Haynes	4M6-15							✓			
14:35	2773-000	Henry H Miller	6Mm-16							✓			
14:55	2774-000	J E Briones	6M6-18							✓			
14:55	2774-000	J E Briones	6M6-18							✓			
14:55	2774-002	Zimmerman LP	6M6-18							✓			
14:55	2774-003	Ana Alicia Becerra	6M6-18							✓			

Comments:

Page 1 of 1 Specialist Signature
Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date: 10/06/2021 Inspections: 17
Time Start: 09:00 Measurement: 1
Time End: 17:00 Doppler: 0
Inspec Time: 4.0 On-Site Notice: 0
RN#: 106122740 Travel Time: 2.5

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:25	2757-000	Javier Acevedo	6M5-11							✓			
09:35	2758-000	Antonio C Lopez	3M5-12A							✓			
10:30	2786-001	El Campo Farms Co	Mining							✓			
10:30	2786-000	E Campo Farms Co	6M8-1C							✓			
10:30	2791-000	Maria E Uribe Ramirez	6M8-1C							✓			
10:30	2791-001	Maria E Uribe Ramirez	Mining							✓			
10:30	2788-000	Guadalupe Martinez Foundation	6M8-1C							✓			
10:45	2793-001	J Santiago Gutierrez	4M8-1B							✓			
13:10	2804-000	Zapata Co Water Works	16M9-21C							✓			
13:10	2804-000	Zapata Co Water Works	16M9-21D							✓			
13:10	2804-000	Zapata Co Water Works	16M9-21E							✓			
14:20	0461-005	Siesta Shores	6M10-6B	300	210					✓	✓		
14:20	0346-001	Siesta Shores	6M10-6C							✓			
15:35	2774-000	J E Briones	6M6-18							✓			
15:35	2774-000	J E Briones	6M6-18							✓			
15:35	2774-002	Zimmernan LP	6M6-18							✓			
15:35	2774-003	Ana Alicia Becerra	6M6-18							✓			

Comments: Skipped field sites due to customer' s appointments

Page 1 of 1

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/11/2021	Inspections:	40
Time Start:	09:00	Measurement:	0
Time End:	15:45	Doppler:	0
Inspec Time:	4.0	On-Site Notice:	0
RN#:	106122757	Travel Time:	2.0

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:35	2775-000	Roberto Vidaurri	4M7-1							✓			
09:35	2775-004	Gerardo Vidaurri	4M7-1B							✓			
10:10	2775-001	Martinez Quarter Horse Ranch	Ghost							✓			
10:45	2780-000	Wichita Partnership Ltd	12M7-14							✓			
10:45	2780-001	Wichita Partnership Lts	Mining							✓			
11:25	1708-001	Joel Ruiz 1	Joel1							✓			
11:25	2708-001	Joel Ruiz 3	Joel3							✓			
11:45	2785-000	Zapata County Water Works	4M7-23							✓			
11:45	2785-000	Zapata County Water Works	4M7-24							✓			
12:05	2786-001	El Campo Farms Co	Mining							✓			
12:05	2786-000	El Campo Farms Co	6M8-1C							✓			
12:05	2791-000	Maria E Uribe Ramirez	6M8-1C							✓			
12:05	2791-001	Maria E Uribe Ramirez	Mining							✓			
12:05	2788-000	Guadalupe Martinez Foundation	6M8-1C							✓			
12:35	2434-000	Orvalle J Flowers	Ghost							✓			
12:35	2433-000	C E Deyo	Ghost							✓			
12:35	2718-000	Gerald Bader	Ghost							✓			
12:40	2806-000	Zapata Co WW	Ghost							✓			
12:45	DF-70	L W Daiker	Ghost							✓			
12:47	DF-57	R N Bledsoe	Ghost							✓			
12:50	2435-002	Rock H Wilkinson	Ghost							✓			
13:00	2803-000	Deluxe Homes	Ghost							✓			
13:10	2719-000	Delozeis Family LP	Ghost							✓			
13:15	2429-001	Straud B Jacobs	Ghost							✓			
13:20	2432-001	T C Miller	Ghost							✓			

Comments: Skipped field sites due to customer' s appointment

Page 1 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
13:25	2435-000	M L Cave	Ghost							✓			
13:25	DF-58	M L Cave	Ghost							✓			
13:25	2435-009	J Reyes	Ghost							✓			
13:25	2431-001	T Weldon	Ghost							✓			
13:35	DF-61	BD Love	Ghost							✓			
13:40	2801-000	Jose Luis Garza	Ghost							✓			
13:40	DF-45	W I Hammond	Ghost							✓			
13:40	DF-14	J R Terrel	Ghost							✓			
13:55	2804-000	Zapata Co Water Works	16M9-21C							✓			
13:55	2804-000	Zapata Co Water Works	16M9-21D							✓			
13:55	2804-000	Zapata Co Water Works	16M9-21E							✓			
14:05	2423-000	Albert Long	Ghost							✓			
14:05	2428-000	A C Durivage	Ghost							✓			
14:05	2426-001	AF Muehsam	Ghost							✓			
14:10	2625-001	Gaylen Gilbreath	Ghost							✓			

Comments:

Specialist Signature
Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/12/2021	Inspections:	29
Time Start:	08:15	Measurement:	1
Time End:	16:45	Doppler:	0
Inspec Time:	6.0	On-Site Notice:	0
RN#: 106122732		Travel Time:	2.0

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:35	2747-A03	Select Energy Services	TP-3	3,570	3,300		30540.22			✓	✓		2
09:35	2747-A03	Select Energy Services	TP-4							✓			
09:35	2802-001	Louis C Lenchenger	Ghost							✓			
09:35	2714-001	Fasken LTD	Ghost							✓			
09:35	0812-010	Segundo Navarro Drilling	Ghost							✓			
09:35	CP-12640	Swift Energy Operations	Ghost							✓			
10:30	0812-010	Segundo Navarro Drilling LTD	Ghost							✓			
10:30	0812-010	Segundo Navarro Drilling LTD	Ghost							✓			
10:30	0812-010	Segundo Navarro Drilling LTD	Ghost							✓			
10:30	0812-010	Segundo Navarro Drilling LTD	Ghost							✓			
10:30	0812-010	Segundo NAvarro Drilling LTD	Ghost							✓			
11:20	3997-000	City of Laredo Colombia	Ghost							✓			
11:20	3997-000	City of Laredo Colombia	Ghost							✓			
11:00	2695-003	Needmore Ranch	10M2-9							✓			
11:00	2695-003	Needmore Ranch	10M2-10							✓			
11:00	2695-003	Needmore Ranch	10M2-11							✓			
12:10	0770-000	R & K Group LLC	2M2-12A							✓			
12:10	2704-007	R & K Group LLC	4M2-12B							✓			
12:50	2699-000	Jessland Properties Ltd	8M3-5							✓			
12:50	2699-000	Jessland Properties Ltd	8M3-5A							✓			
13:20	2699-002	Laredo Sand & Gravel Co	Mining							✓			
13:20	2742-000	Rodolfo Gacria	Ghost							✓			
13:45	2700-002	Gary W Wilkinson	Ghost							✓			
13:50	2700-003	City Ready Mix	Ghost							✓			
13:55	2700-005	Douglas M Brice	Ghost							✓			



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Comments: Page 2 of 2 Specialist Signature
Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date:	10-13-21	Inspections:	20
Time Start:	8:15	Measurement:	3
Time End:	16:00	Doppler:	1
Inspec Time:	5.5	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.5

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:35	2698-000	GML Ranch LLC	8M3-4							✓			
9:35	2698-008	City of Laredo Max MandellnGolf	4M3-4A							✓			
9:35	2774-005	City of Laredo Max Mandel Gold	“							✓			
9:50	2710-000	Nixon Ranch partnership	Ghost							✓			
9:50	2710-000	Nixon Ranch Partnership	Ghost							✓			
9:50	2710-007	Estate of Antonio R Sanchez	Ghost							✓			
10:15	3997-000	City of Laredo	30M3-12B	9000	9100		31214.939			✓	✓		
10:15	3997-000	City of Laredo	30M3-12C							✓			
10:15	3997-000	City of Laredo	30M3-12D							✓			
10:40	2711-000	Florence Arce	6M3-13				203.707			✓			
10:40	2711-000	Javier Emilio Garza	Ghost							✓			
11:15	2422 – 012	Richard Haynes	2M3-13B							✓			
11:15	2422-012	Richard Haynes	2M3-13C							✓			
11:50	2712-000	Julia B Muller	6M3-14							✓			
11:50	2712-001	Emerald Riverview Development	6M3-14							✓			
12:40	2712-002	Robert Muller Ltd	6M3-15A	550	430	429	615225			✓	✓	✓	
13:35	2713-993	Alberto F Muller	8M3-15B	500	350		613577			✓	✓		2
15:00	2743-000	Sheila Slaughter Glassford	Ghost							✓			
15:00	2743-001	David Slaughter Jr	Ghost							✓			
15:35	2746-000	Sacred Heart Children” s Home	6M4-23							✓			

Comments:

Skipped sites for training

Page

1

of

1

Specialist Signature

Macl Mike



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/14/2021	Inspections:	31
Time Start:	09:00	Measurement:	1
Time End:	15:45	Doppler:	0
Inspec Time:	6.0	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.0

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:35	2742-001	Laredo Municipal Jr. College	Ghost							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-18	20,000	23,145					✓	✓		
09:50	3997-000	City of Laredo Jefferson	14M4-19							✓			
09:50	3997-000	City of Laredo Jefferson	20M4-20							✓			
09:50	3997-000	City of Laredo Jefferson	20M4-21							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21A							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21B							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21C							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21D							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21E							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21F							✓			
09:50	3997-000	City of Laredo Jefferson	16M4-21G							✓			
10:20	2700-004	City Ready Mix	6M4-15							✓			
10:20	2734-000	Rodolfo Garcia	Ghost							✓			
10:40	3997-000	City of Laredo Del Mar	Ghost							✓			
10:40	3997-000	City of Laredo Del Mar	Ghost							✓			
10:40	3997-000	City of Laredo Del Mar	Ghost							✓			
11:10	2727-000	Talen Texas Property	10M4-7							✓			
11:10	2727-000	Talen Texas Property	10M4-8							✓			
11:10	2727-000	Talen Texas Property	6M4-9							✓			
11:10	2727-000	Talen Texas Property	6M4-10							✓			
11:20	2724-000	Rodolfo V Soliz	Ghost							✓			
13:20	2721-000	Killam Development	Ghost							✓			
13:20	2715-000	Mines Road Development	Ghost							✓			
13:35	2714-000	Fasken LTD	10M4-1							✓			

Comments:

Specialist Signature
Araceli Thatcher



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Comments: Returned to area to complete the previous day inspections Page 2 of 2 Specialist Signature *Araceli Thatcher*



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10/18/2021	Inspections:	45
Time Start:	08:30	Measurement:	3
Time End:	17:00	Doppler:	1
Inspection Time:	6.5	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.0

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
09:15	2775-000	Mauricio A Vidaurri	4M7-1							✓			
09:15	2775-004	Gerardo Vidaurri	4M7-1B							✓			
09:40	2775-001	Edward J Herbst	8M7-3							✓			
09:40	2775-008	Rosemarie A Geary	8M7-3							✓			
09:40	2775-010	Jennifer Herbst Vergara	8M7-3							✓			
09:40	2775-011	Sandra H Parsons	8M7-3							✓			
09:40	2775-012	Mary Josephine H Garcia	8M7-3							✓			
09:40	2775-014	Alfred Herbst	8M7-3							✓			
10:10	2776-001	Martinez Quarter Horse Ranch	Ghost							✓			
10:30	2779-009	Lone Star La Perla LP	10M7-4	1,500	1,400	1,388	557035			✓	✓		
11:35	2778-A/B00	Knapp Home Place LTD	10M7-7B				404869			✓			
11:00	2799-009	Lone Starr La Perla LP	4M7-11A							✓			
12:15	2782-A/B00	M C Properties Partnership	Ghost							✓			
12:40	2782-A/B00	M C Properties Partnership	Ghost							✓			
12:50	2782-A/B00	MC Properties Partnership	6M62-2							✓			
13:25	2804-000	Zapata County Water Works	4M7-23	350	410		606597			✓	✓		
13:25	2804-000	Zapata County Water Works	4M7-24							✓			
14:35	2743-001	David M SLaughter	6M4-23							✓			
14:35	2743-000	Sheila Slaughter Glassford	6M4-23							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-18	20,000	17,710		7838.57			✓	✓		
14:50	3997-000	City of Laredo - Jefferson	14M4-19							✓			
14:50	3997-000	City of Laredo - Jefferson	20M4-20							✓			
14:50	3997-000	City of Laredo - Jefferson	20M4-21							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21A							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21B							✓			



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:50	3997-000	City of Laredo - Jefferson	16M4-21C							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21D							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21E							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21F							✓			
14:50	3997-000	City of Laredo - Jefferson	16M4-21G							✓			
15:10	2742-001	Laredo Municipal Jr College	Ghost							✓			
15:25	2735-001	U S Dept of Labor	Ghost							✓			
15:40	2700-004	City Ready Mix Inc	6M4-15				785827			✓			
15:55	3997-000	City of Laredo Del Mar	10M4-12							✓			
15:55	3997-000	City of Laredo Del Mar	8M4-13							✓			
15:55	3997-000	City of Laredo Del Mar	10M4-14							✓			
16:05	2727-000	Talen Texas Property LLC	6M4-10				182930			✓			
16:05	2727-000	Talen Texas Property LLC	6M4-9							✓			
16:05	2727-000	Talen Texas Property LLC	6M4-8							✓			
16:05	2727-000	Talen Texas Property LLC	6M4-7							✓			
16:15	2724-000	Rodolfo V Solis	Ghost							✓			
16:20	2721-000	Killam Development Corp	Ghost							✓			
16:20	2715-000	Mines Road Development	Ghost							✓			
15:30	2714-000	Fasken Ltd	10M4-1							✓			
15:30	2714-000	Fasken Ltd	10M4-1							✓			

Comments:

Page

2

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Date:	10-19-2021	Inspections:	44
Time Start:	9:15	Measurement:	1
Time End:	16:50	Doppler:	0
Inspection Time:	5.0	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:15	0812-010	Segundo Navarro Drilling	10M2-8H							✓			
10:15	0812-010	Segundo Navarro Drillong	10M2-8I							✓			
10:15	0812-010	Segundo Navarro Drilling	10M2-8J							✓			
10:15	0812-010	Segundo Navarro Drilling	10M2-8K							✓			
10:15	0812-010	Segundo Navarro Drilling	10MM-8G							✓			
10:35	3997-000	City of Laredo Colombia	4M2-8B							✓			
10:35	3997-000	City of Laredo Colombia	4M2-8C							✓			
10:45	2695-003	Needmore Ranch	10M2-9							✓			
10:45	2695-003	Needmore Ranch	10M2-10							✓			
10:45	2695-003	Needmore Ranch	10M2-11							✓			
11:05	0770-000	R & K Group LLC	2M2-12A							✓			
11:05	2704-007	R & K Group LLC	4M2-12B							✓			
11:25	2696-001	5-D Inc	10M3-1							✓			
11:25	2696-001	5-D Inc	10M3-2							✓			
11:25	2696-001	5-D Inc	3M3-2A							✓			
11:45	2697-000	Mos Professional Bldg Inc	6M3-3A				062069			✓			
11:45	2697-001	Mos Professional Bldg Inc	3M3-3B							✓			
12:20	2698-000	GML Rancho	8M3-4							✓			
12:20	2698-000	GML Rancho	4M3-4A							✓			
12:20	2774-005	City of Laredo	"							✓			
12:45	2699-000	Jessland Properties Ltd	8M3-5							✓			
12:45	2699-000	Jessland Properties Ltd	8M3-5A							✓			
12:50	2699-000	Laredo Sand & Gravel	Mining							✓			
12:50	2742-000	Rodolfo Garcia	Mining							✓			
13:00	2700-003	Gary W Wilkinson	Ghost							✓			

Comments:

Specialist Signature

Anya Ont



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
13:00	2700-003	City Ready Mix	Ghost							✓			
13:10	2700-006	Douglas Brice	Mining							✓			
12:10	2705-000	Haizlip Ranch	Ghost							✓			
13:20	2706-000	Ben Hur	8M3-11				175068			✓			
13:35	2706-000	Ben Hur	6M3-11C							✓			
13:50	2710-007	Robert J Gilpin	6M3-12							✓			
13:50	2710-000	Robert J Gilpin	3M3-12A							✓			
13:50	2782-007	Estate of Antonio R Sanchez	Ghost							✓			
14:10	3997-000	City of Laredo	30M3-12B	9000	5400		1079.670			✓	✓		
14:10	3997-000	City of Laredo	30M3-12C							✓			
14:10	3997-000	City of Laredo	30:3-12D							✓			
14:30	2711-000	Florence Arce	6M3-13							✓			
14:30	2711-000	Florence Arce	Ghost							✓			
14:45	2422-012	Richard Haynes	2M3-13B							✓			
14:45	2422-012	Richard Haynes	2M3-13C							✓			
15:45	2712-A/B00	Julia B Muller Ruhlman	6M3-14							✓			
15:45	2712-A/B01	Emerald Riverview Development	6M3-14							✓			
16:10	2713-A/B02	Robert Muller	6M3-15A							✓			
16:25	2713-A01	Albert F Muller	8M3-15B							✓			

Comments: 2706-000 painted pump - 2422-012 broken chain link and installed a TCEQ lock with the authorization on Ricardo De Anda

Page 2 of 2

Specialist Signature

Ricardo De Anda



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date: 10-20-21 Inspections: 45
Time Start: 9:30 Measurement: 3
Time End: 16:45 Doppler: 1
Inspec Time: 5.5 On-Site Notice: 0
RN#: 106122740 Travel Time: 1.5

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:30	2788-000	The Guadalupe Martinez and Lilia. Mtz	6M8-1C							✓			
10:30	2791-001	Maria E Uribe Ramirez	Mining							✓			
10:30	2791-000	Maria E Uribe Ramirez	6M8-1C							✓			
10:30	2786-003	Lam Family Ranches Ltd	6M8-1C							✓			
10:50	2804-000	Zapata County Water Works	4M7-23	350	280		606834.000			✓	✓		
10:50	2804-000	Zapata County Water Works	4M7-24							✓			
10:55	2708-001	Joel Ruiz	Joel 1							✓			
11:00	2708-001	Joel Ruiz	Joel 2							✓			
11:05	2782-A/B00	M C Partnership	6M62-2							✓			1
11:05	2782-A/B00	M C Partnership	Ghost							✓			
11:25	2782-A/B00	M C Partnership	Ghost							✓			
11:45	2781-001	Fernando Gutierrez	4M7-15							✓			
11:45	1781-001	Fernando Gutierrez	Ghost							✓			
11:55	2780-000	Wichita Partnership Ltd	12M7-14				567441			✓			
12:05	2779-009	Lone Star La Perla	4M7-11A							✓			
12:15	2778-A/B00	Knapp Home Place Ltd	10M7-7B							✓			
12:40	2779-009	Loan Star La Perla LP	10M7-4	1500	1650	1688	557518.00			✓	✓		
12:40	2776-003	ATM 2005 LLC	10M7-4							✓			
12:30	2776-001	Martinez Quarter Horse Ranch	Ghost							✓			
13:05	2775-001	Edward Herbst	8M7-3							✓			
13:05	2775-008	Rosemarie A Geary	8M7-3							✓			
13:05	2775-010	Jennifer Herbst Vergara	8M7-3							✓			
13:05	2775-011	Sandra H Parsons	8M7-3							✓			
13:05	2775-012	MaryJosephine H Garcia	8M7-3							✓			
13:05	2775-014	Alfred J Herbst	8M7-3							✓			

Comments: 6M62-2 painted pump

Page 1 of 2

Specialist Signature

Michael Nicks



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:05	2774-003	Ana Alicia Peña Becerra	6M6-18							✓			
14:05	2774-002	Zimmerman LP No 1	6M6-18							✓			
14:15	2704-002	2MB Land Cattle LLC	6M6-16				273059			✓			
14:35	2704-002	James Haynes Jr	4M6-14							✓			4
14:35	2704-002	James Haynes Jr	8M6-15							✓			4
15:05	2720-001	Webb County Utilities Dept	3M6-1							✓			
15:05	2720-001	Webb County Utilities Dept	3M6-1A							✓			
15:05	2720-002	Webb County Utilities Dept	6M6-1B	850	994		26463543.85			✓	✓		
15:05	2720-002	Webb County Utilities Dept	6M6-1C							✓			
15:05	2720-002	Webb County Utilities Dept	6M6-1D							✓			
15:05	2720-002	Webb County Utilities Dept	CWQMN							✓			
15:15	2772-A/B01	Rancho Blanco LLC	12M6-12				805063.000			✓			
15:20	2772-A/B01	Rancho Blanco LLC	12M6-11							✓			
15:30	2772-A/B01	Rancho Blanco LLC	12M6-6							✓			
15:30	2772-A/B01	Rancho Blanco LLC	12M6-7							✓			
15:50	2772-A/B01	Rancho Blanco LLC	10BC-3							✓			
15:50	2704-002	Rancho Blanco LLC	Mining							✓			
14:10	2768-000	Lasher O' Keefe Hereford	12M6-6							✓			
14:25	2763-000	Compass Bank Trustee	10M6-2A							✓			
14:25	2763-000	Compass Bank Trustee	Ghost							✓			

Comments: 6M6-16 painted pump / James Haynes broken tree on the middle of the road

Page 2 of 2

Specialist Signature

Michael N. [Signature]



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date: **10-25-21** Inspections: **37**
Time Start: **8:45** Measurement: **1**
Time End: **16:30** Doppler: **0**
Inspec Time: **5.5** On-Site Notice: **0**
RN#: **106122732** Travel Time: **2.0**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:50	2812-001	Louis Lechenger	Ghost							✓			
9:50	2714-001	Fasten Ltd	6M2-8A							✓			
9:50	0812-010	Segundo Navarro Drilling	6M2-8D							✓			
9:50	CP-12640	Silver bow Resources Operating LLC	8M2-8E&F							✓			
9:50	2747-A03	Select Energy Services	TP-3	840	827.4					✓	✓		2
9:50	2747-A03	Select Energy Services	TP-4							✓			
10:45	0812-010	Segundo Navarro Drilling Ltd	10M2-8H							✓			
10:45	0812-010	Segundo Navarro Drilling Ltd	10M2-8I							✓			
10:45	0812-010	Segundo Navarro Drilling Ltd	10M2-8J							✓			
10:45	0812-010	Segundo Navarro Drilling Ltd	10M2-8K							✓			
10:45	0812-010	Segundo Navarro Drilling Ltd	10M2-8G							✓			
11:05	3997-000	City of.Laredo - Colombia	Ghost							✓			
11:15	2695-003	Needmore Ranch II Ltd	10M2-9							✓			
11:15	2695-003	Needmore Ranch II Ltd	10M2-10							✓			
11:15	2695-000	Needmore Ranch II Ltd	10M2-11							✓			
11:35	0770-000	R & K Group LLC	2M2-12A							✓			
11:35	2704-000	R & K Group LLC	4M2-12B							✓			
11:50	2696-001	5D Inc	10M3-1				178502			✓			
11:50	2696-001	5D. Inc	10M3-2							✓			
11:50	2696-001	5D Inc	3M3-2A							✓			
12:15	2697-000	Mos Professional Bldg Inc	6M3-3A							✓			
12:15	2697-001	Mos Professional Bldg Inc	3M3-3B							✓			
13:25	2698-000	GML Rancho LLC	8M3-4A							✓			
13:25	2698-000	GML Rancho LLC	4M3-4A							✓			
13:25	2774-005	City of Laredo	"							✓			

Comments:

Page

1

of

2

Specialist Signature

Macl Mike



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Comments:
6M3-11C painted pump

Page
2
of
2

Specialist Signature




Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Date: **10-26-21** Inspections: **41**
Time Start: **8:45** Measurement: **1**
Time End: **16:30** Doppler: **0**
Inspec Time: **5.0** On-Site Notice: **0**
RN#: **106122732** Travel Time: **1.5**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:25	3997-000	City of Laredo	30M3-12B	9000	8262		31359.279			✓	✓		
9:25	3997-000	City of Laredo	30M-12C							✓			
9:25	3997-000	City of Laredo	30M3-12D							✓			
9:45	2711-000	Florence Arce	6M3-13							✓			
9:45	2711-000	Florence Arce	Ghost							✓			
10:15	2422-012	Richard Haynes	2M3-13B							✓			
10:15	2422-012	Richard Haynes	2M3-13C							✓			
10:40	2712-A/B00	Julia B Muller Ruhlman	6M3-14							✓			
10:40	2712-A/B00	Emerald Riverview Development	6M3-14							✓			
11:00	2713-004	Robert Muller	6M3-15A							✓			
11:25	2713-A01	Albert F Muller Jr	8M3-15B							✓			
12:40	2714-000	Fasten Ltd	10M4-1				262893783			✓			
12:40	1714-000	Fasten Ltd	10M4-2							✓			
13:05	2715-000	Mines Road Development	Ghost							✓			
13:05	2721-000	Killam Development Corp	Ghost							✓			
13:20	2724-000	Rodofo V Soliz	Ghost							✓			
13:25	2727-000	Talen Texas Property LLC	10M4-7							✓			
13:25	2727-000	Talen Texas Property LLC	10M-8							✓			
13:25	2727-000	Talen Texas Property LLC	6M4-9							✓			
13:25	2727-000	Talen /Texas Property LLC	6M4-10							✓			
13:35	3997-000	City of Laredo Del Mar	Ghost							✓			
13:35	3997-000	City of Laredo Del Mar	Ghost							✓			
13:45	27000-004	City Reday Mix	6M4-15				790644			✓			
13:45	2735-001	US dept of Labor	Ghost							✓			
14:05	3997-000	City of Laredo Jefferson	16M-18							✓			

Comments:

Page

1

of

2

Specialist Signature

Macl Mike



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:05	3997-000	City of Laredo Jefferson	14M4-19							✓			
14:05	3997-000	City of Laredo Jefferson	20M4-20							✓			
14:05	3997-000	City of Laredo Jefferson	20M4-21							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-21A							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-21B							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-21C							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-21D							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-21E							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-16F							✓			
14:05	3997-000	City of Laredo Jefferson	16M4-16G							✓			
14:25	2742-000	Laredo Municipal Jr College	Ghost							✓			
14:50	2742-000	Rodolfo Garcia	Ghost							✓			
15:10	2743-000	Sheila Slaughter Glassford	Ghost							✓			
15:10	2743-001	David M Slaughter Jr	Ghost							✓			
15:25	2746-000	Sacred Heart Children” s Home	6M5-1							✓			
15:45	2748-000	Francis Richter Farm Partners	6M5-3				250313			✓			

Comments:

Specialist Signature

Maeda Nunez