

WM MR\_Rio Grande\_RP\_20220222\_Monthly Report-athatcher  
**Texas Commission on Environmental Quality**  
**Investigation Report**

The TCEQ is committed to accessibility. If you need assistance in accessing this document, please contact oca@tceq.texas.gov

**Customer: RGWM Insp Middle Reach IV San Antonio Xing  
Laredo Bridge I  
Customer Number: CN603837360**

---

**Regulated Entity Name: RGWM-INSP-MIDDLE REACH IV- SAN ANTONIO  
XING- LAREDO BRIDGE I**

**Regulated Entity Number: RN106122732**

**Investigation #** 1795448

**Investigator:** ARACELI THATCHER

**Conducted:** 02/08/2022 -- 02/22/2022

**Program(s):** WATER RIGHTS

**Investigation Type:** Compliance Investigation

**Incident Numbers**

**Site Classification** CERTIFICATE OF  
ADJUDICATION

**No Industry Code Assigned**

**Location:**

RN105900716,RN103137550,RN102642675,RN102642  
246,RN103130837,  
RN102642832,RN102642915,RN101517796,RN102820  
203,RN101485175,  
RN102643194,RN102631215,RN102888039,RN101481  
687,RN101481042,  
RN102632003,RN101481620,RN102819059,RN10390  
9040,RN102641677, RN102625068,

**Additional ID(s):**

**Address:** ,  
, ,

**Local Unit:** REGION 16 - LAREDO

**Activity Type(s):** WMDIVER - WM Diversion Site  
Investigation

**Principal(s):**

**Role**

**Name**

RESPONDENT  
RESPONDENT  
RESPONDENT

RGWM INSP MIDDLE REACH VI SAN YGNACIO FALCON  
RGWM INSP MIDDLE REACH IV SAN ANTONIO XING L  
RGWM INSP MIDDLE REACH V LAREDO BRIDGE I SAN

**Contact(s):**

**Role**

**Title**

**Name**

**Phone**

---

**Other Staff Member(s):**

**Role**

**Name**

QA Reviewer  
Supervisor

GEORGINA BERMEA  
ANTHONY STAMBAUGH

## Associated Check List

**Checklist Name**

RIO GRANDE WATERMASTER INSPECTION  
CHECKLIST

**Unit Name**

RGWM-CHK

**Investigation Comments:**

CCEDS INVESTIGATION No. 1795448

### INTRODUCTION

Watermaster Specialist, Araceli Thatcher of the Texas Commission on Environmental Quality (TCEQ), Rio Grande Watermaster Program, conducted water right site investigations and monitored surface water use along the Rio Grande River and its tributaries. These field investigations were conducted during the period of February 8 thru February 16, 2022 and included water right holders /diverters within the following reaches of the Rio Grande.

Middle Rio Grande Reach's (MR) have been broken down as follows:

- MR I between Amistad Dam and Del Rio International Bridge - RN106122690
- MR II between Del Rio Int'l Bridge and the Eagle Pass Int'l Bridge - RN106122716
- MR III between the Eagle Pass Int'l Bridge and San Antonio Crossing - R106122724
- MR IV between the San Antonio Crossing (Xing) and Laredo Int'l Bridge - RN106122732
- MR V between the Laredo International Bridge and San Ygnacio - RN106122740
- MR VI between the San Ygnacio to Falcon Dam - RN106122757

Middle Rio Grande Tributaries (MT) have been broken down as follows:

- MT - Cienegas and San Felipe creeks - RN106122765
- MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado, and Rosita creeks - RN106122807
- MT - San Ambrosia, Manadas, Lake Casa Blanca, Becerro, Nopalosa and Javalina creeks - RN106123060

### GENERAL ENTITY AND PROCESS INFORMATION

The following entities referred to in this investigation were surveyed and/or monitored during the field investigations. The entities are described by the following standard industrial classification (SIC) codes: 721 for crop planting, cultivating, and/or protecting, 1381 for oil and gas exploration activities, and/or 4941 for water supply entities.

A detailed description of each regulated entity with its associated water right account information can be found in the TCEQ Rio Grande Watermaster files, including specific SIC codes and associated water right information.

Water right accounts and or diverters in the following reaches or segments:

- MR I-Amistad Dam to Del Rio Bridge,
- MR II-Del Rio Bridge to Eagle Pass Bridge,
- MR III-Eagle Pass Bridge to San Antonio Crossing,
- MR IV-San Antonio Crossing and the Laredo Bridge,
- MR V-Laredo Bridge to San Ygnacio, MR V- Laredo Bridge to San Ygnacio,
- MR VI- San Ygnacio to Falcon Dam,
- MT - Cienegas and San Felipe creeks,
- MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado, and Rosita creeks,
- MT - San Ambrosia, Manadas, Becerra, Nopalosa, and Javalina creeks

### BACKGROUND

The TCEQ Rio Grande Watermaster Program routinely conducts investigations along the Rio Grande River and/or its Tributaries to ensure compliance with applicable State rules and regulations related to the watermaster program and to the diversion and use of State waters.

### ADDITIONAL INFORMATION:

During the course of these investigations, the Watermaster Specialist performed watermaster-related activities that may have included but were not limited to the following:


- 288 Inspections
- 18 Measurements
- 8 Doppler Checks
- 0 On-Site Notices

Please refer to the attached investigation notes (Attachment A: Deputy's Daily Report) for the specific observations of these investigation sites.

**No Violations Associated to this Investigation**

Signed Araceli Thatcher  
 Environmental Investigator

Date 02/28/2022

Signed   
 Supervisor

Date 02/28/2022

**Attachments: (in order of final report submittal)**

- Enforcement Action Request (EAR)
- Letter to Facility (specify type) : \_\_\_\_\_
- Investigation Report
- Sample Analysis Results
- Manifests
- Notice of Registration

- Maps, Plans, Sketches
- Photographs
- Correspondence from the facility
- Other (specify) : Attachment A: Deputy's Daily Report

**TEXAS COMMISSION ON ENVIRONMENTAL  
QUALITY**



**ATTACHMENT A**

<b>Regulated Entity No.</b>	RN106122690 RN106122716 RN106122724 RN106122732 RN106122740 RN106122757	<b>Regulated Entity</b>	<b>Lower Reaches I, II, III, IV, V, VI</b>	<b>County Name</b> WEBB Zapata	<b>WEBB AND ZAPATA</b>
<b>Investigation Date</b>	<b>02/08/2022 to 02/22/2022</b>	<b>TCEQ Investigator(s):</b>	<b>Araceli Thatcher</b>		

Deputy Daily Report

02/08/2022, 02/09/2022, 02/10/2022, 02/14/2022, 02/15/2022, 02/16/2022, 02/22/2022



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/8/2022	Inspections:	42
Time Start:	10:45 AM	Measurement:	3
Time End:	4:20 PM	Doppler:	2
Inspec Time:	5.00	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:25	2793-001	J Santiago Gutierrez	4M8-1B							X			
11:35	2788-000	The Guadalupe & Lilia Mtz	6M8-1C							X			
11:35	2791-001	Maria E Uribe Ramirez	Mining							X			
11:35	2791-000	Maria E Uribe Ramirez	6M8-1C							X			
11:35	2786-003	Lam Family Ranchers Ltd	6M8-1C							X			
11:45	2787-000	Oscar O Lopez	Ghost							X			
11:50	2804-000	Zapata County Water Works	4M7-23	350	280		620941			X	X		
11:50	2804-000	Zapata County Water Works	4M7-24							X			
11:55	2708-001	Joel Ruiz	Joel 1							X			
11:55	2708-001	Joel Ruiz	Joel 2							X			
11:55	2708-001	Joel Ruiz	Joel 3							X			
12:00	2782-A/B00	M C Properties Partnership	6M62-2							X			
12:00	2782-A/B00	M C Properties Partnership	Ghost							X			
12:07	2747-A/B03	Barry Gilpin	Ghost							X			
12:07	2782-A/B00	M C Properties Partnership	Ghost							X			
12:15	2781-001	Fernando Gutierrez	Ghost							X			
12:25	2780-000	Wichita Partnership	12M7-14				575526			X			
12:40	2779-009	Lone Star La Perla	4M7-11A	425	450	432	801837			X	X		
12:50	2778-A/B00	Knapp Home Place Ltd	10M7-7B				42754			X			
13:05	2777-001	Fender Exploration & Product Co	Mining							X			
13:20	2779-009	Lone Star La Perla LP	10M7-4	1500	1750	1732	564681			X	X		
13:20	2776-003	ATM 2005 LLC	10M7-4							X			
13:40	2776-001	Martinez Quarter Horse Rnch Ltd	Ghost							X			
13:45	0339-002	Rufino Garza	6M6-17				42065			X			
14:05	2775-014	Alfred J Herbst	8M7-3							X			

Comments: picked up vehicle from repair shop at 10:30 am ; 4M7-11A painted pump

*Araceli Thatcher*



**Texas Commission on Environmental Quality**  
**Rio Grande Watermaster**  
**Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:05	2775-012	Mary Josephine H Garcia	8M7-3							X			
14:05	2775-011	Sandra H Parsons	8M7-3							X			
14:05	2775-010	Jennifer Herbst Vergara	8M7-3							X			
14:05	2775-008	Rosemarie A Geary	8M7-3							X			
14:05	2775-001	Edward J Herst	8M7-3							X			
14:25	2775-004	Gerardo Vidaurri	4M7-1B							X			
14:25	2775-000	Mauricio A Vidaurri	4M7-1							X			
14:40	2774-003	Ana Alicia Peña Becerra	6M6-18							X			
14:40	2774-002	Zimmerman LP No 1	6M6-18							X			
15:00	2773-000	2MB Land and Cattle LLC	6M6-16							X			
15:15	2704-002	James Haynes Jr	8M6-15							X			
15:15	2704-002	James Haynes Jr	4M6-14							X			
15:40	2720-001	Webb County (Utilities Dept)	3M6-1							X			3
15:40	2720-001	Webb County (Utilities Dept)	3M6-1A							X			
15:40	2720-002	Webb County (Utilities Dept)	6M6-1B							X			
15:40	2720-002	Webb County (Utilities Dept)	6M6-1C							X			
15:40	2720-002	Webb County (Utilities Dept)	6M6-1D							X			
15:40													

Comments:

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/9/2022	Inspections:	51
Time Start:	8:45 AM	Measurement:	2
Time End:	4:10 PM	Doppler:	1
Inspec Time:	5.00	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:45	2772-A/B01	Rancho Blanco LLC	10BC-3							X			
9:55	2772-A/B01	Rancho Blanco LLC	12M6-12							X			
10:00	2772-A/B01	Rancho Blanco LLC	12M6-11							X			
10:20	2768-000	Lasker O'Keefe Hereford	12M6-6							X			
10:40	2763-000	Compass Bank, Trustee	Ghost							X			
10:40	2763-000	Compass Bank, Trustee	10M6-2A							X			
10:55	2720-002	Webb County(Uilities Dpt)	6M6-1B				13388912.3			X			
10:55	2720-002	Webb County(Uilities Dpt)	6M6-1C							X			
10:55	2720-002	Webb County(Uilities Dpt)	6M6-1D							X			
10:55	2720-001	Webb County(Uilities Dpt)	3M6-1							X			
10:55	2720-001	Webb County(Uilities Dpt)	3M6-1A							X			
11:10	2721-000	Killam Development Ltd	3M Temp							X			
11:10	2759-001	Killam Development Ltd	3M Temp							X			
11:15	2759-000	Carlos Y Benavides Jr	8M5-13							X			
11:25	2758-000	Antonio C Lopez Sr	3M5-12A							X			
11:35	2757-000	Javier Acevedo	6M5-11							X			
11:40	2754-000	Martha Cadena	Ghost							X			
11:55	2753-001	Porfirio Hernandez	4M5-8							X			
11:55	2753-000	Angelita Hernandez	4M5-8							X			
11:55	2812-000	Sherry R Lewis	5M5-7							X			
12:00	2751-000	City of Laredo	Ghost							X			
12:10	2748-000	Francis Ruchter Farm Partners	6M5-3							X			
12:25	2746-000	Sacred Heart Children's Home	6M5-1							X			
13:20	2743-001	David M Slaughter Jr	6M4-23							X			
13:20	2743-000	Sheila Slaughter Gassford	6M4-23							X			

Comments: Charging doppler instrument for field work use

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
12:30	2742-000	Rodolfo Garcia	Ghost							X			
13:45	2742-001	Laredo Munciple Jr College	3M4-22							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-18	20000	18700		75169.17			X	X		
14:00	3997-000	City of Laredo - Jefferson	14M4-19							X			
14:00	3997-000	City of Laredo - Jefferson	20M4-20							X			
14:00	3997-000	City of Laredo - Jefferson	20M4-21							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21A							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21B							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21C							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21D							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21E							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21F							X			
14:00	3997-000	City of Laredo - Jefferson	16M4-21G							X			
14:00	2735-001	U S Dept of Labor	Ghost							X			
14:20	2700-001	CityReadyMix	6M4-15	600	580	584	4540			X	X		3
14:45	3997-000	City of Laredo Del Mar	10M4-14							X			
14:45	3997-000	City of Laredo Del Mar	8M4-13							X			
14:45	3997-000	City of Laredo Del Mar	10M4-12							X			
14:50	2727-000	Talen Texas Property LLC	6M4-9							X			
14:50	2727-000	Talen Texas Property LLC	6M4-10							X			
14:50	2727-000	Talen Texas Property LLC	10M4-7							X			
14:50	2727-000	Talen Texas Property LLC	10M4-8							X			
15:15	2721-000	Killam Development Corp	Ghost							X			
15:20	2715-000	Mines Road Development	Ghost							X			
15:30	2714-000	Fasken Ltd	10M4-1				278670353			X			

Comments:

Specialist Signature  
*Araceli Thatcher*







**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/10/2022	Inspections:	34
Time Start:	11:35 AM	Measurement:	3
Time End:	4:10 PM	Doppler:	1
Inspec Time:	3.00	On-Site Notice:	0
RN#:	106122732	Travel Time:	1.50

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:45	2743-001	David M Slaughter	6M4-23							X			
11:45	2743-000	Sheila Slaughter Glassford	6M4-23							X			
11:55	2742-000	Rodolfo Garcia	Ghost							X			
12:10	2742-001	Laredo Municipal Jr College	3M4-22							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-18	20000	15600		75191.938			X	X		
12:25	3997-000	City of Laredo - Jefferson	14M6-19							X			
12:25	3997-000	City of Laredo - Jefferson	20M4-20							X			
12:25	3997-000	City of Laredo - Jefferson	20M4-21							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21A							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21B							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21C							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21D							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21E							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21F							X			
12:25	3997-000	City of Laredo - Jefferson	16M4-21G							X			
12:40	2735-001	US Dept of Labor	Ghost							X			
12:45	2735-004	CityReady Mix Inc	6M4-15				5342			X			
12:55	3997-000	City of Laredo - Del Mar	10M4-12							X			
12:55	3997-000	City of Laredo - Del Mar	8M4-13							X			
12:55	3997-000	City of Laredo - Del Mar	10M4-14							X			
12:55	3997-000	City of Laredo - Del Mar	6M4-15							X			
13:05	2727-000	Talen Texas Propery, LLC	6M4-10							X			
13:05	2727-000	Talen Texas Propery, LLC	6M4-9							X			
13:05	2727-000	Talen Texas Propery, LLC	10M4-8							X			
13:05	2727-000	Talen Texas Propery, LLC	10M4-7							X			

Comments: Medical monitoring at 10:00 am - started route at 11:35 am

Specialist Signature  
*Araceli Thatcher*





**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/14/2022	Inspections:	45
Time Start:	8:30 AM	Measurement:	2
Time End:	4:10 PM	Doppler:	1
Inspec Time:	5.00	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:05	2812-001	Louis C Lechenger	Ghost							X			
10:05	0812-010	Fasken Ltd	6M2-8A							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	6M2-8D							X			
10:05	CP-12640	Silverbow Resources Operating LLC	8M2-8E&F							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	10M2-8H							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-13							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	10M2-8J							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-14							X			
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-8G							X			1
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-15	1844	3872		2173450.3			x	X		1
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-16							X			1
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-17							X			1
10:05	0812-010	Segundo Navarro Drilling Ltd	8M2-18							X			1
11:25	3997-000	City of Laredo Colombia	4M2-8B							X			
11:25	3997-000	City of Laredo Colombia	4M2-8C							X			
11:40	2695-003	Needmore Ranch II Ltd	10M2-9							X			
11:40	2695-003	Needmore Ranch II Ltd	10M2-10							X			
11:40	2695-003	Needmore Ranch II Ltd	10M2-11							X			
11:55	0770-000	R & K Group LLC	2M2-12A							X			
11:55	2704-007	R & K Group LLC	4M2-12B							X			
12:20	2696-001	5D Inc	10M3-1				229792			X			
12:20	2696-001	5D Inc	10M3-2							X			
12:20	2696-001	5D Inc	3M3-2A							X			
12:30	2697-000	Mos Professional Bldg Inc	6M3-3A							X			
12:30	2697-001	Mos Professional Bldg Inc	3M3-3B							X			

Comments: Painted pumps for 8M3-12, 8M2-14, 10M2-10 & 10M2-11 -  
No doppler due to rubber pipes

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
12:45	2698-000	GML Ranch LLC	8M3-4							X			
12:45	2698-000	GML Ranch LLC	4M3-4A							X			
12:45	2774-005	City of Laredo	—							X			
13:05	2699-000	Jessland Properties Ltd	8M3-5							X			
13:05	2699-000	Jessland Properties Ltd	8M3-5A							X			
14:15	2699-002	Laredo Sand & Gravel Co	Mining							X			
14:15	2700-002	Gary W Wilkinson	Ghost							X			
14:15	2700-003	CityReady Mic Inc	Ghost							X			
14:15	2703-000	Gary W Wilkinson	3M3-9							X			
14:15	2704-003	J & B Contractors	Ghost							X			
14:35	2705-000	Haizlip Ranch Lo	Ghost							X			
14:45	2706-000	Ben Hur Enterprises Ltd	6M3-11C				218428			X			
14:55	2706-000	Ben Hur Enterprises Ltd	8M3-11							X			
15:05	2706-000	Ben Hur Enterprises Ltd	4M3-1B							X			
15:25	2710-000	Robert and Lourdes Gilpin	6M3-12							X			
15:25	2710-000	Robert and Lourdes Gilpin	3M3-12A							X			
15:35	2782-007	Estate of Antonio R Sanchez	Ghost							X			
15:45	3997-000	Cityof Laredo	30M3-12B	9000	5199		32542.29			X	X		
15:45	3997-000	City of Laredo	30M3-12C							X			
15:45	3997-000	City of Laredo	30M3-12D							X			

Comments:

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/15/2022	Inspections:	45
Time Start:	8:45 AM	Measurement:	2
Time End:	4:10 PM	Doppler:	0
Inspec Time:	4.00	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:55	2812-001	Louis C Lechenger	Ghost							X			
9:55	0812-010	Fasken Ltd	6M2-8A							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	6M2-8D							X			
9:55	CP-12640	Silverbow Resources Operating LLC	8M2-8E&F							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	10M2-8H							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-13							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	10M2-8J							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-14							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-8G							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-15				2263910.7			x			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-16							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-17							X			
9:55	0812-010	Segundo Navarro Drilling Ltd	8M2-18							X			
10:20	3997-000	City of Laredo Colombia	4M2-8B							X			
10:20	3997-000	City of Laredo Colombia	4M2-8C							X			
10:35	2695-003	Needmore Ranch II Ltd	10M2-9							X			
10:35	2695-003	Needmore Ranch II Ltd	10M2-10							X			
10:35	2695-003	Needmore Ranch II Ltd	10M2-11							X			
10:55	0770-000	R & K Group LLC	2M2-12A							X			
10:55	2704-007	R & K Group LLC	4M2-12B							X			
11:15	2696-001	5D Inc	10M3-1				229792			X			
11:15	2696-001	5D Inc	10M3-2							X			
11:15	2696-001	5D Inc	3M3-2A							X			
11:35	2697-000	Mos Professional Bldg Inc	6M3-3A							X			
11:35	2697-001	Mos Professional Bldg Inc	3M3-3B							X			

Comments: Charged doppler for 30 min for field use  
Painted 8M2-8G,8M2-15, 8M2-16, 8M2-17, and 8M2-18

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:50	2698-000	GML Ranch LLC	8M3-4	1200	1000		2368.6504			X	X		2
11:50	2698-000	GML Ranch LLC	4M3-4A							X			
11:50	2774-005	City of Laredo	—							X			
12:40	2699-000	Jessland Properties Ltd	8M3-5							X			
12:40	2699-000	Jessland Properties Ltd	8M3-5A				797332			X			
13:10	2699-002	Laredo Sand & Gravel Co	Mining							X			
13:10	2700-002	Gary W Wilkinson	Ghost							X			
13:10	2700-003	CityReady Mic Inc	Ghost							X			
13:10	2703-000	Gary W Wilkinson	3M3-9							X			
13:20	2704-003	J & B Contractors	Ghost							X			
13:30	2705-000	Haizlip Ranch Lo	Ghost							X			
13:45	2706-000	Ben Hur Enterprises Ltd	6M3-11C				220468			X			
13:50	2706-000	Ben Hur Enterprises Ltd	8M3-11				1908			X			
14:05	2706-000	Ben Hur Enterprises Ltd	4M3-1B							X			
15:15	2710-000	Robert and Lourdes Gilpin	6M3-12							X			
15:15	2710-000	Robert and Lourdes Gilpin	3M3-12A							X			
15:15	2782-007	Estate of Antonio R Sanchez	Ghost							X			
15:35	3997-000	Cityof Laredo	30M3-12B	9000	5328		32555.363			X	X		
15:35	3997-000	City of Laredo	30M3-12C							X			
15:35	3997-000	City of Laredo	30M3-12D							X			

Comments: 8M3-4 and 4M3-4A unable to doppler

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Date:	2/16/2022	Inspections:	27
Time Start:	8:40 AM	Measurement:	3
Time End:	4:25 PM	Doppler:	2
Inspec Time:	4.00	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.00

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:50	2793-001	J Santiago Gutierrez	4M8-1B							X			
10:20	2788-000	The Guadalupe and Lilia Mtz Foundation	6M8-1C							X			
10:20	2791-001	Maria W Uribe	Mining							X			
10:20	2791-000	Maria W Uribe	6M8-1C							X			
10:20	2786-003	Lam Family Ranches Ltd	6M8-1C	350	400		621775			X	X		
10:35	2804-000	Zapata County Water Works	4M7-24							X			
10:35	2804-000	Zapata County Water Works	4M7-23							X			
10:50	2708-001	Joel Ruiz	Joel 3							X			
10:50	2808-001	Joel Ruiz	Joel 1							X			
11:10	2782-A/B00	M C Properties Partnership	6M62-2							X			1
11:10	2782-A/B00	M C Properties Partnership	Ghost							X			
11:20	2747-A/B03	M C Properties Partnership	Ghost							X			
11:35	2781-001	Fernando Gutierrez	Ghost							X			
11:50	2780-000	Wichita Partnership	12M7-14				576101			X			
12:05	2779-009	Lone Star La Perla LP	4M7-11A	425	400	409	815805			X	X		
12:30	2778-A/B00	Knapp Home Place Ltd	10M7-7B							X			1
14:10	2779-009	Lone Star La Perla LP	10M7-4	1500	1700	1676	565326			X	X		
14:35	2776-001	Martinez Quarter Horse Rnch Ltd	Ghost							X			
14:50	0339-002	Rufino Garza	6M6-17							X			
15:00	2775-014	Alfred Herbst	8M7-3							X			
15:00	2775-012	Mary Josephine H Garcia	8M7-3							X			
15:00	2775-011	Sandra H Parsons	8M7-3							X			
15:00	2775-010	Jennifer Herbst Vergara	8M7-3							X			
15:00	2775-008	Rosemarie A Geary	8M7-3							X			
15:00	2775-001	Edward J Herbst	8M7-3							X			

Comments: Charged the doppler instrument for 30 min : 6M62-2 painted, 10M7-7B painted

Specialist Signature  
*Araceli Thatcher*







**Texas Commission on Environmental Quality**  
**Rio Grande Watermaster**  
**Deputy's Daily Report**

Date: 2/22/2022      Inspections: 44  
Time Start: 10:45 AM      Measurement: 3  
Time End: 4:15 PM      Doppler: 1  
Inspection Time: 4.00      On-Site Notice: 0  
RN#: 106122732      Travel Time: 1.50

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:00	2743-001	David M Slaughter	6M4-23							X			
11:00	2743-000	Sheila Slaughter Glassford	6M4-23							X			
11:10	2742-000	Rodolfo Garcia	Ghost							X			
11:20	2742-001	Laredo Municipal Jr College	3M4-22							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-18	20000	10690		75466.43			X	X		
11:30	3997-000	City of Laredo - Jefferson	14M6-19							X			
11:30	3997-000	City of Laredo - Jefferson	20M4-20							X			
11:30	3997-000	City of Laredo - Jefferson	20M4-21							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21A							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21B							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21C							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21D							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21E							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21F							X			
11:30	3997-000	City of Laredo - Jefferson	16M4-21G							X			
11:45	2735-001	US Dept of Labor	Ghost							X			
12:00	2735-004	CityReady Mix Inc	6M4-15							X			
12:20	3997-000	City of Laredo - Del Mar	10M4-12							X			
12:20	3997-000	City of Laredo - Del Mar	8M4-13							X			
12:20	3997-000	City of Laredo - Del Mar	10M4-14							X			
12:20	3997-000	City of Laredo - Del Mar	6M4-15							X			
12:30	2727-000	Talen Texas Propery, LLC	6M4-10							X			
12:30	2727-000	Talen Texas Propery, LLC	6M4-9							X			
12:30	2727-000	Talen Texas Propery, LLC	10M4-8							X			
12:30	2727-000	Talen Texas Propery, LLC	10M4-7							X			

Comments: Picked up vehicle for repair shop and continued with route

Specialist Signature  
*Araceli Thatcher*



**Texas Commission on Environmental Quality  
Rio Grande Watermaster  
Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
12:40	2724-000	Rodolfo V Solis	Ghost							X			
12:50	2721-000	Killam Development Corp	Ghost							X			
12:50	2715-000	Mines Road Development	Ghost							X			
13:15	2714-000	Fasten Ltd	10M4-1							X			
13:15	2714-000	Fasten Ltd	10M4-2							X			
13:35	2713-A01	Albert F Muller Jr	8M3-15B	500	400	386	703472			X	X		
13:50	2713-A/B02	Roberto Muller, Ltd	6M3-15A				623779			X			
14:20	2712-A/B01	Emerald Riverview Devpmt	6M3-14							X			
14:20	2712-A/B00	Julia B Muller Ruhlman	6M3-14							X			
14:45	2711-000	Florence Arce	6M3-13							X			
14:45	2711-000	FlorenceArce	Ghost							X			
15:10	2422-012	Richard Haynes	2M3-13B							X			
15:10	2422-012	Richard Haynes	2M3-13C							X			
15:30	3997-000	City of Laredo	30M3-12B	9000	5966		32634.844			X	X		
15:30	3997-000	City of Laredo	30M3-12C							X			
15:30	3997-000	City of Laredo	30M3-12D							X			
15:45	2782-007	Estate of Antonio R Sanchez	Ghost							X			
15:45	2710-000	Roberto and Lourdes Gilpin	3M3-12A							X			
15:45	2710-000	Roberto and Lourdes Gilpin	6M3-12							X			

Comments:

Specialist Signature  
*Araceli Thatcher*