

WM MR_Rio Grande_RP_20230324_Monthly Report-athatcher
Texas Commission on Environmental Quality
Investigation Report

The TCEQ is committed to accessibility. If you need assistance in accessing this document, please contact oce@tceq.texas.gov

Customer: RGWM Insp Middle Reach IV San Antonio Xing
Laredo Bridge I
Customer Number: CN603837360

Regulated Entity Name: RGWM-INSP-MIDDLE REACH V- LAREDO BRIDGE
I- SAN YGNACIO

Regulated Entity Number: RN106122740

Investigation # 1887636

Investigator: ARACELI THATCHER

Incident Numbers

Site Classification CERTIFICATE OF
ADJUDICATION

Conducted: 03/01/2023 -- 03/23/2023

No Industry Code Assigned

Program(s): WATER RIGHTS

Investigation Type: Compliance Invest File Review

Location:

RN101509719,RN101484506,RN102887999,RN101483
717,RN102628799,
RN102973286,RN101482768,RN102741865,RN103081
246,RN103189239,
RN103898375,RN101510972,RN102825726,RN102888
039,RN101658540,
RN102641602,RN102972437,RN102073905,RN10390
5782,RN102820263, RN103021242,

Additional ID(s):

Address: ,

, ,

Local Unit: REGION 16 - LAREDO

Activity Type(s): WMDIVER - WM Diversion Site
Investigation - Rio Grande Only

Principal(s):

Role

Name

RESPONDENT
RESPONDENT
RESPONDENT

RGWM INSP MIDDLE REACH VI SAN YGNACIO FALCON
RGWM INSP MIDDLE REACH IV SAN ANTONIO XING L
RGWM INSP MIDDLE REACH V LAREDO BRIDGE I SAN

Contact(s):

Role

Title

Name

Phone

Other Staff Member(s):

Role

Name

QA Reviewer
Supervisor

DANIEL GUERRA
GEORGINA BERMEA

Associated Check List

Checklist Name

RIO GRANDE WATERMASTER INSPECTION
CHECKLIST

Unit Name

RGWM-CHK

Investigation Comments:

CCEDS INVESTIGATION No. 1887636

INTRODUCTION

Watermaster Specialist, Araceli Thatcher, of the Texas Commission on Environmental Quality (TCEQ), Rio Grande Watermaster Program, conducted water right site investigations and monitored surface water use along the Rio Grande River and its tributaries. These field investigations were conducted during the period of March 1 thru March 23, 2023 ; and included water right holders /diverters within the following reaches of the Rio Grande.

Middle Rio Grande Reach's (MR) have been broken down as follows:

MR I between Amistad Dam and Del Rio International Bridge - RN106122690

MR II between Del Rio Int'l Bridge and the Eagle Pass Int'l Bridge - RN106122716

MR III between the Eagle Pass Int'l Bridge and San Antonio Crossing - RN106122724

MR IV between the San Antonio Crossing (Xing) and Laredo Int'l Bridge - RN106122732

MR V between the Laredo International Bridge and San Ygnacio - RN106122740

MR VI between the San Ygnacio to Falcon Dam - RN106122757

Middle Rio Grande Tributaries (MT) have been broken down as follows:

MT - Cienegas and San Felipe creeks - RN106122765

MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado, and Rosita creeks - RN106122807

MT - San Ambrosia, Manadas, Lake Casa Blanca, Becerro, Nopalosa and Javalina creeks - RN106123060

GENERAL ENTITY AND PROCESS INFORMATION

The following entities referred to in this investigation were surveyed and/or monitored during the field investigations. The entities are described by the following standard industrial classification (SIC) codes: 721 for crop planting, cultivating, and/or protecting, 1381 for oil and gas exploration activities, and/or 4941 for water supply entities.

A detailed description of each regulated entity with its associated water right account information can be found in the TCEQ Rio Grande Watermaster files, including specific SIC codes and associated water right information.

Water right accounts and or diverters in the following reaches or segments:

MR I-Amistad Dam to Del Rio Bridge,

MR II-Del Rio Bridge to Eagle Pass Bridge,

MR III-Eagle Pass Bridge to San Antonio Crossing,

MR IV-San Antonio Crossing and the Laredo Bridge,

MR V-Laredo Bridge to San Ygnacio, MR V- Laredo Bridge to San Ygnacio,

MR VI- San Ygnacio to Falcon Dam,

MT - Cienegas and San Felipe creeks,

MT - Mud, Pinto, Elm, Las Moras, Canyon Grande, Quemado, and Rosita creeks,

MT - San Ambrosia, Manadas, Becerra, Nopalosa, and Javalina creeks

BACKGROUND

The TCEQ Rio Grande Watermaster Program routinely conducts investigations along the Rio Grande River and/or its Tributaries to ensure compliance with applicable State rules and regulations related to the watermaster program and to the diversion and use of State waters.

ADDITIONAL INFORMATION:

3/1/2023 to 3/23/2023 Inv. # - 1887636

Page 3 of 3

During the course of these investigations, the Watermaster Specialist performed watermaster-related activities that may have included but were not limited to the following:

679 Inspections
13 Measurements
4 Doppler Checks
0 On-Site Notices

Please refer to the attached investigation notes (Attachment A: Deputy's Daily Report) for the specific observations of these investigation sites.

No Violations Associated to this Investigation

Signed

*Araceli Thatcher*Date 03/31/2023**Environmental Investigator**

Signed

Date 03/31/2023**Supervisor****Attachments: (in order of final report submittal)**☐ Enforcement Action Request (EAR)☐ Maps, Plans, Sketches☐ Letter to Facility (specify type) : _____☐ Photographs☐ Investigation Report☐ Correspondence from the facility☐ Sample Analysis Results☒ Other (specify) :☐ ManifestsAttachment A: Deputy's Daily Report☐ Notice of Registration

**TEXAS COMMISSION ON ENVIRONMENTAL
QUALITY**



ATTACHMENT A

Regulated Entity No.	RN106122690 RN106122716 RN106122724 RN106122732 RN106122740 RN106122757	Regulated Entity	Middle Reaches I, II, III, IV, V, VI	County Name WEBB Zapata	WEBB AND ZAPATA
Investigation Date	03/1/2023 to 03/23/2023	TCEQ Investigator(s):	Araceli Thatcher		

Deputy Daily Report

03/01/2023, 03/07/2023, 03/8/2023, 03/9/2023, 03/10/2023, 03/13/2023,03/14/2023,
03/15/2023, 03/16/2023, 03/20/2023, 03/21/2023, 03/22/2023, 03/23/2023



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date:	3/1/2023	Inspections:	49
Time Start:	8:25 AM	Measurement:	2
Time End:	12:00 AM	Doppler:	1
Inspec Time:	5.00	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:45	2788-000	The Guadalupe & Lilia Mtz	6M8-1C							X			
9:45	2791-001	Maria E Uribe Ramirez	Mining							X			
9:45	2791-000	Maria E Uribe Ramirez	6M8-1C							X			
9:45	2786-003	Lam Family Ranchers Ltd	6M8-1C							X			
9:45	2787-000	Oscar O Lopez (T-7)	Ghost							X			
9:55	2804-000	Zapata County Water Works	4M7-23	350	300		37107			X	X		
9:55	2804-000	Zapata County Water Works	4M7-24							X			
10:08	2708-001	Joel Ruiz	Joel 1							X			
10:13	2708-001	Joel Ruiz	Joel 2							X			
10:13	2708-001	Joel Ruiz	Joel 3							X			
10:13	2422-008	Hachar Real Estate	Ghost							X			
10:13	2782-A/B00	M C Properties Partnership	6M62-2							X			
10:13	2782-A/B00	M C Properties Partnership	Ghost							X			
10:13	2784-000	Delfina Lozano Jr (T-7)	Ghost							X			
10:13	2783-001	HugoA Gutierrez Jr (T-7)	Ghost							X			
10:13	2747-A/B03	Barry Gilpin (T-7)	Ghost							X			
10:13	2747-A/B03	Select Energy (T-7)	Ghost							X			
10:13	2782-A/B00	M C Properties Partnership (T-7)	Ghost							X			
10:20	2781-001	Fernando Gutierrez (T-7)	Ghost							X			
10:35	2780-000	Wichita Partnership	12M7-14							X			
10:35	2780-000	Wichita Partnership	Mining							X			
10:50	2779-009	Lone Star La Perla LP	4M7-11A				985087			X			
10:50	2779-002	Larry G Hancock	2M7-11							X			
10:50	2779-001	Larry G Hancock	Mining							X			
11:05	2778-A/B00	Knapp Home Place Ltd	10M7-7B	2100	1800	1671	471979			X	X		

Comments:

Rev: 3/31/22

Page 1 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:30	2777-001	Fender Exploration & Product Co (T-7)	Ghost							X			
11:30	2777-001	Fender Exploration & Product Co	Mining							X			
11:45	2779-009	Lone Star La Perla LP	10M7-4							X			
11:45	2776-003	ATM 2005 LLC	10M7-4							X			
12:05	2776-001	Martinez Quarter Horse Rnch Ltd (T-7)	Ghost							X			
12:25	0339-002	Rufino Garza	6M6-17							X			
12:35	2775-014	Alfred J Herbst	8M7-3							X			
12:35	2775-012	Mary Josephine H Garcia	8M7-3							X			
12:35	2775-011	Sandra H Parsons	8M7-3							X			
12:35	2775-010	Jennifer Herbst Vergara	8M7-3							X			
12:35	2775-008	Rosemarie A Geary	8M7-3							X			
12:35	2775-001	Edward J Herst	8M7-3							X			
12:55	2775-004	Gerardo Vidaurri	4M7-1B							X			
12:55	2775-000	Mauricio A Vidaurri	4M7-1							X			
14:10	2774-003	Ana Alicia Peña Becerra	6M6-18							X			
14:10	2774-002	Zimmerman LP No 1	6M6-18							X			
14:10	2774-001	J E Briones	6M6-18							X			
14:25	2773-000	2MB Land and Cattle LLC	6M6-16							X			
14:45	2704-002	James Haynes Jr	8M6-15							X			
14:45	2704-002	James Haynes Jr	4M6-14							X			
15:15	2772-A/B01	Rancho Blanco LLC Becerro Creek	Mining							X			
15:15	2772-A/B01	Rancho Blanco LLC Becerro Creek	10BC-3							X			
15:25	2772-A/B01	Rancho Blanco LLC	12M6-12							X			3
15:40	2772-A/B01	Rancho Blanco LLC	12M6-11							X			

Comments:

Rev: 3/31/22

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/7/2023

Inspections: 50

Time Start: 10:00 AM

Measurement: 1

Time End: 4:20 PM

Doppler: 1

Inspec Time: 3.00

On-Site Notice: 0

RN#: 106122757

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:55	0346-001	Siesta Shores WCID	6M10-6C				185158			X			
10:55	0461-005	Siesta Shores WCID	6M10-6B							X			
11:00	DF-75	Dan A Richter	—							X			
11:00	2426-002	Donald L Hayes	1M10-6							X			
11:01	2430-000	Wayne Pierce	1M10-5							X			
11:08	2806-000	DavidG Delore (T-10)	Ghost							X			
11:12	2810-000	Juan Antonio and Rosa Maria Guevara (T-10)	Ghost							X			
11:16	2809-000	David G Delorme Bass Lake RV (T-10)	Ghost							X			
11:19	2422-003	Christine McKee (T-10)	Ghost							X			
11:22	2725-001	Cyrus B Reynolds	2M9-27							X			
11:26	2422-002	Lynn D Smith (T-9)	Ghost							X			
11:35	2426-001	Lendol C Baker	1M9-25							X			
11:37	2421-002	J E Bravo (T-9)	Ghost							X			
11:39	2804-002	John A Nixon	1M9-22A							X			
11:39	2804-002	Elena F Strokes	1M9-22A							X			
11:50	2804-000	Zapata Co Water Works	16M9-21C	1650	1951		1344.427			X	X		
11:50	2804-000	Zapata Co Water Works	16M9-21D							X			
11:50	2804-000	Zapata Co Water Works	16M9-21E							X			
13:10	DF-14	J R Terrell	—							X			
13:10	DF-34	J H Kuykendall	—							X			
13:10	DF-45	W I Hammond	—							X			
13:11	2801-000	Jose Luis Garza	1M9-20							X			
13:14	DF-61	B D Love	—							X			
13:16	DF-20	J E Fields	—							X			
13:17	2425-001	Gaylen Gilbreath	1M9-19A							X			

Comments:

Rev: 3/1/2023

Page

1

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
13:17	2424-001	Albert and Frances Muehsam	1M9-17							X			
13:17	2428-000	A C Durivage	1M9-16							X			
13:17	2423-000	Albert Long	1M9-15							X			
13:18	DF-56	R E Lee	—							X			
13:22	2803-000	Shady Have LLC (T-9)	Ghost							X			
13:30	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
13:38	2429-001	Straud B Jacobs	1M9-11							X			
13:42	2432-001	Theodore C Miller (T-9)	Ghost							X			
13:43	2431-001	Troy D Weldon	1M9-7C							X			
13:43	2435-009	Javier Reyes	1M9-7B							X			
13:43	DF-58	M L Cave	—							X			
13:43	2435-010	M L Cave	1M9-7A							X			
13:45	2435-007	Frederick J Kilian	1M9-6							X			
13:45	2435-002	Rock H Wilkinson	1M9-5							X			
13:55	DF-57	R N Bledsoe	—							X			
13:55	DF-70	L W Daiker	—							X			
14:00	2804-000	Zapata Co WW (T-9)	Ghost							X			
14:02	2718-001	Barton E Anderson (T-9)	Ghost							X			
14:02	2718-000	Gerald A Bader	1M9-3							X			
14:03	2433-000	C.E. And Evelyn Deyo	1M9-2							X			
14:25	2800-000	Jose F Gutierrez (T-8)	Ghost							X			
14:45	DF-67	Steve Lillard (T-8)	Ghost							X			
15:10	2708-001	Joel Ruiz	Joel 3	50	54	36	4906			X	X		
15:40	2708-001	Joel Ruiz	Joel 2							X			
13:40	2708-001	Joel Ruiz	Joel 1							X			



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/8/2023

Inspections: 64

Time Start: 8:20 AM

Measurement: 1

Time End: 4:27 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122757

Travel Time: 3.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:45	3132-000	IBWC	GM10-20	200	0		57675950.3			X			
11:00	0068-006	White Oak Resources	3M10-18							X			
11:00	0068-000	White Oak Resources	3M10-18A							X			
11:15	2807-000	James W Wolfe (T-10)	Ghost							X			
11:25	DF-76	AF & JF Martin	-							X			
11:40	2747-001	Union Pacific Oil & Gas Co	2M10-14							X			
11:50	DF-74	Clarence Holt	-							X			
11:55	2435-008	JD Gutierrez Jr Family LTD	1M10-12							X			
12:00	DF-4	B C Williams	-							X			
12:05	DF-48	H W Harrington Jr	-							X			
12:10	0248-006	Mary Jane Cox Green	3M10-11B							X			
12:15	DF-53	J C Brown	-							X			
12:20	DF-50DF-35	W A Krauss	-							X			
12:22	DF-77	D E Woodruff	-							X			
12:25	2422-005	Jamie Bray	-							X			
12:30	2658-000	The Estate of Rebecca A Gonzalez (T-10)	Ghost							X			
12:50	2421-A/B03	Adan Volpe (T-10)	Ghost							X			
12:50	2421-A/B03	AdanVolpe	6M10-10A							X			
13:05	0346-001	Siesta Shores WCID	6M10-6C				185158			X			
13:05	0461-005	Siesta Shores WCID	6M10-6B							X			
13:07	DF-75	Dan A Richter	—							X			
13:07	2426-002	Donald L Hayes	1M10-6							X			
13:08	2430-000	Wayne Pierce	1M10-5							X			
13:12	2806-000	DavidG Delore (T-10)	Ghost							X			
13:15	2810-000	Juan Antonio and Rosa Maria Guevara (T-10)	Ghost							X			

Comments: 3132-000 reported to admin, certified to pump intermittently

Rev: 3/1/2023

Page 1 of 3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
13:18	2809-000	David G Delorme Bass Lake RV (T-10)	Ghost							X			
13:20	2422-003	Christine McKee (T-10)	Ghost							X			
13:25	2725-001	Cyrus B Reynolds	2M9-27							X			
13:30	2422-002	Lynn D Smith (T-9)	Ghost							X			
13:35	2426-001	Lendol C Baker	1M9-25							X			
13:37	2421-002	J E Bravo (T-9)	Ghost							X			
13:40	2804-002	John A Nixon	1M9-22A							X			
13:40	2804-002	Elena F Strokes	1M9-22A							X			
13:55	2804-000	Zapata Co Water Works	16M9-21C	1500	1951		1347.209			X	X		
13:55	2804-000	Zapata Co Water Works	16M9-21D							X			
13:55	2804-000	Zapata Co Water Works	16M9-21E							X			
14:20	DF-14	J R Terrell	—							X			
14:20	DF-34	J H Kuykendall	—							X			
14:20	DF-45	W I Hammond	—							X			
14:22	2801-000	Jose Luis Garza	1M9-20							X			
14:26	DF-61	B D Love	—							X			
14:30	DF-20	J E Fields	—							X			
14:32	2425-001	Gaylen Gilbreath	1M9-19A							X			
14:33	2424-001	Albert and Frances Muehsam	1M9-17							X			
14:33	2428-000	A C Durivage	1M9-16							X			
14:33	2423-000	Albert Long	1M9-15							X			
14:34	DF-56	R E Lee	—							X			
14:40	2803-000	Shady Have LLC (T-9)	Ghost							X			
14:45	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
14:57	2429-001	Straud B Jacobs	1M9-11							X			

Comments:

Rev: 3/1/2023

Page

2

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date:	3/9/2023	Inspections:	57
Time Start:	8:20 AM	Measurement:	0
Time End:	4:10 PM	Doppler:	0
Inspection Time:	5.00	On-Site Notice:	0
RN#:	106122740	Travel Time:	2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:35	2708-001	Joel Ruiz (T-8)	Ghost							X			
9:45	MP	MP (Size Unknown Not Operating)	MP-UNK							X			5
9:45	MP	MP (Size Unknown Not Operating)	MP-UNK							X			5
9:45	MP	MP (Size Unknown Not Operating)	MP-UNK							X			5
9:45	2799-000	Amanda Rash (T-8)	Ghost							X			
9:45	2799-001	La Roca Real Inc (T-8)	Ghost							X			
9:45	2799-000	Amanda Rash (T-8)	Ghost							X			
10:10	DF-67	Steve Lillard (T-8)	Ghost							X			
10:25	2800-000	Jose F Gutierrez (T-8)	Ghost							X			
10:50	2433-000	C.E. And Evelyn Deyo	1M9-2							X			
10:50	2718-000	Gerald A Bader	1M9-3							X			
10:51	2718-001	Barton E Anderson (T-9)	Ghost							X			
10:53	2804-000	Zapata Co WW (T-9)	Ghost							X			
10:56	DF-70	L W Daiker	—							X			
10:56	DF-57	R N Bledsoe	—							X			
11:11	2435-002	Rock H Wilkinson	1M9-5							X			
11:11	2435-007	Frederick J Kilian	1M9-6							X			
11:12	2435-010	M L Cave	1M9-7A							X			
11:12	DF-58	M L Cave	—							X			
11:12	2435-009	Javier Reyes	1M9-7B							X			
11:12	2431-001	Troy D Weldon	1M9-7C							X			
11:13	2432-001	Theodore C Miller (T-9)	Ghost							X			
11:22	2429-001	Straud B Jacobs	1M9-11							X			
11:28	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
11:35	2803-000	Shady Have LLC (T-9)	Ghost							X			

Comments:		Page	1	of	3	Specialist Signature



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:40	DF-56	R E Lee	—							X			
11:40	2423-000	Albert Long	1M9-15							X			
11:40	2428-000	A C Durivage	1M9-16							X			
11:41	2424-001	Albert and Frances Muehsam	1M9-17							X			
11:41	2425-001	Gaylen Gilbreath	1M9-19A							X			
11:41	DF-20	J E Fields	—							X			
11:42	DF-61	B D Love	—							X			
11:43	2801-000	Jose Luis Garza	1M9-20							X			
11:43	DF-45	W I Hammond	—							X			
11:43	DF-34	J H Kuykendall	—							X			
11:43	DF-14	J R Terrell	—							X			
11:55	2804-000	Zapata Co Water Works	16M9-21C	1650	0		1349.356			X			
11:55	2804-000	Zapata Co Water Works	16M9-21D							X			
11:55	2804-000	Zapata Co Water Works	16M9-21E							X			
12:00	2804-002	John A Nixon	1M9-22A							X			
12:00	2804-001	Elena Strokes	1M9-22A							X			
13:20	2421-002	J E Bravo (T-9)	Ghost							X			
13:21	2425-001	Lendol C Baker	1M9-25							X			
13:22	2422-002	Lynn D Smith (T-9)	Ghost							X			
13:28	2725-001	Cyrus B Reynolds	2M9-27							X			
13:32	2422-003	Christine McKee (T-10)	Ghost							X			
13:34	2809-000	David G Delmore (T-10)	Ghost							X			
13:37	2810-000	Jose A Rosa Ma Guevara (T-10)	Ghost							X			
13:40	2808-000	David G Delmore (T-10)	Ghost							X			
13:45	2430-000	Wayne Pierce	1M10-5							X			



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

[illegible]

Rev: 3/1/2023

Page 3 of 3

Specialist Signature

Anaceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/10/2023

Inspections: 47

Time Start: 8:25 AM

Measurement: 1

Time End: 4:00 PM

Doppler: 0

Inspection Time: 4.00

On-Site Notice: 0

RN#: 106122757

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:15	2421-A/B03	Adan Volpe (T-10)	Ghost							X			
10:15	2421-A/B03	AdanVolpe	6M10-10A							X			
10:35	0346-001	Siesta Shores WCID	6M10-6C							X			
10:35	0461-005	Siesta Shores WCID	6M10-6B							X			
10:40	DF-75	Dan A Richter	—							X			
10:40	2426-002	Donald L Hayes	1M10-6							X			
10:41	2430-000	Wayne Pierce	1M10-5							X			
10:46	2806-000	DavidG Delore (T-10)	Ghost							X			
10:48	2810-000	Juan Antonio and Rosa Maria Guevara (T-10)	Ghost							X			
10:51	2809-000	David G Delorme Bass Lake RV (T-10)	Ghost							X			
10:53	2422-003	Christine McKee (T-10)	Ghost							X			
10:58	2725-001	Cyrus B Reynolds	2M9-27							X			
11:02	2422-002	Lynn D Smith (T-9)	Ghost							X			
11:04	2426-001	Lendol C Baker	1M9-25							X			
11:05	2421-002	J E Bravo (T-9)	Ghost							X			
11:20	2804-002	John A Nixon	1M9-22A							X			
11:20	2804-002	Elena F Strokes	1M9-22A							X			
11:35	2804-000	Zapata Co Water Works	16M9-21C	1650	1847		1351.818			X	X		
11:35	2804-000	Zapata Co Water Works	16M9-21D							X			
11:35	2804-000	Zapata Co Water Works	16M9-21E							X			
11:50	DF-14	J R Terrell	—							X			
11:50	DF-34	J H Kuykendall	—							X			
11:50	DF-45	W I Hammond	—							X			
11:51	2801-000	Jose Luis Garza	1M9-20							X			
11:54	DF-61	B D Love	—							X			

Comments:

Rev: 3/1/2023

Page

1

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:56	DF-20	J E Fields	—							X			
11:56	2425-001	Gaylen Gilbreath	1M9-19A							X			
11:56	2424-001	Albert and Frances Muehsam	1M9-17							X			
11:57	2428-000	A C Durivage	1M9-16							X			
11:57	2423-000	Albert Long	1M9-15							X			
11:58	DF-56	R E Lee	—							X			
13:13	2803-000	Shady Have LLC (T-9)	Ghost							X			
13:18	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
13:21	2429-001	Straud B Jacobs	1M9-11							X			
14:35	2432-001	Theodore C Miller (T-9)	Ghost							X			
14:35	2431-001	Troy D Weldon	1M9-7C							X			
14:36	2435-009	Javier Reyes	1M9-7B							X			
14:36	DF-58	M L Cave	—							X			
14:36	2435-010	M L Cave	1M9-7A							X			
14:37	2435-007	Frederick J Kilian	1M9-6							X			
14:37	2435-002	Rock H Wilkinson	1M9-5							X			
14:44	DF-57	R N Bledsoe	—							X			
14:44	DF-70	L W Daiker	—							X			
14:47	2804-000	Zapata Co WW (T-9)	Ghost							X			
14:50	2718-001	Barton E Anderson (T-9)	Ghost							X			
14:50	2718-000	Gerald A Bader	1M9-3							X			
14:50	2433-000	C.E. And Evelyn Deyo	1M9-2							X			

Comments:

Rev: 3/1/2023

Page

2

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/13/2023

Inspections: 48

Time Start: 8:50 AM

Measurement: 0

Time End: 3:55 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122740

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:20	2788-000	The Guadalupe Martinez & Linda Martinez foundation	6M8-1C							X			
10:20	2791-001	Maria E Uribe Ramirez	Mining							X			
10:20	2786-003	Lam Family Ranches Ltd	6M8-1C							X			
10:20	2786-001	El Campo Farms Co	Mining							X			
10:20	2787-000	Oscar O Lopez (T-8)	Ghost							X			
10:30	2804-000	Zapata County Water Works	4M7-23	350	0		39132			X			
10:30	2804-000	Zapata County Water Works	4M7-24							X			
10:40	2708-001	Joel Ruiz	Joel 1							X			
10:45	2708-001	Joel Ruiz	Joel 2							X			
10:45	2708-001	Joel Ruiz	Joel 3							X			
10:45	2422-008	Hachar Real Estate (T-7)	Ghost							X			
10:45	2782-A/B00	M C Properties Partnership	6M62-2							X			
10:45	2782-A/B00	M C Properties Partnership (T-7)	Ghost							X			
10:45	2784-000	Delfina Lozano Jr (T-7)	Ghost							X			
10:45	2783-001	HugoA Gutierrez Jr (T-7)	Ghost							X			
10:45	2747-A/B03	Barry Gilpin (T-7)	Ghost							X			
10:45	2747-A/B03	Select Energy (T-7)	Ghost							X			
10:45	2782-A/B00	M C Properties Partnership (T-7)	Ghost							X			
11:00	2781-001	Fernando Gutierrez (T-7)	Ghost							X			
11:10	0884-000	Tx Dot Temp (T-7)	Ghost							X			
11:20	0487-001	Antonio R Sanchez (T-7)	Ghost							X			
11:30	2780-000	Wichita Partnership	12M7-14							X			
11:30	2780-000	Wichita Partnership	Mining							X			
11:40	2779-009	Lone Star La Perla LP	4M7-11A							X			
11:40	2779-002	Larry G Hancock	2M7-11							X			

Comments: 2804-000 reported to admin, certified to pump intermittently

Rev: 3/1/2023

Page 1 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:40	2779-001	Larry G Hancock	Mining							X			
11:50	2778-A/B00	Knapp Home Place Ltd	10M7-7B							X			
11:50	2778-A/B00	Knapp Home Place Ltd	10M7-7C							X			
11:45	2777-000	Fender Exploration & Product Co (T-7)	Ghost							X			
11:45	2777-001	Fender Exploration & Product Co	Mining							X			
11:50	2779-009	Lone Star La Perla LP	10M7-4							X			
11:50	2776-003	ATM 2005 LLC	10M7-4							X			
12:05	2776-001	Martinez Quarter Horse Rnch Ltd (T-7)	Ghost							X			
13:20	0339-002	Rufino Garza	6M6-17							X			
13:45	2775-014	Alfred J Herbst	8M7-3							X			
13:45	2775-012	Mary Josephine H Garcia	8M7-3							X			
13:45	2775-011	Sandra H Parsons	8M7-3							X			
13:45	2775-010	Jennifer Herbst Vergara	8M7-3							X			
13:45	2775-008	Rosemarie A Geary	8M7-3							X			
13:45	2775-001	Edward J Herst	8M7-3							X			
14:10	2775-004	Gerardo Vidaurri	4M7-1B							X			
14:10	2775-000	Mauricio A Vidaurri	4M7-1							X			
14:35	2774-000	J E Briones	6M6-18							X			
14:35	2774-003	Ana Alicia Peña Becerra	6M6-18							X			
14:35	2774-002	Zimmerman LP No 1	6M6-18							X			
14:55	2773-000	2MB Land and Cattle LLC	6M6-16							X			
15:15	2704-002	James Haynes Jr	8M6-15							X			
15:15	2704-002	James Haynes Jr	4M6-14							X			

Comments:

Rev: 3/1/2023

Page 2 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/14/2023

Inspections: 55

Time Start: 8:25 AM

Measurement: 2

Time End: 2:00 PM

Doppler: 1

Inspection Time: 4.00

On-Site Notice: 0

RN#: 106122740

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:15	2772-A/B01	Rancho Blanco LLC Becerro Creek	Mining							X			
9:15	2772-A/B01	Rancho Blanco LLC Becerro Creek	10BC-3							X			
9:22	2772-A/B01	Rancho Blanco LLC	12M6-12							X			
9:27	2772-A/B01	Rancho Blanco LLC	12M6-11							X			
9:40	2768-000	Lasker O'Keefe Hereford	12M6-6							X			
9:55	2763-000	Compass Bank, Trustee	10M6-2A							X			
9:55	2763-000	Compass Bank, Trustee (T-6)	Ghost							X			
10:10	2771-000	Agustin Vela (T-6)	Ghost							X			
10:20	2720-002	Webb County(Utilities Dpt)	6M6-1B				356946752			X			
10:20	2720-002	Webb County(Utilities Dpt)	6M6-1C							X			
10:20	2720-002	Webb County(Utilities Dpt)	6M6-1D							X			
10:20	2720-001	Webb County(Utilities Dpt)	3M6-1							X			
10:20	2720-001	Webb County(Utilities Dpt)	3M6-1A							X			
10:30	2759-000	Carlos Y Benavides (T-5)	Ghost							X			
10:40	2761-000	William McKendrick (T-5)	Ghost							X			
10:40	2761-001	William McKendrick (T-5)	Ghost							X			
10:45	2759-000	Carlos Y Benavides (T-5)	Ghost							X			
10:50	2721-000	Killam Development Ltd	3M-Temp							X			
10:50	2759-001	Killam Development Ltd	3M-Temp							X			
10:52	2759-000	Carlos Y Benavides	8M5-13							X			
10:53	2759-001	Winfield Ltd	8M5-13							X			
11:05	2758-000	Antonio C Lopez	6M5-12							X			
11:05	2758-000	Antonio C Lopez (T-5)	Ghost							X			
11:08	2758-000	Antonio C Lopez	3M5-12A	500	350	277	522300			X	X		
11:25	2757-000	Horacio Acevedo	6M5-11							X			

Comments:

Rev: 3/1/2023

Page

1

of

3

Specialist Signature

Araceli Thatcher



**Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report**

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:25	2757-000	Javier Acevedo	6M5-11							X			
11:30	2756-000	Micheal MacMahon	4M5-10							X			
11:30	2756-000	Micheal MacMahon	4M5-10M							X			
11:30	2756-000	Micheal MacMahon	Minning							X			
11:40	2754-000	Martha Cadena (T-5)	Ghost							X			
11:50	2753-001	Porfirio Hernandez	4M5-8							X			
11:50	2753-000	Angelita Hernandez	4M5-8							X			
12:00	2812-000	Sherry R Lewis	5M5-7							X			
12:15	2751-000	HAPO Holdings LLC (T-5)	Ghost							X			
12:15	2751-000	J C Trevino (T-5)	Ghost							X			
12:15	2751-000	J C Trevino Jr (T-5)	Ghost							X			
12:25	2751-000	City of Laredo (T-5)	Ghost							X			
12:35	2748-000	F J Richter Farms Partners	6M5-3							X			
12:50	2746-000	Sacred Heart Children's Home	6M5-1							X			
13:05	2743-001	David M Slaughter	6M4-23							X			
13:05	2743-000	Sheila Slaughter Glassford	6M4-23							X			
13:15	2742-000	Rodolfo Garcia (T-4)	Ghost							X			
13:25	2742-001	Laredo Municipal Jr College	3M4-22							X			
13:30	3997-000	City of Laredo - Jefferson	16M4-18	20000	18751		73227.406			X	X		
13:30	3997-000	City of Laredo - Jefferson	14M6-19							X			
13:30	3997-000	City of Laredo - Jefferson	20M4-20							X			
13:30	3997-000	City of Laredo - Jefferson	20M4-21							X			
13:30	3997-000	City of Laredo - Jefferson	16M4-21A							X			
13:30	3997-000	City of Laredo - Jefferson	16M4-21B							X			
13:30	3997-000	City of Laredo - Jefferson	16M4-21C							X			

Comments:

Rev: 3/1/2023

Page

2

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/15/2023

Inspections: 54

Time Start: 8:25 AM

Measurement: 1

Time End: 3:57 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122732

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
8:45	2735-004	City Ready Mix Inc	6M4-15	600	0		683184			X			
8:55	3997-000	City of Laredo - Del Mar	10M4-12							X			
8:55	3997-000	City of Laredo - Del Mar	8M4-13							X			
8:55	3997-000	City of Laredo - Del Mar	10M4-14							X			
9:00	2727-000	Talen Texas Propery, LLC	6M4-10							X			
9:00	2727-000	Talen Texas Propery, LLC	6M4-9							X			
9:00	2727-000	Talen Texas Propery, LLC	10M4-8							X			
9:00	2727-000	Talen Texas Propery, LLC	10M4-7							X			
9:20	2724-000	Rodolfo V Solis (T-4)	Ghost							X			
9:25	2715-000	Mines Road Development (T-4)	Ghost							X			
9:25	2721-000	Killam Development Corp (T-4)	Ghost							X			
9:35	2714-000	Fasken Ltd	10M4-2	2000	0		394979140			X			
9:35	2714-000	Fasken Ltd	10M4-1							X			
10:00	2713-A01	Albert F Muller	8M3-15B							X			
10:10	2713-A/B02	Roberto Muller Ltd	6M3-15A							X			
10:20	2712-A/B01	Emerald Riverview Development	6M3-14							X			
10:20	2712-A/B00	Julia B Mukker Ruhlman	—							X			
10:50	2422-012	Richard Haynes	2M3-13B							X			
10:50	2422-012	Richard Haynes	2M3-13C							X			
11:15	2711-000	Florence Arce (T-3)	Ghost							X			
11:15	2711-000	Florence Arce	6M3-13							X			
11:30	3997-000	City of Laredo	30M3-12B	8500	9708		37220.674			X	X		
11:30	3997-000	City of Laredo	30M3-12C							X			
11:30	3997-000	City of Laredo	30M3-12D							X			
11:45	2782-007	Estate of Antonio Sanchez (T-3)	Ghost							X			

Comments:

2735-004 & 2714-000 reported to admin, certified to pump intermittently

Rev: 3/1/2023

Page

1

of

2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:45	2710-000	Robert J and Lourdes Gilpin	6M3-12							X			
11:45	2710-000	Robert J and Lourdes Gilpin	3M3-12A							X			
12:05	2695-003	Needmore Ranch II Ltd/Headington Energy Partners	10M2-14							X			
12:05	2695-003	Needmore Ranch II Ltd/Headington Energy Partners (T-3)	Ghost							X			
12:20	2706-000	Ben Hur Enterprises Ltd	8M3-11							X			
12:27	2706-000	Ben Hur Enterprises Ltd	4M3-11B							X			
12:31	2706-000	Ben Hur Enterprises Ltd	6M3-11C-M1	600	0		403146			X			
12:35	2706-000	Ben Hur Enterprises Ltd	6M3-11C-M2				170858			X			
12:50	2705-000	Haizlip Ranch LP (T-3)	Ghost							X			
12:50	2704-003	J & B Contractors (T-3)	Ghost							X			
12:50	2703-000	Gary W Wilkinson	3M3-9							X			
12:50	2700-006	Douglas M Brice	Mining							X			
12:50	2700-006	Douglas M Brice (T-3)	Ghost							X			
12:50	2700-003	City Ready Mix (T-3)	Ghost							X			
12:50	2700-002	Gary Wilkinson (T-3)	Ghost							X			
14:25	2742-000	Rodolfo Garcia	Mining							X			
14:25	2699-002	Laredo Sand & Gravel Co	Mining							X			
14:25	2699-000	Jessland Properties Ltd/Lewis Energy Group	8M2-15							X			
14:25	2699-000	Jessland Properties Ltd	8M3-5							X			
14:25	2699-000	Jessland Properties Ltd	8M3-5A							X			
14:55	2774-005	City of Laredo	—							X			
14:55	2698-000	GML Rancho LLC	4M3-4A							X			
14:55	2698-000	GML Rancho LLC	8M3-4							X			
15:20	0812-010	Segundo Navarro / Lewis Energy	5M3-20							X			
15:20	0812-010	Segundo Navarro / Lewis Energy	5M3-22							X			

Comments: 2706-000 reported to admin, certified to pump intermittently

Rev: 3/1/2023

Page 2 of 3

Specialist Signature

Araceli Thatcher



On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

[illegible]

Rev: 3/1/2023

Page

3

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date:	3/16/2023	Inspections:	47
Time Start:	8:30 AM	Measurement:	0
Time End:	3:30 PM	Doppler:	0
Inspec Time:	4.00	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:55	2697-000	Barry Gilpin / Hydroline	10M2-26							X			1&3
10:35	2696-001	5D Inc	3M3-2A							X			
10:35	2696-001	5D Inc	10M3-2							X			
10:35	2696-001	5D Inc	10M3-1							X			
10:50	0770-000	R & K Group LLC	2M2-12A							X			
10:50	2704-007	R & K Group LLC	4M2-12B							X			
10:50	T-4	MP-4 (Not Operating)	MP-4							X			5
11:15	2696-003	Needmore Ranch II, Ltd/Hydroline	8M3-19							X			
11:15	2696-003	Needmore Ranch II, Ltd	10M2-9							X			
11:15	2695-003	Needmore Ranch II, Ltd	10M2-10							X			
11:15	2695-003	Needmore Ranch II, Ltd	10M2-11							X			
11:15	2696-003	Laredo Select Energy	10M2-12							X			
11:15	2696-003	Laredo Select Energy	10M2-13							X			
11:15	2696-003	Laredo Select Energy	10M2-14							X			
11:15	2696-003	Needmore Ranch II, Ltd/Headington	12M2-26							X			
11:15	2696-003	Needmore Ranch II, Ltd/Hydroline	12M2-44							X			
11:30	3997-000	City of Laredo -Colombia	4M2-8B							X			
11:30	3997-000	City of Laredo -Colombia	4M2-8C							X			
13:35	2812-001	Louis C Lechenger (T-2)	Ghost							X			
13:35	0812-010	Lewis Energy	4M2-21							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	5M2-22							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	6M2-8D							X			
13:35	0812-010	Fasken Ltd	6M2-8A							X			
13:35	CP-12640	Silverbow Resources Operating LLC	8M2-8E&F							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-8G							X			

Comments:		Page	1	of	2	Specialist Signature	<i>Araceli Thatcher</i>



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-13							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-14							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-15	1176	0		12713993			X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-16							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-17							X			
13:35	0812-010	Segundo Navarro Drilling Ltd	8M2-18							X			
13:35	B804-000	Kingsley Water Company	8M2-18							X			
13:35	B804-000	Kingsley Water Company	8M2-28	1176	0		12713993			X			
14:10	B804-000	Kingsley Water Company	8M2-31							X			
14:10	B804-000	Kingsley Water Company	8M2-32							X			
14:10	B804-000	Kingsley Water Company	8M2-34							X			
14:10	B804-000	Kingsley Water Company	8M2-35							X			
14:10	2747-B03	Barry Gilpin/Select Energy Services	8M2-36							X			
14:10	2747-A03	Barry Gilpin/Select Energy Services	8M2-36							X			
14:10	0812-010	Segundo Navarro Drilling Ltd	8M2-37							X			
14:10	0812-010	Segundo Navarro Drilling Ltd	10M2-8H							X			
14:10	0812-010	Segundo Navarro Drilling Ltd	10M2-8J							X			
14:10	0297-000	Kingsley Water Company	10M2-19							X			
14:10	0297-000	Kingsley Water Company	10M2-20							X			
14:10	2747-A03	Barry Gilpin/Select Energy Services	10M2-24							X			
14:10	2747-B03	Barry Gilpin/Select Energy Services	10M2-24							X			
14:10	0220-004	RBWR LLC/Endeavor Natural Gas	10M2-25							X			

Comments:

Rev: 3/1/2023

Page 2 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date:	3/20/2023	Inspections:	54
Time Start:	8:30 AM	Measurement:	2
Time End:	4:05 PM	Doppler:	1
Inspec Time:	4.00	On-Site Notice:	0
RN#:	106122732	Travel Time:	2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
9:20	2714-000	Fasken Ltd	10M4-1							X			
9:20	2714-000	Fasken Ltd	10M4-2							X			
9:30	2721-000	Killam Development Corp (T-4)	Ghost							X			
9:30	2715-000	Mines Road Development (T-4)	Ghost							X			
9:40	2724-000	Rodolfo V Solis	Ghost							X			
10:00	2727-000	Talen Texas Property	6M4-10							X			
10:00	2727-000	Talen Texas Property	6M4-9							X			
10:00	2727-000	Talen Texas Property	10M4-8							X			
10:00	2727-000	Talen Texas Property	10M4-7	750	680	604	209746			X	X		
10:35	3997-000	City of Laredo - Del Mar	10M4-12							X			
10:35	3997-000	City of Laredo - Del Mar	8M4-13							X			
10:35	3997-000	City of Laredo - Del Mar	10M4-14							X			
10:45	2735-004	City Ready Mix	6M4-15							X			
10:50	2735-001	US Dept of Labor (T-4)	Ghost							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-18	20000	11284		73360.648			X	X		
11:00	3997-000	City of Laredo - Jefferson	14M6-19							X			
11:00	3997-000	City of Laredo - Jefferson	20M4-20							X			
11:00	3997-000	City of Laredo - Jefferson	20M4-21							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21A							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21B							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21C							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21D							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21E							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21F							X			
11:00	3997-000	City of Laredo - Jefferson	16M4-21G							X			

Comments:

Rev: 3/1/2023

Page

1

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:20	2742-001	Laredo Municipal Jr College	3M4-22							X			
11:30	2742-000	Rodolfo Garcia (T-4)	Ghost							X			
11:45	2743-001	David M Slaughter	6M4-23							X			
11:45	2743-000	Sheila Slaughter Glassford	6M4-23							X			
12:00	2746-000	Sacred Heart Children's Home	6M5-1							X			
12:18	2748-000	F J Richter Farms Partners	6M5-3							X			
13:40	2751-000	City of Laredo (T-5)	Ghost							X			
13:45	2751-000	J C Trevino Jr (T-5)	Ghost							X			
13:45	2751-000	J C Trevino (T-5)	Ghost							X			
13:55	2751-000	HAPO Holdings LLC (T-5)	Ghost							X			
14:10	2812-000	Sherry R Lewis	5M5-7							X			
14:20	2753-001	Porfirio Hernandez	4M5-8							X			
14:20	2753-000	Angelita Hernandez	4M5-8							X			
14:35	2754-000	Martha Cadena (T-5)	Ghost							X			
14:45	2756-000	Micheal MacMahon	4M5-10							X			
14:45	2756-000	Micheal MacMahon	4M5-10M							X			
14:45	2756-000	Micheal MacMahon	Minning							X			
14:55	2757-000	Javier Acevedo eat al	6M5-11							X			
14:55	2757-000	Horacio Acevedo	6M5-11							X			
15:05	2758-000	Antonio C Lopez	3M5-12A							X			
15:05	2758-000	Antonio C Lopez	6M5-12							X			
15:05	2758-000	Antonio C Lopez (T-5)	Ghost							X			
15:15	2759-001	Winfield Ltd (T-5)	Ghost							X			
15:15	2759-000	Carlos Y Benavides	8M5-13							X			
15:18	2721-000	Killam Development Ltd	3M-Temp							X			

Comments:

Rev: 3/1/2023

Page

2

3

Specialist Signature

Anaceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/21/2023

Inspections: 54

Time Start: 8:40 AM

Measurement: 1

Time End: 4:02 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122740

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:10	0346-001	Siesta Shores WCID	6M10-6C							X			
10:10	0461-005	Siesta Shores WCID	6M10-6B							X			
10:15	DF-75	Dan A Richter	—							X			
10:15	2426-002	Donald L Hayes	1M10-6							X			
10:16	2430-000	Wayne Pierce	1M10-5							X			
10:22	2806-000	DavidG Delore (T-10)	Ghost							X			
10:26	2810-000	Juan Antonio and Rosa Maria Guevara (T-10)	Ghost							X			
10:30	2809-000	David G Delorme Bass Lake RV (T-10)	Ghost							X			
10:33	2422-003	Christine McKee (T-10)	Ghost							X			
10:40	2725-001	Cyrus B Reynolds	2M9-27							X			
10:55	2422-002	Lynn D Smith (T-9)	Ghost							X			
10:57	2426-001	Lendol C Baker	1M9-25							X			
11:00	2421-002	J E Bravo (T-9)	Ghost							X			
11:20	2804-002	John A Nixon	1M9-22A							X			
11:20	2804-002	Elena F Strokes	1M9-22A							X			
11:35	2804-000	Zapata Co Water Works	16M9-21C							X			
11:35	2804-000	Zapata Co Water Works	16M9-21D							X			
11:35	2804-000	Zapata Co Water Works	16M9-21E	1700	1673		1378.165			X	X		
11:55	DF-14	J R Terrell	—							X			
11:55	DF-34	J H Kuykendall	—							X			
11:55	DF-45	W I Hammond	—							X			
11:57	2801-000	Jose Luis Garza	1M9-20							X			
12:00	DF-61	B D Love	—							X			
12:03	DF-20	J E Fields	—							X			
12:05	2425-001	Gaylen Gilbreath	1M9-19A							X			

Comments:

Rev: 3/1/2023

Page

1

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
12:06	2424-001	Albert and Frances Muehsam	1M9-17							X			
12:07	2428-000	A C Durivage	1M9-16							X			
12:07	2423-000	Albert Long	1M9-15							X			
12:08	DF-56	R E Lee	—							X			
12:12	2803-000	Shady Have LLC (T-9)	Ghost							X			
12:16	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
12:20	2429-001	Straud B Jacobs	1M9-11							X			
12:23	2432-001	Theodore C Miller (T-9)	Ghost							X			
12:23	2431-001	Troy D Weldon	1M9-7C							X			
12:24	2435-009	Javier Reyes	1M9-7B							X			
12:24	DF-58	M L Cave	—							X			
12:24	2435-010	M L Cave	1M9-7A							X			
12:25	2435-007	Frederick J Kilian	1M9-6							X			
12:25	2435-002	Rock H Wilkinson	1M9-5							X			
12:35	DF-57	R N Bledsoe	—							X			
12:35	DF-70	L W Daiker	—							X			
12:38	2804-000	Zapata Co WW (T-9)	Ghost							X			
12:39	2718-001	Barton E Anderson (T-9)	Ghost							X			
12:39	2718-000	Gerald A Bader	1M9-3							X			
12:40	2433-000	C.E. And Evelyn Deyo	1M9-2							X			
13:15	2800-000	Jose F Gutierrez (T-8)	Ghost							X			
13:35	DF-67	Steve Lillard (T-8)	Ghost							X			
13:50	2799-000	Amanda Rash (T-8)	Ghost							X			
14:15	2799-001	La Roca Real Inc (T-8)	Ghost							X			
14:45	2799-000	Amanda Rash (T-8)	Ghost							X			

Comments:

Rev: 3/1/2023

Page

2

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/22/2023

Inspections: 44

Time Start: 8:50 AM

Measurement: 1

Time End: 3:25 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122757

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
10:20	2433-000	C.E. And Evelyn Deyo	1M9-2							X			
10:20	2718-000	Gerald A Bader	1M9-3							X			
10:20	2718-001	Barton E Anderson (T-9)	Ghost							X			
10:23	2804-000	Zapata Co WW (T-9)	Ghost							X			
10:27	DF-70	L W Daiker	—							X			
10:27	DF-57	R N Bledsoe	—							X			
10:35	2435-002	Rock H Wilkinson	1M9-5							X			
10:35	2435-007	Frederick J Kilian	1M9-6							X			
10:36	2435-010	M L Cave	1M9-7A							X			
10:36	DF-58	M L Cave	—							X			
10:37	2435-009	Javier Reyes	1M9-7B							X			
10:38	2431-001	Troy D Weldon	1M9-7C							X			
10:39	2432-001	Theodore C Miller (T-9)	Ghost							X			
10:43	2429-001	Straud B Jacobs	1M9-11							X			
10:45	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
10:55	2803-000	Shady Have LLC (T-9)	Ghost							X			
11:03	DF-56	R E Lee	—							X			
11:03	2423-000	Albert Long	1M9-15							X			
11:04	2428-000	A C Durivage	1M9-16							X			
11:04	2424-001	Albert and Frances Muehsam	1M9-17							X			
11:05	2425-001	Gaylen Gilbreath	1M9-19A							X			
11:05	DF-20	J E Fields	—							X			
11:05	DF-61	B D Love	—							X			
11:06	2801-000	Jose Luis Garza	1M9-20							X			
11:07	DF-45	W I Hammond	—							X			

Comments:

Rev: 3/1/2023

Page 1 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:07	DF-14	J R Terrell	—							X			
11:25	2804-000	Zapata Co Water Works	16M9-21C							X			
11:25	2804-000	Zapata Co Water Works	16M9-21D							X			
11:25	2804-000	Zapata Co Water Works	16M9-21E	1700	1743		1380.007			X	X		
11:45	2804-002	John A Nixon	1M9-22A							X			
11:45	2804-001	Elena Strokes	1M9-22A							X			
13:15	2421-002	J E Bravo (T-9)	Ghost							X			
13:17	2425-001	Lendol C Baker	1M9-25							X			
13:18	2422-002	Lynn D Smith (T-9)	Ghost							X			
13:25	2725-001	Cyrus B Reynolds	2M9-27							X			
13:35	2422-003	Christine McKee (T-10)	Ghost							X			
13:37	2809-000	David G Delmore (T-10)	Ghost							X			
13:39	2810-000	Jose A Rosa Ma Guevara (T-10)	Ghost							X			
13:42	2808-000	David G Delmore (T-10)	Ghost							X			
13:55	2430-000	Wayne Pierce	1M10-5							X			
13:55	2426-002	Donald L Hayes	1M10-5							X			
13:56	DF-75	Dan A Richter	—							X			
14:00	0461-005	Siesta Shores Inc	6M10-6B							X			
14:00	0346-001	Siesta Shores Inc	6M10-6C							X			

Comments:

Rev: 3/1/2023

Page 2 of 2

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality

Rio Grande Watermaster

Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Date: 3/23/2023

Inspections: 56

Time Start: 8:35 AM

Measurement: 1

Time End: 4:25 PM

Doppler: 0

Inspec Time: 4.00

On-Site Notice: 0

RN#: 106122757

Travel Time: 2.00

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
11:00	DF-76	AF & JF Martin	-							X			
11:15	2747-001	Union Pacific Oil & Gas Co	2M10-14							X			
11:18	DF-74	Clarence Holt	-							X			
11:18	DF-68	Clarence Holt	-							X			
11:25	2435-008	JD Gutierrez Jr Family LTD	1M10-12							X			
11:30	2752-000	Far Point Estate	-							X			
11:32	DF-4	B C Williams	-							X			
11:35	DF-48	H W Harrington Jr	-							X			
11:40	0248-006	Mary Jane Cox Green	3M10-11B							X			
11:50	DF-53	J C Brown	-							X			
11:51	DF-50	W A Krauss	-							X			
11:52	DF-35	D E Woodruff	-							X			
12:04	DF-77	Jamie Bray	-							X			
12:20	2422-005	The Estate of Rebecca A Gonzalez (T-10)	Ghost							X			
12:40	2658-000	Salvador Garcia (T-10)	Ghost							X			
13:05	2421-A/B03	Adan Volpe (T-10)	Ghost							X			
13:05	2421-A/B03	AdanVolpe	6M10-10A							X			
14:10	0346-001	Siesta Shores WCID	6M10-6C							X			
14:10	0461-005	Siesta Shores WCID	6M10-6B							X			
14:14	DF-75	Dan A Richter	—							X			
14:14	2426-002	Donald L Hayes	1M10-6							X			
14:15	2430-000	Wayne Pierce	1M10-5							X			
14:22	2806-000	David G Delore (T-10)	Ghost							X			
14:24	2810-000	Juan Antonio and Rosa Maria Guevara (T-10)	Ghost							X			
14:27	2809-000	David G Delorme Bass Lake RV (T-10)	Ghost							X			

Comments:

Rev: 3/1/2023

Page

1

of

3

Specialist Signature

Araceli Thatcher



Texas Commission on Environmental Quality
Rio Grande Watermaster
Deputy's Daily Report

Site Code: 1 = ID New Pump ; 2 = No Doppler Reading ; 3 = Meter Diagram ; 4 = No Access ; 5 = MX Pump

On-Site Notice Codes: A = No Note/Cert Posted ; B = No Certification ; C = No Meter ; D = Inoperable Meter ; E = +/- 10% ; F=Hazard

Time	Adjudication #	Diverter Name	Pump #	Cert Rate	Meter Rate	Doppler Rate	Totalizer	IBWC Gage		I	M	N	Code
								SB	BR				
14:30	2422-003	Christine McKee (T-10)	Ghost							X			
14:35	2725-001	Cyrus B Reynolds	2M9-27							X			
14:36	2422-002	Lynn D Smith (T-9)	Ghost							X			
14:38	2426-001	Lendol C Baker	1M9-25							X			
14:39	2421-002	J E Bravo (T-9)	Ghost							X			
14:48	2804-002	John A Nixon	1M9-22A							X			
14:48	2804-002	Elena F Strokes	1M9-22A							X			
14:55	2804-000	Zapata Co Water Works	16M9-21C							X			
14:55	2804-000	Zapata Co Water Works	16M9-21D							X			
14:55	2804-000	Zapata Co Water Works	16M9-21E	1700	1673		1382.821			X	X		
15:03	DF-14	J R Terrell	—							X			
15:03	DF-34	J H Kuykendall	—							X			
15:03	DF-45	W I Hammond	—							X			
15:04	2801-000	Jose Luis Garza	1M9-20							X			
15:06	DF-61	B D Love	—							X			
15:08	DF-20	J E Fields	—							X			
15:08	2425-001	Gaylen Gilbreath	1M9-19A							X			
15:08	2424-001	Albert and Frances Muehsam	1M9-17							X			
15:09	2428-000	A C Durivage	1M9-16							X			
15:09	2423-000	Albert Long	1M9-15							X			
15:09	DF-56	R E Lee	—							X			
15:15	2803-000	Shady Have LLC (T-9)	Ghost							X			
15:17	2719-000	Delozeis Family Limited Partnership	1M9-13							X			
15:18	2429-001	Straud B Jacobs	1M9-11							X			
15:19	2432-001	Theodore C Miller (T-9)	Ghost							X			

Comments:

Rev: 3/1/2023

Page

2

of

3

Specialist Signature

Araceli Thatcher

