

## **Document Control Sheet**

Sheet Title:

Box ID:

Control Sheet ID:

Record Series Name:

Record Series:

Primary ID:

Secondary ID:

Doc Type:

Security:

Date:

Title:

Tertiary ID

AIR CP - OLS

22335

0000-0000-0054-4891

OCE / Air Compliance

AIR CP

100788959

Compliance

Public

10/8/2021 12:00AM

Investigation

1765894

# AIR CP\_100788959\_CP\_20211008\_Investigation\_1765894 **Texas Commission on Environmental Quality Investigation Report**

The TCEQ is committed to accessibility. If you need assistance in accessing this document, please contact oce@tceq.texas.gov

# **Customer: Building Materials Investment Corporation** Customer Number: CN605251487

**Regulated Entity Name: GAF MATERIALS** Regulated Entity Number: RN100788959

Investigation # 1765894

**Incident Numbers** 

368480

Investigator:

JOSEPH VU

Site Classification

Conducted: 10/08/2021 -- 10/14/2021

SIC Code: 2951

SIC Code: 2952

**NAIC Code: 324122** 

Program(s):

AIR OPERATING PERMITS

AIR NEW SOURCE PERMITS

Investigation Type: Compliance Investigation

Location: 2600 Singleton Blvd

Additional ID(s):

Address: ,

Local Unit: CITY OF DALLAS LOCAL PROGRAM

**Activity Type(s):** 

AIRCOMPL - AIR CMPL - AIR

COMPLAINT INV

Principal(s):

Role

Name

RESPONDENT

BUILDING MATERIALS INVESTMENT CORPORATION

Contact(s):

Role

Title

Name

Phone

REGULATED

MR KEVIN BUSH

Phone

(972) 872-2325

**ENTITY MAIL** 

Cell

(469) 337-4475

CONTACT

Other Staff Member(s):

Role

Name

RECEIVED

Supervisor **QA** Reviewer PAUL WHITE

PAUL WHITE

DEC 2 1 2021

**Associated Check List** 

CENTRAL FILE ROOM

**Checklist Name** 

**Unit Name** 

#### **Investigation Comments:**

**Investigation Comments:** 

On October 8th, 13th and 14th of 2021, Mr. Joseph Vu, Environmental Investigator for the Dallas Local Air Program, conducted an Air Quality Complaint (AIR-CMPL) in the general area of 2816 Bedford Street Dallas, Tx 75212. Map/Figures depicting the general area of 75212 are attached (Attachment 1).

#### **GAF MATERIALS - DALLAS**

### 10/8/2021 to 10/14/2021 Inv. # - 1765894

#### Page 2 of 4

The purpose of the investigation was to respond to the complaint to evaluate compliance with Title 30 Texas Administrative Code (30 TAC) §101.4: General Rules for Nuisance Conditions, specifically for nuisance odor.

The complainant alleged nuisance odor conditions detected along Bedford Street which consisted of odors smelling like burnt rubber and asphalt tar. This was an unannounced investigation because it was initiated by a complaint. The purpose of this investigation was to perform an odor survey to assess current nuisance conditions and identify a possible source.

#### Daily Narrative:

The following is information regarding a description of the complaint:

# COMPLAINANT NAME/ADDRESS:

This information is being handled as confidential and is included in the regional confidential file. Refer to Incident number 368480 for more information.

## TIME, DATE, FREQUENCY, DURATION OF THE ODOR

The complainant alleged nuisance odors were detected along Bedford Street potentially originating from the GAF Dallas facility. Nuisance odors consisted of burnt rubber and asphalt tar odors. The odors were detected during high winds coming from the south-southeast.

## DESCRIBE ACTIVITY/OPERATIONS AT THE TIME OF THE COMPLAINT

The physical address given by the complainant was 2816 Bedford Street, a vacant residential property void of any structures. An eight-foot wooden fence is located on the property obstructing the view onto the property. The GAF Dallas facility was in operation at that time.

## DESCRIPTION OF THE ALLEGED EFFECTS

The complainant alleged nuisance odors were detected along Bedford Street potentially originating from the GAF Dallas facility.

#### INVESTIGATION INFORMATION

# METEOROLOGICAL DATA AT THE TIME OF THE INVESTIGATION

10/08/2021 Temperature: 90°F, 37 % humidity, south-southwest 15 mph winds, and clear skies. 10/13/2021 Temperature: 78°F, 64 % humidity, south-southeast 12 mph winds, and broken skies. 10/14/2021 Temperature: 86°F, 71 % humidity, south 16 mph winds, and cloudy skies.

#### LOCATION OF THE ACTIVITY

Nuisance odor conditions were detected along Bedford Street. The complainant provided the physical address of 2816 Bedford Street but alleged the GAF Dallas facility as the potential source of odors.

#### DESCRIPTION OF THE ACTIVITY

No visible emissions or smoke was observed by the complainant at the time of the nuisance odor incident. The GAF Dallas facility was in full operation according to the complainant.

#### DESCRIPTION OF THE EFFECTS ON THE INVESTIGATOR

No nuisance odor conditions were detected by the investigator; therefore, no effects were noted.

#### SOURCE EMISSIONS CONSISTENT WITH THE ALLEGED ACTIVITY

Based on the description of the nuisance odors by the complainant, the nuisance odor descriptions match the potential odors associated with operations performed at the GAF Dallas facility.

#### **GAF MATERIALS - DALLAS**

### 10/8/2021 to 10/14/2021 Inv. # - 1765894

## Page 3 of 4

#### SPECIFIC CAUSE OF THE ODOR

No burning was observed at 2816 Bedford Street, but the potential source was alleged to be from the GAF Dallas facility.

### COMPLAINANT LOG NECESSARY/ APPROPRIATE

On October 8, 2021, a copy of the TCEQ Odor Log for public use was provided to the complainant via email. No odor logs have been returned to the investigator by the complainant to date.

On 10/08/2021, Mr. Vu visited the complaint area around 2:30pm to perform an odor survey. No odors were detected at 2816 Bedford Street or east and westbound along Bedford Street. Lumber/pinewood odors were detected at the intersection of Manila Road and Bedford Street coming from the GAF Dallas facility but did not match the complainant's description.

Later, 10/08/2021, the complainant responded to an inquiry by Mr. Vu via email describing the odors in detail and the conditions when the nuisance odors were experienced. The complainant confirmed that nuisance odors were not detected in the afternoon on 10/08/2021 but detected at 12:00pm and lasted for approximately 30 minutes.

Mr. Vu contacted Mr. Kevin Bush, Senior Environmental Engineer for the GAF Dallas facility on 10/08/2021 via email to inform them of the alleged nuisance odor complaint. Mr. Vu also inquired if any reportable/non-reportable emissions, deliveries of raw materials, or upsets to their production line were experienced on 10/08/2021 at 12:00pm. Mr. Bush responded on 10/12/2021 stating no reportable/non-reportable emissions, deliveries of raw materials, or upsets to their production line were experienced at the facility. In addition, there were on loading or unloading activities of raw materials in the morning of 10/08/2021 which could have caused the nuisance odor conditions.

On 10/13/2021, Mr. Vu visited the complaint area around 6:50am to perform an odor survey. Again, no odors were detected at 2816 Bedford Street or east and westbound along Bedford Street. No odors were detected during the odor survey.

On 10/14/2021, Mr. Vu visited the complaint area around 3:35pm to perform an odor survey. Again, no odors were detected at 2816 Bedford Street or east and westbound along Bedford Street. No odors were detected during the odor survey.

On 10/14/2021, Mr. Vu informed the complainant of the results of the investigation and inquired if the complainant would like to receive a copy of the investigation report and if the complainant has completed the TCEQ Odor log. To date, the complainant has not responded to the inquiry.

### Exit Interview:

Mr. Bush was informed via email no violations will be issued and a general compliance letter will be sent.

# GENERAL FACILITY AND PROCESS INFORMATION

**Process Description:** 

Alleged nuisance odor conditions were originating near Savor by Samir, a full-service catering company. BACKGROUND

GAF Materials RN:100788959 Classification: High Rating: 0.0

Build Materials Investment Corporation CN:605251487 Classification: High Rating: 0.0

Agreed Orders, Court Orders, and other Compliance Agreements:

No violations were noted during this investigation.

# Prior Enforcement Issues:

No violations were noted during this investigation.

#### Complaints:

A total of eight (8) complaints have been received against the GAF Dallas facility from 2016 through 2021. No

/2021 to 10/14/2021 Inv. # - 1765894	
4 of 4	
complaints have resulted in Notice of Violations or Notice of	Enforcements.
ADDITIONAL INFORMATION Conclusions, Recommendations, and Current Enforcement A No violations are being alleged at this time. A general complia 368480	
Additional Issues: No additional issues were noted during this investigation.	
Attachments:  1. Map Figures	
No Violations Associated	to this Investigation
Signed Signed Engineering to the state of th	Date /3/27/7/
Signed Environmental Investigator	Date
Environmental Investigator	
for -	Date 10/22/21
Environmental Investigator	
Environmental Investigator  Signed	Date 10/22/21
Signed Supervisor  Attachments: (in order of final report su	Date 10/22/21
Signed  Supervisor  Attachments: (in order of final report suEnforcement Action Request (EAR)	Date 10/22/21
Signed Supervisor  Attachments: (in order of final report su	Date 10/22/21  abmittal) Maps, Plans, Sketches

\_\_\_Manifests

\_\_\_\_Notice of Registration

Inv 1765894

Attachment 1

Map/figures

**Total Pages 3** 


CN605251487

RN1007889859

**Building Materials Investment Corporation** 

**GAF Materials** 

10/08/21 through 10/14/2021








# Attachment 1 Map/Figures

City of Dallas Local Air Program Investigation 1765894 10/08/2021 2816 Bedford Street Dallas, TX 75212








Attachment 1 Map/Figures

City of Dallas Local Air Program Investigation 1765894 10/13/2021 2816 Bedford Street Dallas, TX 75212







Attachment 1 Map/Figure
City of Dallas Local Air Program
Investigation 1765894
10/14/2021
2816 Bedford Street

Dallas, TX 75212



October 25, 2021

Building Materials Investment Corporation Attn: Mr. Kevin Bush 202 Cedar Road Ennis, TX 75119

Re:

Complaint Investigation

**GAF Materials** 

2600 Singleton Boulevard

Dallas, TX 75212

TCEQ ID #: RN100788959 CN605251487

Dear Mr. Bush,

On October 8<sup>th</sup>, 13<sup>th</sup> and 14<sup>th</sup> of 2021, Mr. Joseph Vu with the City of Dallas Air Compliance Program conducted a complaint investigation of the above-referenced address to evaluate compliance with applicable requirements for air pollution. No violations were documented during this investigation.

The City of Dallas Air Compliance Program and Texas Commission on Environmental Quality (TCEQ) appreciates your assistance in this matter and your compliance efforts to ensure protection of the State's environment. Please feel free to contact me at 214-670-4059.

Sincerely

Joseph Vu MS, P.G., Manager

Air Compliance Program

Office of Environmental Quality and Sustainability